

Equipment Inspection Technical Report



Client Name:	NOOR AL-RASHEED Co.		Job Number:	QC-J-9-2024-0072
Date of Examination:	12-09-2024	Location:	QC-yard	Certificate No: QC-J-9-2024-0072-01

Equipment under Inspection: High Pressure /Hydrovac Water Pump Truck

Pump Manufacture	Pump Type	Pump S/N	Pump Pressure
PRALISSOLI	KS36	WP110201	1900 PSI
Truck Manufacture	Reg.No.	Chassis number	Tank Volume
SCANIA	26319-ERBIL	XLER4X20004500493	16,000 Liters

Inspection Method: Visual and function Inspection

No.	Section Under Inspection	Status
1	Hydraulic system	OK
1.1	Hydraulic Oil Level	OK
1.2	Condition of Oil	OK
1.3	System and hoses	OK
1.4	Lubrication	OK
2	Pump & Operation system	OK
2.1	Hoses and fittings are of the correct pressure rating (250 BAR) and in good condition	OK
2.2	Pressure gauge Checked and Calibrated (gauge pressure (250 BAR) ST-3868-02	OK
	Pressure Safety valve checked and tested (Valve set pressure 120BAR) ST-3868-03	OK
2.3	Tank /vessel	OK
2.4	Pressure pump (max pressure 170 BAR)	OK
2.5	Operation controls for pump or transfer system ,gauge and valves	OK
2.6	All hoses are joined by threaded female couplings of the correct pressure rating	OK
2.7	Water washing gun (P560,600 bar 60 Mpa,60L/min) is visually inspection and secured with Whip check safety cable	OK
3	Safety devices	OK
3.1	Warning alarms	OK
3.2	First aid box	OK
3.3	Fire extinguisher	OK
4	General	OK
4.1	Tires	OK
4.2	Drive gears	OK
4.3	Hydraulic Cylinder	OK

Name of Inspector:	Name of person authenticating this report:	Signature & Stamp:	
Abdullah Mofeed	Ashraf El Said		
Date of Next Through Examination:	11-09-2025		



Equipment Inspection Technical Report

No.	Section Under Inspection	Status
4.4	Electrics	OK
4.5	Engine compartment	OK
4.6	Exhaust system	OK
4.7	Steering	OK
4.8	Gauge in cabin	OK
4.9	Safety belt	OK
4.10	Front and rear lights	OK
4.11	Windscreen	OK
4.12	Windshield wipers	OK
4.13	Driver right mirror	OK



Result:-

- 1-The vehicle has been inspected, tested and found to meet the manufacture's specifications
- 2-Inspection has been done in According with BS 474-1:2022
- 3-Inspection has been done In According with OHS Regulation
- 4-This inspection report is valid for one year.
- 5-The inspected equipment is in specification at the time it had been inspected
- 6-This inspection was carried out in compliance with the OHS Regulations
- 7-Inspection has been done for the above-mentioned items
- 8-This report is valid only with signature and stamp

Name of Inspector:	Name of person authenticating this report:	Signature & Stamp	
Abdullah Mofeed	Ashraf El Said		
Date of Next Through Examination:	11-09-2025		