




CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Date of Examination:	17-09-2024	Date of Report:	17-09-2024	Certificate No:	QC-BGG-09-24-0152 -1
Client Name:	Black Gold Gulf Oil And Gas Services Co.Ltd Basra Iraq	Location:	QC Yard	Job Number:	QC-BGG-09-24-0152
Serial Number:	QTY	Description		SWL	Date of last Thorough examination
1261-6T/6M-19 1261-6T/6M-06	02	<p style="text-align: center;">Flat Polyester Woven Webbing Sling</p> <p>Manufacture: DAWSON Type: Webbing Sling Material: Polyester Safety Factor: 6:1 Length: 6 M Color: Brown Date: June-2023</p> 		Vertical 6000 Kg Chocker 4800 Kg Basket 12000 Kg	NEW
Reference Standard:		BS EN 1492-1:2008			
Is this the first examination after Installation or assembly at a new site or location?		YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>		Was the examination carried out: Within an interval of 6 months? YES <input checked="" type="checkbox"/> NO <input type="checkbox"/> With an interval of 12 months? YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> In accordance with an examination scheme? YES <input checked="" type="checkbox"/> NO <input type="checkbox"/> After the occurrence of exceptional circumstances? YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>	
If the answer to the above question is YES has the equipment been installed correctly?		YES <input type="checkbox"/> NO <input type="checkbox"/> N/A			
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none state NONE) NONE					
Is the above a defect which is of immediate danger to persons:				YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>	
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)				N/A	
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
Particulars of any tests carried out as part of the examination: (If none state NONE)					
The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory					
IS THIS EQUIPMENT SAFE TO OPERATE?				YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>	
Name of Inspector:	Name of person authenticating this report:	Signature:			
Sajjad Mohammed	Mohamed Abdalla				
Date of Next Thorough Examination:	16.03.2025				




REV: 01 Dated: 20 June 2022

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Date of Examination:	17-09-2024	Date of Report:	17-09-2024	Certificate No:	QC-BGG-09-24-0152 -2
Client Name:	Black Gold Gulf Oil And Gas Services Co.Ltd Basra Iraq	Location:	QC Yard	Job Number:	QC-BGG-09-24-0152
Serial Number:	QTY	Description		SWL	Date of last Thorough examination
01278	01	Flat Polyester Woven Webbing Sling Manufacture: DAWSON Type: Webbing Sling Material: Polyester Safety Factor: 5:1 Length: 4 M Color: Grey Date: 2022 		Vertical 4000 Kg Choker 3200 Kg Basket 8000 Kg	NEW
Reference Standard:		BS EN 1492-1:2008			
Is this the first examination after Installation or assembly at a new site or location?		YES	NO	√	
If the answer to the above question is YES has the equipment been installed correctly?		YES	NO		
		N/A			
Was the examination carried out: Within an interval of 6 months?		YES	NO	√	
With an interval of 12 months?		YES	NO	√	
In accordance with an examination scheme?		YES	NO		
After the occurrence of exceptional circumstances?		YES	NO	√	
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none state NONE) NONE					
Is the above a defect which is of immediate danger to persons:				YES	NO
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)				N/A	
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
Particulars of any tests carried out as part of the examination: (If none state NONE) The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory					
IS THIS EQUIPMENT SAFE TO OPERATE?				YES	NO
Name of Inspector:	Name of person authenticating this report:	Signature & Stamp			
Sajjad Mohammed	Mohamed Abdalla				
Date of Next Through Examination:	16.03.2025				

REV: 01 Dated: 20 June 2022

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.

