

AI TAKAMUL COMPANY FOR ENGINEERING TESTS AND PROFESSIONAL SAFETY LIMITED

Basra, North Rumaila, Quality Control Yard - Iraq


Tel: +9647810009138 / +9647834964657

Email: OP@qualitycontrol-iraq.com / hany.akafi@qualitycontrol-iraq.com



CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Date of Examination:	16/10/2024	Date of Report:	16/10/2024	Certificate No:	QC-HAL-IEM-24-0363-02
Client Name:	HALLIBURTON	Location:	FMG	Job Number:	161024
Manufacturer / Date:	CATERPILLAR 2012	Model:	DP30N	SWL:	3000 KG
Serial No.:	ET14E05057	Chasses No:	ET14E05057	SAP No:	12405526
Description of Equipment	<p>Diesel Engine Powered Hydraulic System Forklift Truck.</p> <p><i>Capacity: 3000 KG.</i> <i>Model: DP30N</i> <i>Manufacturing Year: 2012</i> <i>Nominal Power: 38 kN</i> <i>Truck Weight: 4.48 ton</i> <i>Maximum Fork Height: 7000 mm</i> <i>Equipment SAP No: 12405526</i></p>				
Ref. Standard	BS ISO 2330:2002 / BS ISO 5057:1993				

Date of Last Examination:	12/12/2019	Date of Last Proof Load Test:	12/12/2019
----------------------------------	------------	--------------------------------------	------------

TESTING	Pass	Fail	Notes
Operational (No Load)	✓		Forklift Found Satisfactory For Further Use.
Performance Test (Rated Capacity)	✓		Forklift found to be acceptable to lift 100 % from SWL .
Proof Load Test (1.1 x Rated Capacity)	✓		Forklift found to be acceptable to lift 110 % from SWL .

Is this the first examination after Installation or assembly at a new site or location?	YES	✓	NO		Was the examination carried out: Within an interval of 6 months? With an interval of 12 months? In accordance with an examination scheme? After the occurrence of exceptional circumstances?	YES		NO	✓
	YES	✓	NO			YES	✓	NO	
If the answer to the above question is YES has the equipment been installed correctly?	YES	✓	NO			YES	✓	NO	
	YES		NO	✓		YES		NO	✓

Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none State NONE) **NONE**

Is the above a defect which is of immediate danger to persons: YES NO



Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when) YES by: _____

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: (If none state NONE)

In the light of inspection findings subject Forklift was Inspected visually, operationally, performance test and load test were performed where no defects were observed during testing Hence, it was found satisfactory and fit for intended use.

IS THIS EQUIPMENT SAFE TO OPERATE? YES NO

Name of Inspector:	Name of person authenticating this report:	Signature & Stamp:	
ASHRAF ELSAID	MOHAMED ABDALLAH		
Date of Next Through Examination:	15/10/2025		

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.





CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client Name:	Halliburton	Location:	FMG	Examination Date:	16/10/2024
Manufacturer / Date:	CATERPILLAR 2012	Model:	DP30N	SWL:	3000 kg
Serial No.:	ET14E05057	Chasses No:	ET14E05057	SAP No:	12405526

REV: 00 Dated: 30 May 2021

No	COMPONANT CHECKS	RESULT	COMMENTS
DATA PLATE			
1	Manufacturers data plate	√	
MAST/Boom			
1	Operation	√	
2	Structure and welds	√	
3	Rollers & bearings	√	
4	Main hoist cylinder(s)	√	
5	Load chains	√	
6	Anchor pins	√	
7	Tilt cylinders	√	
8	Hydraulic hoses	√	
9	Side shift	√	
FORKS			
1	Condition	√	
2	Heel wear	√	
3	Locking pins	√	
POWER PACK			
1	Operation	√	
2	Engine/motor	√	
3	Mountings	√	
4	Battery	√	
5	Wiring	√	
6	Hydraulic pump	√	
7	Isolation switches	√	
STEERING AND WHEELS			
1	Operation	√	
2	Steering cylinders	√	
3	Braking system	√	
4	Ball joints	√	
5	Wheel bearings	√	
6	Tire condition	√	

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client Name:	Halliburton	Location:	FMG	Examination Date:	16/10/2024
Manufacturer / Date:	CATERPILLAR 2012	Model:	DP30N	SWL:	3000 kg
Serial No.:	ET14E05057	Chasses No:	ET14E05057	SAP No:	12405526

No	COMPONANT CHECKS	RESULT	COMMENTS
CABIN & CONTROLS			
1	Condition	√	
2	Control levers	√	
3	Control pedals	√	
4	Internal/external lights	√	
5	Gauges	√	
6	Seat and seat belt	√	
7	Horn	√	
8	Windscreen and wipers	N/A	
OTHER			
1	Light Alarm	√	
2	Sound Alarm	√	

Key Category:

1 = Immediate action	2= Action within ...	3= Worn/Serviceable	✓	No Apparent Defects	N/A = Not Applicable
----------------------	----------------------	---------------------	---	---------------------	----------------------

Name of Inspector:	Name of person authenticating this report:	Signature & Stamp:	
ASHRAF ELSAID	MOHAMED ABDALLAH		
Date of Next Through Examination:	15/10/2025		

REV: 00 Dated: 30 May 2021

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner’s work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation “LOLER”. The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client Name:	Halliburton	Location:	FMG	Examination Date:	16/10/2024
Manufacturer / Date:	CATERPILLAR 2012	Model:	DP30N	SWL:	3000 kg
Serial No.:	ET14E05057	Chasses No:	ET14E05057	SAP No:	12405526

Test Methods:		
DESCRIPTION	RESULT	COMMENTS
VT	√	Forklift Found Satisfactory at The Time of Inspection
MT	√	MPI was Carried Out on The Attached Forks
Functional Testing	√	Forklift Found Satisfactory at The Time of Inspection
Performance Testing	√	Forklift Found Satisfactory at The Time of Inspection
Proof Load Test	√	Next Load Test Shall Be Carried out After Any Repair/ Modification

Functional Testing: Carried Out without Load on all functions (including brakes and safety devices) and Controls (including and remote controls) to check correct and smooth operation of equipment and is free from wear and other damage.

Performance Testing: Carried out after Functional Test and with the rated load (SWL) applied where Hoist brakes were found satisfactory.

Proof Load Test: Only applicable Before First Use or after major repair or rectification.

Name of Inspector:	Name of person authenticating this report:	Signature & Stamp:	
ASHRAF ELSAID	MOHAMED ABDALLAH		
Date of Next Through Examination:	15/10/2025		

REV: 00 Dated: 30 May 2021

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.