




LIFTING EQUIPMENT CERTIFICATE OF VISUAL & THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client Name:	Hamza Abass Company. Al Basra, Iraq			Certificate No:	QC-J-10-2024-0094 -01			
Date of Examination:	20.10.2024	Location:	Quality Control Yard	Job Number:	QC-J-10-2024-0094			
Equipment Serial No:	0711176			SWL:	8300 KG @ 3.6 M			
Description of Equipment	Truck Mounted Hydraulic Operated Telescopic Boom Lorry Crane (HIAB) 8300 KG SWL on 3.6 M Radius @ 3.6 m Boom Length @ Fully Four Extended Outriggers Manufacture: Palfinger Manufacture Year: 2001 Model: PK32080 MAX Radius: 20.8 M MAX Boom Length: 20.8 M Chasses NO: YS2R6X20002119264 Swivel Hook WLL: 11 TON & SN: 17 Registration No: 22-F24999							
Ref. Standard	BS 7121-2-4							
PERFORMANCE TEST	BOOM LENGTH	RADIUS	SWL	APPLIED LOAD (KG)				
	3.6 M	3.6 M	8300 KG	FUNCTION TEST				
	8.0 M	8.0 M	3630 KG	3720 KG				
Date of Last Examination:	05.November.2023		Date of Last Load Test:	05.November.2023				
Examination Type	Pass	Fail	Notes					
Operational (No Load)	√		Elevating Work Platform Found Satisfactory For Further Use.					
Performance Test (Rated Capacity)	√		Elevating Work Platform found to be acceptable to lift 100 % from SWL .					
Proof Load Test (1.25 x Rated Capacity)	--		Proof Load Test Shall Be Done After any Repair/ Modification					
Is this the first examination after Installation or assembly at a new site or location?	YES		NO	√	Was the examination carried out: Within an interval of 6 months?			
						YES		NO
If the answer to the above question is YES has the equipment been installed correctly?	YES		NO		Was the examination carried out: With an interval of 12 months?			
					YES	√	NO	
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none State NONE) NONE					Was the examination carried out: In accordance with an examination scheme?			
					YES	√	NO	
Is the above a defect which is of immediate danger to persons:					After the occurrence of exceptional circumstances?			
YES					YES		NO	√
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)					YES by:			
Particulars of any repair, renewal or alteration required to remedy the defect identified above:								
Particulars of any tests carried out as part of the examination: (If none state NONE)								
In the light of inspection findings subject {HIAB} was Inspected visually, operationally was performed where no defects were observed during testing Hence, it was found satisfactory and fit for intended use								
IS THIS EQUIPMENT SAFE TO OPERATE?								
YES								
√								
NO								

QC-QA-MT-001 Rev.01Date SEP-2024

ASNT Level II Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Mahmoud Ali Khaled Mahmoud	Mohamed Abdulla		19.10.2025

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations and Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



LIFTING EQUIPMENT CERTIFICATE OF VISUAL & THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client Name:	Hamza Abass Company. Al Basra, Iraq	Location:	Quality Control Yard
Description of Equipment:	Truck Mounted Hydraulic Operated Telescopic Boom Lorry Crane (HIAB)	Serial No:	0711176
Date of Examination:	20.10.2024	Certificate No:	QC-J-10-2024-0094-01
		SWL:	8300 KG @ 3.6 M

HIAB Inspection Checklist


No	COMPONANT CHECKS	RESULT	COMMENTS
DATA PLATE			
1	WHEELS & TYRES	√	
2	ANGLE INDICATOR	√	
3	EMERGENCY KEY	√	
4	OPERATING EVERS & PEDALES	√	
5	LIGHT INDICATORE & HORN	√	
6	INTEGRITY OF CHASSSIS	√	
7	OUTRIGGERS & HOSUSING	√	
8	LEVEL INDICATORS	√	
9	LIGHTS & HORN	√	
10	HYDRULIC SYSTEM	√	
11	PRIM MOTIVE POWER UNIT	√	
12	OPERATORE MANUAL & LOAD CHART	√	
13	PLATE FORM DECK & ACCESS	√	
14	AXLES	√	
15	BREAKS & CLUTCHES	√	
16	STEERING	√	
17	CABIN CONDITION & ACCESS	√	
18	MAIN HOIST DRUM	N/A	
19	MINIMUM TURNS OF DRUM	N/A	
20	ROPES & ANCHORAGES	N/A	
21	BASKET CONDATION	√	
22	BOOM LIFT	√	
23	WEAR BADS	√	
24	HYDRULLIC HOSES	√	
25	BOOM SECTION FOR DAMAGE	√	
26	SLEW MOTOR & GEAR	√	
27	OIL LEAKAGES OF OPERATION	√	
28	GENERAL CONDITIONS	√	
29	EMERGENCY LOWERING SYSTEM	√	

NOTE:

* HIAB visual, function & performance test were carried out and found accept at the time of inspection.

Key Category:

1 = Immediate action	2= Action within ...	3= Worn/Serviceable	✓	No Apparent Defects	N/A = Not Applicable
----------------------	----------------------	---------------------	---	---------------------	----------------------

ASNT Level II Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Mahmoud Ali Khaled Mahmoud	Mohamed Abdulla		19.10.2025

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned own work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations and Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.






LIFTING EQUIPMENT CERTIFICATE OF VISUAL & THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client Name:	Hamza Abass Company. Al Basra, Iraq	Location:	Quality Control Yard
Description of Equipment:	Truck Mounted Hydraulic Operated Telescopic Boom Lorry Crane (HIAB)	Serial No:	0711176
Date of Examination:	20.10.2024	Certificate No:	QC-J-10-2024-0094-01
		SWL:	8300 KG @ 3.6 M

PICTORIAL



ASNT Level II Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Mahmoud Ali Khaled Mahmoud	Mohamed Abdulla		19.10.2025

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations and Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.




LIFTING EQUIPMENT CERTIFICATE OF VISUAL & THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client Name:	Hamza Abass Company. Al Basra, Iraq	Location:	Quality Control Yard
Description of Equipment:	Truck Mounted Hydraulic Operated Telescopic Boom Lorry Crane (HIAB)	Serial No:	0711176
Date of Examination:	20.10.2024	Certificate No:	QC-J-10-2024-0094-01
		SWL:	8300 KG @ 3.6 M



ASNT Level II Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Mahmoud Ali Khaled Mahmoud	Mohamed Abdulla		19.10.2025

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations and Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.