

**AI TAKAMUL COMPANY FOR ENGINEERING TESTS  
AND PROFESSIONAL SAFETY LIMITED**

Basra, North Rumaila, Quality Control Yard - Iraq

Tel: +9647810009138 / +9647834964657

Email: OP@qualitycontrol-iraq.com / hany.akafi@qualitycontrol-iraq.com



**CERTIFICATE OF THOROUGH EXAMINATION**

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

<b>Date of Examination:</b>	30.10.2024	<b>Date of Report:</b>	30.10.2024	<b>Certificate No:</b>	QC-Hall-HPS-2424-045
<b>Client Name:</b>	HALLIBURTON	<b>Location:</b>	HPS YARD	<b>Job Number:</b>	24102024
<b>Serial Number:</b>	QTY	<b>Description</b>	<b>WLL</b>	<b>Date of manufacture if known:</b>	<b>Date of last thorough examination</b>
47614	01	<b>FLAT POLYESTER WOVEN WEBBING SLING</b>  <b>Manufacture:</b> Delta plus <b>Material:</b> Polyester <b>Safety Factor:</b> 7:1 <b>Length:</b> 2 M <b>Color:</b> GREEN	Vertical 2000 kg Chocker 1600 Kg Basket 4000 kg	06/2023	NEW
<b>Reference Standard:</b>	BS EN 1492-1 / HAL DOC: WM-GL-HAL-HSE-0420F & WM-GL-HAL-HSE-0420C REV 1				
Is this the first examination after Installation or assembly at a new site or location?		YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>	Was the examination carried out: Within an interval of 6 months? With an interval of 12 months? In accordance with an examination scheme? After the occurrence of exceptional circumstances?		YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>
If the answer to the above question is YES has the equipment been installed correctly?		YES <input type="checkbox"/> NO <input type="checkbox"/>			YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>
		N/A			YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none state NONE) NONE					
Is the above a defect which is of immediate danger to persons:					YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)					N/A
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
Particulars of any tests carried out as part of the examination: (If none state NONE) The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory					
<b>IS THIS EQUIPMENT SAFE TO OPERATE?</b>					YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>
<b>Name of Inspector:</b>	<b>Name of person authenticating this report:</b>		<b>Signature &amp; Stamp:</b>		
ASHRAF ELSAID	MOHAMED ABDALLAH				
<b>Date of Next Through Examination:</b>	29.04.2025				

REV: 01 Dated: 20 June 2022

**THIS IS TO CERTIFY THAT;** a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.

