QUALITY CONTROL	**Al Takamul Company for Engineering Services** **Quality Control - Iraq**	

LIFTING ACCESSORIES OF VISUAL AND THOROUGH EXAMINATION & NDT

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	Aberdeen Technical Services	**Certificate no:**	QC-YB-240020/07
Location:	ATS Yard	**Job Order No:**	QC-YB-240020
Date of Examination:	02/Nov/2024	**Next Inspection Due:**	01/May/2025
Last Inspection		**Last Proof Load Test Date**	
24/May/2024		By Manufacture	

IDENTIFICATION NO	DESCRIPTION	QTY	SWL
67751807015 67751807001 57751807018 18-1	Horizontal plate lifting clamp Manufacture: Toyolift Model: TL-FHX020 Jaw opening range: 0 – 60 mm Each pair SWL: 2 tons	04	2 TONS Each Pair

Applicable Reference Standard:	BS EN 13155:2020								
					Was the examination carried out?				
*** Is this the first examination after installation or assembly at a new site or location?**	YES		NO	√	*** Within an interval of 6 months?**	YES	√	NO	
					*** Within an interval of 12 months?**	YES		NO	√
*** If the answer to the above question is YES has the equipment been installed correctly?**	YES	√	NO		*** In accordance with an examination scheme?**	YES	√	NO	
					*** After the occurrence of exceptional circumstances?**	YES		NO	√

Identification Of Any Part Found to Have a Defect Which Is or Could Become a Danger to Persons and a Description of The Defect: **None**

Is The Above a Defect Which Is of Immediate Danger to Persons			**YES**		**NO**	√
Is The Above a Defect Which Is Not Yet but Could Become a Danger to Persons: (If YES State the Date by When)	**NO**	√	**YES**		**By:**	

Particulars Of Any Repair, Renewal or Alteration Required to Remedy the Defect Identified Above: **None**

**** Visual And Dimension Check was Carried Out.**

Is This Equipment Safe to Operate?	**Yes Accept**	√	**NO Reject**	

LEEA & ASNT Level II Inspector Name:	SIGNATURE:	Authenticating This Report:	SIGNATURE:
Mohamed Abdullah		**Ashraf El Said**	

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection. And considered Safe for Lifting.