



Al Takamul Company for Engineering Services
Quality Control - Iraq



LIFTING ACCESSORIES OF VISUAL AND THOROUGH EXAMINATION & NDT

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	Aberdeen Technical Services	Certificate no:	QC-YB-240020/10
Location:	ATS Yard	Job Order No:	QC-YB-240020
Date of Examination:	02/Nov/2024	Next Inspection Due:	01/May/2025
Last Inspection		Last Proof Load Test Date	
24/May/2024		By Manufacture	

IDENTIFICATION NO	DESCRIPTION	QTY	SWL
0154	Lanyard shock absorber Manufacture: kratos Model No: FAP30199(6) Mfrd: 01/2019 Average arresting force: 900 lbs Size: 6 ft	01	130 – 310 (lbs)

Applicable Reference Standard:	BS EN 354:2010								
* Is this the first examination after installation or assembly at a new site or location?	YES		NO	√	Was the examination carried out?				
					* Within an interval of 6 months?	YES	√	NO	
* If the answer to the above question is YES has the equipment been installed correctly?					* Within an interval of 12 months?	YES		NO	√
	YES	√	NO		* In accordance with an examination scheme?	YES	√	NO	
					* After the occurrence of exceptional circumstances?	YES		NO	√

Identification Of Any Part Found to Have a Defect Which Is or Could Become a Danger to Persons and a Description of The Defect: **None**

Is The Above a Defect Which Is of Immediate Danger to Persons	YES		NO	√
Is The Above a Defect Which Is Not Yet but Could Become a Danger to Persons: (If YES State the Date by When)	NO	√	YES	By:
Particulars Of Any Repair, Renewal or Alteration Required to Remedy the Defect Identified Above: None				
** Visual And Dimension Check was Carried Out.				
Is This Equipment Safe to Operate?	Yes Accept	√	NO Reject	

LEE & ASNT Level II Inspector Name:	SIGNATURE:	Authenticating This Report:	SIGNATURE:
Mohamed Abdullah		Ashraf El Said	

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection. And considered Safe for Lifting.

