




**LIFTING ACCESSORIES OF VISUAL AND THOROUGH EXAMINATION & NDT**

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

<b>Client:</b>	Aberdeen Technical Services	<b>Certificate no:</b>	QC-YB-240020/13
<b>Location:</b>	ATS Yard	<b>Job Order No:</b>	QC-YB-240020
<b>Date of Examination:</b>	02/Nov/2024	<b>Next Inspection Due:</b>	01/May/2025
<b>Last Inspection</b>		<b>Last Proof Load Test Date</b>	
24/May/2024		By Manufacture	

IDENTIFICATION NO	DESCRIPTION	QTY	SWL
03	Mechanical joining device  Manufacture: MT Grade: 8 Size: 16 mm	04	8 Tons
04			
05			
06			

<b>Applicable Reference Standard:</b>	BS EN 1677-1:2000+A1:2008								
* Is this the first examination after installation or assembly at a new site or location?	YES		NO	√	<b>Was the examination carried out?</b>				
					* Within an interval of 6 months?	YES	√	NO	
* If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO		* Within an interval of 12 months?	YES		NO	√
					* In accordance with an examination scheme?	YES	√	NO	
					* After the occurrence of exceptional circumstances?	YES		NO	√
Identification Of Any Part Found to Have a Defect Which Is or Could Become a Danger to Persons and a Description of The Defect: <b>None</b>									
Is The Above a Defect Which Is of Immediate Danger to Persons					YES		NO	√	
Is The Above a Defect Which Is Not Yet but Could Become a Danger to Persons: (If YES State the Date by When)					NO	√	YES		By:
Particulars Of Any Repair, Renewal or Alteration Required to Remedy the Defect Identified Above: <b>None</b>									
<b>** Visual And Dimension Check was Carried Out.</b>									
Is This Equipment Safe to Operate?					Yes Accept	√	NO Reject		

<b>LEEA &amp; ASNT Level II Inspector Name:</b>	<b>SIGNATURE:</b>	<b>Authenticating This Report:</b>	<b>SIGNATURE:</b>
Mohamed Abdullah		Ashraf El Said	

**THIS IS TO CERTIFY THAT;** a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection. And considered Safe for Lifting.