



**LIFTING ACCESSORIES OF VISUAL AND THOROUGH EXAMINATION & NDT**

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

<b>Client:</b>	Aberdeen Technical Services	<b>Certificate no:</b>	QC-YB-240020/03
<b>Location:</b>	ATS Yard	<b>Job Order No:</b>	QC-YB-240020
<b>Date of Examination:</b>	02/Nov/2024	<b>Next Inspection Due:</b>	01/May/2025
<b>Last Inspection</b>		<b>Last Proof Load Test Date</b>	
24/May/2024		By Manufacture	

IDENTIFICATION NO	DESCRIPTION	QTY	SWL
1119018 1119019	<b>Jaw winch</b>  <b>Manufacture: Tractel</b> <b>Model: Tirfor TU16</b> <b>Wire size: 11.5 mm</b> <b>Rope serial no: 21</b> <b>+V120E10 + V203E10</b> <b>Length (m): 20.2 + 10.2</b> <b>+ 9.4</b>	02	1600 daN (KG)

<b>Applicable Reference Standard:</b>	BS EN 13157:2004+A1:2009								
* Is this the first examination after installation or assembly at a new site or location?	YES		NO	√	<b>Was the examination carried out?</b>				
					* Within an interval of 6 months?	YES	√	NO	
* If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO		* Within an interval of 12 months?	YES		NO	√
					* In accordance with an examination scheme?	YES	√	NO	
					* After the occurrence of exceptional circumstances?	YES		NO	√

Identification Of Any Part Found to Have a Defect Which Is or Could Become a Danger to Persons and a Description of The Defect: **None**

Is The Above a Defect Which Is of Immediate Danger to Persons **YES** **NO** √

Is The Above a Defect Which Is Not Yet but Could Become a Danger to Persons: **NO** √ **YES** **By:**

Particulars Of Any Repair, Renewal or Alteration Required to Remedy the Defect Identified Above: **None**

**\*\* Visual And Dimension Check was Carried Out.**

Is This Equipment Safe to Operate? **Yes Accept** √ **NO Reject**

<b>LEE &amp; ASNT Level II Inspector Name:</b>	<b>SIGNATURE:</b>	<b>Authenticating This Report:</b>	<b>SIGNATURE:</b>
Mohammed Abdullah Mohamed Al-Ilfi		Ashraf El-said	Ashraf El-said

**THIS IS TO CERTIFY THAT:** a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection. And considered Safe for Lifting.

