

**AI TAKAMUL COMPANY FOR ENGINEERING TESTS  
AND PROFESSIONAL SAFETY LIMITED**

Basra, North Rumaila, Quality Control Yard - Iraq




**CERTIFICATE OF QUALIFICATION VISUAL INSPECTION AND LEAK TESTING**

THIS REPORT COMPLIES WITH RECOGNIZED INTERNATIONAL STANDARDS & TECHNICAL REQUIREMENTS

<b>CLIENT:</b>	<b>HALLIBURTON (HPS)</b>		
<b>LOCATION:</b>	HPS YARD	<b>REPORT No.:</b>	QC-25-HALL-HPS-MARCH- VT & LEAK -005B
<b>STANDARD:</b>	CUSOMER SPECIFICATION	<b>JOB NO:</b>	QC-25/HALL-HPS-008
<b>INSPECTION DATE:</b>	Thursday, March 20, 2025	<b>Due Date</b>	<b>Friday, September 19, 2025</b>
<b>TYPE OF INSPECTION:</b>	<b>*VISUAL TESTING AND *LEAK TESTING</b>		
<b>DESCRIPTION:</b>	<b>FRAC TANK</b>	<b>SAP NO:</b>	<b>12353286</b>
<b>MEDIUM USED:</b>	<b>WATER</b>	<b>HOLDING TIME:</b>	<b>15 MINUTES</b>

**PICTURES**



**INSPECTION RESULT**

<b>VISUAL TESTING:</b>	Visual Testing of Frac Tank did not found Deforms Mechanical Damage, Cracks and Corrosion. At time of Inspection.
<b>LEAK TESTING:</b>	Leak Testing of Frac Tank did not found any leakage during the holding time. At time of Inspection.

**Inspection Evaluation**

**VISUAL TESTING-**The above mentioned Frac Tank was found "Satisfactory" Fit for intended used.

**LEAK TESTING-** The above mentioned Frac Tank was found "Satisfactory" Fit for intended used.

PERSONNEL DETAILS			REVIEW BY		
<b>NAME:</b>	ASHRAF ELSAID		<b>SENIOR INSPECTOR:</b>	Mohamed Abdullah	<b>CUSTOMER NAME</b>
<b>QUALIFICATION:</b>	ASNT LEVEL II MT,PT,VT		<b>SUPERVISOR:</b>	HANI ALI	
<b>STAMP &amp; SIGNATURE:</b>			<b>DATE:</b>		

Original - Client Files Copy - Area Office QC/FN/MPI/065 Rev.00 DATED 07 NOV 2021



Tel: +9647810009138 / +9647834964657  
Email: OP@qualitycontrol-iraq.com  
hany.akafi@qualitycontrol-iraq.com