



Al Takamul Company for Engineering Services  
Quality Control – Iraq



### LIFTING ACCESSORIES OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	Al-Eshriaq Company	Certificate no:	QC-J-11-2024-0106/01
Location:	Quality Control Yard	Job Order No:	QC-J-11-2024-0106
Date of Examination:	08-Nov-2024	Next Inspection Due:	07-May-2025
Last Inspection		Last Proof Load Test Date	
New		By Manufacture	

IDENTIFICATION NO	DESCRIPTION	QTY	SWL
78715375-01	<p>SAFETY BODY HARNESS WITH LANYARD</p> <p>Model: WK JS 41            Manufacturer: Workman            Date Of Manufacturer: Aug-2023            Size: X-Larg            Shock Absorber SN: 78717120-01</p>	01	One Person
Reference Standard:	EN 361, EN 358		

**RESULTS INSPECTION ON THE SAFETY BODY HARNESS ACCEPTANCE AS FOLLOWS:**

Item	Inspection Point	Yes	No
1	18" EXTENDED BACK D-RING	✓	
2	BACK PADDING	✓	
3	OVERSIZED ID TAG	✓	
4	WEB FINIAL	✓	
5	CAM BUCKLE	✓	
6	ENHANCED LUMBAR PADDING	✓	
7	SEAT SLING WITH SIDE D-RING	✓	
8	LEG PADDING	✓	
9	TONGUE BUCKLE LEGS	✓	
10	REMOVABLE BELT WITH LEATHER GUIDE	✓	
11	MESH BACK SHIELD	✓	
12	MATING BUCKLE CHEST STRAP	✓	
13	INTEGRAL LABEL PACK	✓	
14	FRONT D-RING	✓	
15	PATENTED DURAFLEX STRETCHABLE WEBBING	✓	
16	STAND UP BACK D-RING	✓	
17	OPTIONAL BOS'N CHAIR WITH SIDE D-RING	✓	

The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307  
 The Supply of Machinery (Safety) Regulations 1992 S.I. No. 3073  
 The Provision and Use of Work Equipment Regulations 1998 S.I. No. 2306

LEEA & ASNT Level II Inspector Name:	SIGNATURE:	Authenticating This Report:	SIGNATURE:
Khaled Mahmoud Mahmoud Ali		Mohamed Abdalla	

**THIS IS TO CERTIFY THAT;** a competent person did attend the above-mentioned owner’s work location on the date shown above and the Equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation “LOLER”. The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.

