




LIFTING ACCESSORIES OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	Tareeq Al Salim company	Certificate no:	QC-YB-240059/01
Location:	Quality Control Yard	Job Order No:	QC-YB-240059
Date of Examination:	17-Nov-2024	Next Inspection Due:	16-May-2025
Last Inspection		Last Proof Load Test Date	
New		By Manufacture	

IDENTIFICATION NO	DESCRIPTION	QTY	SWL
SC736 SC737 SC738 SC739 SC740 SC741	<p>Safety pin bow Shackles</p> <p>Size: 7/8"</p> <p>Grade: 6</p> <p>Manufacturer: Lifmex</p> <p>Safety Factor 6:1</p> 	06	6.5 ton

Reference Standard:	BS EN 13889
---------------------	-------------

Is this the first examination after Installation or assembly at a new site or location?	YES	NO	v	Was the examination carried out: Within an interval of 6 months?	YES	NO	v
					With an interval of 12 months?	YES	NO
If the answer to the above question is YES has the equipment been installed correctly?	YES	NO		By an examination scheme?	YES	NO	
				After the occurrence of exceptional circumstances?	YES	NO	v

Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none state NONE) **NONE**

Is the above a defect which is of immediate danger to persons: YES NO v

Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when) N/A

Particulars of any repair, renewal, or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: (If none state NONE)

The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory

IS THIS EQUIPMENT SAFE TO OPERATE? YES NO

LEEA & ASNT Level II Inspector Name:	Signature:	Authenticating This Report:	Signature:
Khaled Mahmoud Mahmoud Ali		Ashraf El-said	



THIS IS TO CERTIFY THAT: a competent person did attend to the owner as mentioned earlier work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.