




**LIFTING ACCESSORIES OF VISUAL AND THOROUGH EXAMINATION**

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	Tareeq Al Salim company	Certificate no:	QC-YB-240059/02
Location:	Quality Control Yard	Job Order No:	QC-YB-240059
Date of Examination:	17-Nov-2024	Next Inspection Due:	16-May-2025
Last Inspection		Last Proof Load Test Date	
New		By Manufacture	

IDENTIFICATION NO	DESCRIPTION	QTY	SWL
SC742 SC743 SC744 SC745 SC746 SC747	<p>Safety pin bow Shackles</p> <p>Size: 7/8"</p> <p>Grade: 6</p> <p>Manufacturer: Lifmex</p> <p>Safety Factor 6:1</p> 	06	6.5 ton

Reference Standard:	BS EN 13889
---------------------	-------------

Is this the first examination after Installation or assembly at a new site or location?	YES		NO	v	Was the examination carried out: Within an interval of 6 months?	YES	v	NO	
						With an interval of 12 months?	YES		NO
If the answer to the above question is YES has the equipment been installed correctly?	YES		NO		By an examination scheme?	YES	v	NO	
					After the occurrence of exceptional circumstances?	YES		NO	v

Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none state NONE) **NONE**

Is the above a defect which is of immediate danger to persons: YES  NO

Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when) N/A

Particulars of any repair, renewal, or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: (If none state NONE)

The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory

**IS THIS EQUIPMENT SAFE TO OPERATE?** YES  NO

LEEA & ASNT Level II Inspector Name:	Signature:	Authenticating This Report:	Signature:
Khaled Mahmoud Mahmoud Ali		Ashraf El-said	



**THIS IS TO CERTIFY THAT:** a competent person did attend to the owner as mentioned earlier work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.