





**LIFTING ACCESSORIES OF VISUAL AND THOROUGH EXAMINATION**

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

<b>Client:</b>	Egyptian Maintenance Company	<b>Certificate no:</b>	QC-YB-240043-08
<b>Location:</b>	Quality Control Yard	<b>Job Order No:</b>	QC-YB-240043
<b>Date of Examination:</b>	10/Nov/2024	<b>Next Inspection Due:</b>	09/May/2025
<b>Last Inspection</b>		<b>Last Proof Load Test Date</b>	
New		By Manufacture	

IDENTIFICATION NO	DESCRIPTION	QTY	SWL
H3 H4 H5	<p><b>Single Leg Wire Rope Sling</b></p> <p>Diameter: 10 mm Length: 8.40 m Safety Factor: 5:1</p> <p>Non-Rotating Const.6×19, IWRC, RHO, Galv Steel IWRC, Mechanically Spliced with Aluminum Ferrule. Soft Eye X Soft Eye.</p> 	03	1.28 Ton
<b>Applicable Reference Standard:</b>	BS EN 13414-1:2003+A2:2008		
* Is this the first examination after installation or assembly at a new site or location?	YES	NO	√
	Was the examination carried out?		
* If the answer to the above question is YES has the equipment been installed correctly?	YES	NO	
	* Within an interval of 6 months?		YES √ NO
* Within an interval of 12 months?		YES	NO √
* In accordance with an examination scheme?		YES √	NO
* After the occurrence of exceptional circumstances?		YES	NO √
Identification Of Any Part Found to Have a Defect Which Is or Could Become a Danger to Persons and a Description of The Defect: <b>None</b>			
Is The Above a Defect Which Is of Immediate Danger to Persons	YES	NO	√
Is The Above a Defect Which Is Not Yet but Could Become a Danger to Persons: (If YES State the Date by When)	NO	√	YES
Particulars Of Any Repair, Renewal or Alteration Required to Remedy the Defect Identified Above: <b>None</b>			
<b>** Visual And Dimension Check was Carried Out.</b>			
Is This Equipment Safe to Operate?	Yes Accept	√	NO Reject

<b>LEE &amp; ASNT Level II Inspector Name:</b>	<b>SIGNATURE:</b>	<b>Authenticating This Report:</b>	<b>SIGNATURE:</b>
Mahmoud Ali		Ashraf El-said	

**THIS IS TO CERTIFY THAT:** a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection. And considered Safe for Lifting.

