

**AI TAKAMUL COMPANY FOR ENGINEERING TESTS  
AND PROFESSIONAL SAFETY LIMITED**

Basra, North Rumaila, Quality Control Yard - Iraq

Tel: +9647834966105 / +9647834964657

Email: ashraf.said@qualitycontrol-iraq.com / hany.akafi@qualitycontrol-iraq.com



## Certificate of visual and thorough examination

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

<b>Date of Examination:</b>	17-Nov-2024	<b>Date of Report:</b>	17-Nov-2024	<b>Certificate No:</b>	QC-YB-240059/01
<b>Client Name:</b>	HALLIBURTON	<b>Location:</b>	HPS	<b>Job Number:</b>	QC-YB-240059

Serial Number:	QTY	Description	SWL	Date of last thorough examination
SC736 SC737 SC738 SC739 SC740 SC741	06	<b>Safety pin bow Shackles</b>  Size: 7/8" Grade: 6 Manufacturer: Lifmex Safety Factor 6:1	6.5 TON	New

**Reference Standard:** BS EN 13889/ HAL DOC: WM-GL-HAL-HSE-0420F & WM-GL-HAL-HSE-0420C REV 1

Is this the first examination after Installation or assembly at a new site or location?	YES	NO	✓	Was the examination carried out: Within an interval of 6 months? With an interval of 12 months? In accordance with an examination scheme? After the occurrence of exceptional circumstances?	YES	✓	NO	✓
If the answer to the above question is YES has the equipment been installed correctly?	YES	NO			YES	✓	NO	

Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none state NONE) **NONE**

Is the above a defect which is of immediate danger to persons: YES  NO



Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when) **N/A**

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: (If none state NONE)

The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory

**IS THIS EQUIPMENT SAFE TO OPERATE?** YES  NO

<b>Name of Inspector:</b>	<b>Name of person authenticating this report:</b>	<b>Signature &amp; Stamp:</b>	
ASHRAF ELSAID	MOHAMMED ABDULLAH		
<b>Date of Next Through Examination:</b>	<b>16-May-2025</b>		

REV: 01 Dated: 20 June 2022

**THIS IS TO CERTIFY THAT;** a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



**AI TAKAMUL COMPANY FOR ENGINEERING TESTS  
AND PROFESSIONAL SAFETY LIMITED**

Basra, North Rumaila, Quality Control Yard - Iraq

Tel: +9647834966105 / +9647834964657

Email: ashraf.said@qualitycontrol-iraq.com / hany.akafi@qualitycontrol-iraq.com



## Certificate of visual and thorough examination

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

<b>Date of Examination:</b>	17-Nov-2024	<b>Date of Report:</b>	17-Nov-2024	<b>Certificate No:</b>	QC-YB-240059/02
<b>Client Name:</b>	HALLIBURTON	<b>Location:</b>	HPS	<b>Job Number:</b>	QC-YB-240059

Serial Number:	QTY	Description	SWL	Date of last thorough examination
SC742 SC743 SC744 SC745 SC746 SC747	06	<b>Safety pin bow Shackles</b>  Size: 7/8" Grade: 6 Manufacturer: Lifmex Safety Factor 6:1	6.5 TON	New

**Reference Standard:** BS EN 13889/ HAL DOC: WM-GL-HAL-HSE-0420F & WM-GL-HAL-HSE-0420C REV 1

Is this the first examination after Installation or assembly at a new site or location?	YES	NO	√	Was the examination carried out: Within an interval of 6 months? With an interval of 12 months? In accordance with an examination scheme? After the occurrence of exceptional circumstances?	YES	√	NO	√
If the answer to the above question is YES has the equipment been installed correctly?	YES	NO			YES	√	NO	
					YES		NO	√

Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none state NONE) **NONE**

Is the above a defect which is of immediate danger to persons: YES  NO



Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when) **N/A**

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: (If none state NONE)

The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory

**IS THIS EQUIPMENT SAFE TO OPERATE?** YES  NO

<b>Name of Inspector:</b>	<b>Name of person authenticating this report:</b>	<b>Signature &amp; Stamp:</b>	
ASHRAF ELSAID	MOHAMMED ABDULLAH		
<b>Date of Next Through Examination:</b>	<b>16-May-2025</b>		

REV: 01 Dated: 20 June 2022

**THIS IS TO CERTIFY THAT;** a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



**AI TAKAMUL COMPANY FOR ENGINEERING TESTS  
AND PROFESSIONAL SAFETY LIMITED**

Basra, North Rumaila, Quality Control Yard - Iraq

Tel: +9647834966105 / +9647834964657

Email: ashraf.said@qualitycontrol-iraq.com / hany.akafi@qualitycontrol-iraq.com



## Certificate of visual and thorough examination

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

<b>Date of Examination:</b>	17-Nov-2024	<b>Date of Report:</b>	17-Nov-2024	<b>Certificate No:</b>	QC-YB-240059/03
<b>Client Name:</b>	HALLIBURTON	<b>Location:</b>	HPS	<b>Job Number:</b>	QC-YB-240059

Serial Number:	QTY	Description	SWL	Date of last thorough examination
WS1-354 WS1-355 WS1-356 WS1-357	04	<b>Single Leg Wire Rope Sling</b>  <b>Wire Length:</b> 30 M <b>Wire Dimeter:</b> 16 mm <b>Safety Factor:</b> 6:1 <b>Manufacturer:</b> Lifmex 6X36 IWRC, Rope Grade 1960 N/MM2 Galvanized Mechanically Spliced with Aluminium Ferrule, Steel Core. Hard Eye at Both End.	3 TON	New

<b>Reference Standard:</b>	BS EN 13414-1/ HAL DOC: WM-GL-HAL-HSE-0420F & WM-GL-HAL-HSE-0420C REV 1
----------------------------	---

Is this the first examination after Installation or assembly at a new site or location?  If the answer to the above question is YES has the equipment been installed correctly?	YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>	Was the examination carried out: Within an interval of 6 months? With an interval of 12 months? In accordance with an examination scheme? After the occurrence of exceptional circumstances?	YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>	YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>	YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>	YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>
---	---	--	---	---	---	---

Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none state NONE) **NONE**

Is the above a defect which is of immediate danger to persons: YES  NO

Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when) N/A

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: (If none state NONE)

The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory

**IS THIS EQUIPMENT SAFE TO OPERATE?** YES  NO

<b>Name of Inspector:</b>	<b>Name of person authenticating this report:</b>	<b>Signature &amp; Stamp:</b>	
ASHRAF ELSAID	MOHAMMED ABDULLAH		
<b>Date of Next Through Examination:</b>	<b>16-May-2025</b>		

REV: 01 Dated: 20 June 2022

**THIS IS TO CERTIFY THAT;** a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



**AI TAKAMUL COMPANY FOR ENGINEERING TESTS  
AND PROFESSIONAL SAFETY LIMITED**

Basra, North Rumaila, Quality Control Yard - Iraq

Tel: +9647834966105 / +9647834964657

Email: ashraf.said@qualitycontrol-iraq.com / hany.akafi@qualitycontrol-iraq.com



## Certificate of visual and thorough examination

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

<b>Date of Examination:</b>	17-Nov-2024	<b>Date of Report:</b>	17-Nov-2024	<b>Certificate No:</b>	QC-YB-240059/04
<b>Client Name:</b>	HALLIBURTON	<b>Location:</b>	HPS	<b>Job Number:</b>	QC-YB-240059

Serial Number:	QTY	Description	SWL	Date of last thorough examination
WS1-358 WS1-359 WS1-360 WS1-361	04	<b>Single Leg Wire Rope Sling</b>  <b>Wire Length:</b> 2 M <b>Wire Dimeter:</b> 16 mm <b>Safety Factor:</b> 6:1 <b>Manufacturer:</b> Lifmex 6X36 IWRC, Rope Grade 1960 N/MM2 Galvanized Mechanically Spliced with Aluminium Ferrule, Steel Core. Hard Eye at Both End.	3 TON	New

**Reference Standard:** BS EN 13414-1/ HAL DOC: WM-GL-HAL-HSE-0420F & WM-GL-HAL-HSE-0420C REV 1

Is this the first examination after Installation or assembly at a new site or location?  If the answer to the above question is YES has the equipment been installed correctly?	YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>	Was the examination carried out: Within an interval of 6 months? With an interval of 12 months? In accordance with an examination scheme? After the occurrence of exceptional circumstances?	YES <input checked="" type="checkbox"/> NO <input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>
---	---	--	--

Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none state NONE) **NONE**

Is the above a defect which is of immediate danger to persons: YES  NO

Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when) N/A

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: (If none state NONE)

The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory

**IS THIS EQUIPMENT SAFE TO OPERATE?** YES  NO

<b>Name of Inspector:</b>	<b>Name of person authenticating this report:</b>	<b>Signature &amp; Stamp:</b>	
ASHRAF ELSAID	MOHAMMED ABDULLAH		
<b>Date of Next Through Examination:</b>	<b>16-May-2025</b>		

REV: 01 Dated: 20 June 2022

**THIS IS TO CERTIFY THAT;** a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



**AI TAKAMUL COMPANY FOR ENGINEERING TESTS  
AND PROFESSIONAL SAFETY LIMITED**

Basra, North Rumaila, Quality Control Yard - Iraq

Tel: +9647834966105 / +9647834964657

Email: ashraf.said@qualitycontrol-iraq.com / hany.akafi@qualitycontrol-iraq.com



## Certificate of visual and thorough examination

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

<b>Date of Examination:</b>	17-Nov-2024	<b>Date of Report:</b>	17-Nov-2024	<b>Certificate No:</b>	QC-YB-240059/05
<b>Client Name:</b>	HALLIBURTON	<b>Location:</b>	HPS	<b>Job Number:</b>	QC-YB-240059

Serial Number:	QTY	Description	SWL	Date of last thorough examination
24071131 24071134 24071136 24071163	04	<b>Single Leg Wire Rope Sling</b>  <b>Wire Length:</b> 20 M <b>Wire Dimeter:</b> 16 mm <b>Safety Factor:</b> 6:1 <b>Manufacturer:</b> Lifmex 6X36 IWRC, Rope Grade 1960 N/MM2 Galvanized Mechanically Spliced with Aluminium Ferrule, Steel Core. Hard Eye with Safety Hook at Plain.	3 TON	New

**Reference Standard:** BS EN 13414-1/ HAL DOC: WM-GL-HAL-HSE-0420F & WM-GL-HAL-HSE-0420C REV 1

Is this the first examination after Installation or assembly at a new site or location?  If the answer to the above question is YES has the equipment been installed correctly?	YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>	Was the examination carried out: Within an interval of 6 months? With an interval of 12 months? In accordance with an examination scheme? After the occurrence of exceptional circumstances?	YES <input checked="" type="checkbox"/> NO <input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>
---	---	--	--

Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none state NONE) **NONE**

Is the above a defect which is of immediate danger to persons: YES  NO

Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when) N/A

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: (If none state NONE)

The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory

**IS THIS EQUIPMENT SAFE TO OPERATE?** YES  NO

<b>Name of Inspector:</b>	<b>Name of person authenticating this report:</b>	<b>Signature &amp; Stamp:</b>	
ASHRAF ELSAID	MOHAMMED ABDULLAH		
<b>Date of Next Through Examination:</b>	<b>16-May-2025</b>		

REV: 01 Dated: 20 June 2022

**THIS IS TO CERTIFY THAT;** a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



**AI TAKAMUL COMPANY FOR ENGINEERING TESTS  
AND PROFESSIONAL SAFETY LIMITED**

Basra, North Rumaila, Quality Control Yard - Iraq

Tel: +9647834966105 / +9647834964657

Email: ashraf.said@qualitycontrol-iraq.com / hany.akafi@qualitycontrol-iraq.com



## Certificate of visual and thorough examination

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

<b>Date of Examination:</b>	17-Nov-2024	<b>Date of Report:</b>	17-Nov-2024	<b>Certificate No:</b>	QC-YB-240059/06
<b>Client Name:</b>	HALLIBURTON	<b>Location:</b>	HPS	<b>Job Number:</b>	QC-YB-240059

Serial Number:	QTY	Description	SWL	Date of last thorough examination
24071131 24071134 24071136 24071163	04	<b>Wire Rope Winch (Tirfor)</b>  <b>Model:</b> LWRT3200 <b>Rope Diameter:</b> 16 mm <b>Rope Length:</b> 20 m <b>Wire Rope:</b> WLL 3000 kg Lifting <b>Manufacture:</b> Lifmex	3200 KG	New

<b>Reference Standard:</b>	BS EN 13157:2004/ HAL DOC: WM-GL-HAL-HSE-0420F & WM-GL-HAL-HSE-0420C REV 1
----------------------------	--

Is this the first examination after Installation or assembly at a new site or location?	YES	NO	✓	Was the examination carried out: Within an interval of 6 months?	YES	✓	NO	
				With an interval of 12 months?	YES		NO	✓
If the answer to the above question is YES has the equipment been installed correctly?	YES	NO		In accordance with an examination scheme?	YES	✓	NO	
				After the occurrence of exceptional circumstances?	YES		NO	✓

Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none state NONE) **NONE**

Is the above a defect which is of immediate danger to persons: YES  NO



Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when) N/A

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: (If none state NONE)

The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory

**IS THIS EQUIPMENT SAFE TO OPERATE?** YES  NO

<b>Name of Inspector:</b>	<b>Name of person authenticating this report:</b>	<b>Signature &amp; Stamp:</b>	
ASHRAF ELSAID	MOHAMMED ABDULLAH		
<b>Date of Next Through Examination:</b>	<b>16-May-2025</b>		

REV: 01 Dated: 20 June 2022

**THIS IS TO CERTIFY THAT;** a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.

