





### LIFTING ACCESSORIES OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

<b>Client:</b>	DAQING DRILLING COMPANY	<b>Certificate no:</b>	QC-DQ-12-24-0249/71
<b>Location:</b>	DQ RIG 022	<b>Job Order No:</b>	QC-YB-240135
<b>Date of Examination:</b>	21.Dec.2024	<b>Next Inspection Due:</b>	20.Jun.2025
<b>Last Inspection</b>		<b>Last Proof Load Test Date</b>	
15.Jun.2024		BY MANUFACTURE	

IDENTIFICATION NO	DESCRIPTION	QTY	SWL
P7027	<p><b>Four Leg Wire Rope Sling</b></p> <p>Diameter: 19 MM Length: 8 M</p>  <p>IWRC, MECANICALLY SPICED WITH STEEL FERRULE C/W MASTER LINK ASSEMBLY HARD EYE X SOFT EYE SAFETY FACTOR: 5:1 <b>Location: Attached With Sewage Tank</b></p>	01	9.0 TON
<b>Applicable Reference Standard:</b>	BS EN 13414-1:2003+A2:2008		
* Is this the first examination after installation or assembly at a new site or location?	Was the examination carried out?		
	YES	NO	√
* If the answer to the above question is YES has the equipment been installed correctly?	* Within an interval of 6 months?		
	YES	NO	√
	* Within an interval of 12 months?		
	YES	NO	√
	* By an examination scheme?		
	YES	NO	√
	* After the occurrence of exceptional circumstances?		
	YES	NO	√
Identification Of Any Part Found To Have A Defect Which Is Or Could Become A Danger To Persons And A Description Of The Defect: <b>None</b>			
Is The Above A Defect Which Is Of Immediate Danger To Persons		YES	NO
Is The Above A Defect Which Is Not Yet But Could Become A Danger To Persons: (If YES State The Date By When)		NO	By:
Particulars Of Any Repair, Renewal, Or Alteration Required To Remedy The Defect Identified Above: <b>None</b>			
<b>** Visual And Dimension Check was Carried Out.</b>			
Is This Equipment Safe To Operate?		Yes Accept	NO Reject

<b>LEE A &amp; ASNT Level II Inspector Name:</b>	<b>SIGNATURE:</b>	<b>Authenticating This Report:</b>	<b>SIGNATURE:</b>
MOHAMMED ABDULLAH		Ashraf Alsaad	

**THIS IS TO CERTIFY THAT:** a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.