





## LIFTING ACCESSORIES OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

<b>Client:</b>	DAQING DRILLING COMPANY	<b>Certificate no:</b>	QC-DQ-12-24-0249/76
<b>Location:</b>	DQ RIG 022	<b>Job Order No:</b>	QC-YB-240135
<b>Date of Examination:</b>	21.Dec.2024	<b>Next Inspection Due:</b>	20.Jun.2025
<b>Last Inspection</b>		<b>Last Proof Load Test Date</b>	
15.Jun.2024		BY MANUFACTURE	

IDENTIFICATION NO	DESCRIPTION	QTY	SWL
M1 15	<p><b>Safety pin bow Shackles</b></p> <p>Diameter: 7/8" Grade: 6 Manufacturer: H.K</p>  <p><b>Location: Store</b></p>	02	6.5 TON
<b>Applicable Reference Standard:</b>	BS EN 13889/US FED SPEC RR-C-27 1 D		
* Is this the first examination after installation or assembly at a new site or location?	<b>Was the examination carried out?</b>		
	YES	NO	√
* If the answer to the above question is YES has the equipment been installed correctly?	* Within an interval of 6 months?		
	YES	NO	√
	* Within an interval of 12 months?		
	YES	NO	√
	* By an examination scheme?		
	YES	NO	√
	* After the occurrence of exceptional circumstances?		
	YES	NO	√
Identification Of Any Part Found To Have A Defect Which Is Or Could Become A Danger To Persons And A Description Of The Defect: <b>None</b>			
Is The Above A Defect Which Is Of Immediate Danger To Persons		YES	NO
Is The Above A Defect Which Is Not Yet But Could Become A Danger To Persons:		NO	YES
(If YES State The Date By When)		√	By:
Particulars Of Any Repair, Renewal, Or Alteration Required To Remedy The Defect Identified Above: <b>None</b>			
<b>** Visual And Dimension Check was Carried Out.</b>			
Is This Equipment Safe To Operate?	Yes Accept	√	NO Reject

<b>LEE &amp; ASNT Level II Inspector Name:</b>	<b>SIGNATURE:</b>	<b>Authenticating This Report:</b>	<b>SIGNATURE:</b>
MOHAMMED ABDULLAH		Ashraf Alsaad	

**THIS IS TO CERTIFY THAT:** a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.