

**AI TAKAMUL COMPANY FOR ENGINEERING TESTS
AND PROFESSIONAL SAFETY LIMITED**

Basra, North Rumaila, Quality Control Yard - Iraq

Tel: +9647810009138 / +9647834964657

Email: OP@qualitycontrol-iraq.com / hany.akafi@qualitycontrol-iraq.com



CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Date of Examination:	11/FEB/2025	Date of Report:	11/FEB/2025	Certificate No:	QC-02-25-HALL-10																																
Client Name:	Halliburton	Location:	Sperry Workshop	Job Number:	040425																																
Serial Number:	QTY	Description	SWL	Date of manufacture if known:	Date of last thorough examination																																
C2597 C2563 F168 F169	04	<u>FLAT POLYESTER WOVEN WEBBING SLING</u> Manufacture: SAFETY MARINE SERVICES Material: Polyester Safety Factor: 7:1 Length: 1 M Width: 1 Inch Color: VIOLET	1 TON	01/FEB/2024	NEW																																
Reference Standard:	BS EN 1492-1 /HAL DOC: ST-GL-HAL-HSE-0420																																				
Is this the first examination after Installation or assembly at a new site or location?		<table border="1"> <tr> <td>YES</td> <td>√</td> <td>NO</td> <td></td> </tr> </table>		YES	√	NO		Was the examination carried out:																													
YES	√	NO																																			
If the answer to the above question is YES has the equipment been installed correctly?		<table border="1"> <tr> <td>YES</td> <td></td> <td>NO</td> <td></td> </tr> <tr> <td colspan="4">N/A</td> </tr> </table>		YES		NO		N/A				<table border="1"> <tr> <td colspan="2">Within an interval of 6 months?</td> <td>YES</td> <td>√</td> <td>NO</td> <td></td> </tr> <tr> <td colspan="2">Within an interval of 12 months?</td> <td>YES</td> <td></td> <td>NO</td> <td>√</td> </tr> <tr> <td colspan="2">In accordance with an examination scheme?</td> <td>YES</td> <td>√</td> <td>NO</td> <td></td> </tr> <tr> <td colspan="2">After the occurrence of exceptional circumstances?</td> <td>YES</td> <td></td> <td>NO</td> <td>√</td> </tr> </table>		Within an interval of 6 months?		YES	√	NO		Within an interval of 12 months?		YES		NO	√	In accordance with an examination scheme?		YES	√	NO		After the occurrence of exceptional circumstances?		YES		NO	√
YES		NO																																			
N/A																																					
Within an interval of 6 months?		YES	√	NO																																	
Within an interval of 12 months?		YES		NO	√																																
In accordance with an examination scheme?		YES	√	NO																																	
After the occurrence of exceptional circumstances?		YES		NO	√																																
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none state NONE) NONE																																					
Is the above a defect which is of immediate danger to persons:				YES	NO																																
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)				N/A																																	
Particulars of any repair, renewal or alteration required to remedy the defect identified above:																																					
Particulars of any tests carried out as part of the examination: (If none state NONE) The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory																																					
IS THIS EQUIPMENT SAFE TO OPERATE?				YES	NO																																
Name of Inspector:		Name of person authenticating this report:		Signature & Stamp																																	
ASHRAF ELSAID		M.ABDULLAH																																			
Date of Next Through Examination:		10/AUG/2025																																			

REV: 02 Dated: 01 NOV 2023

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.

