

**AI TAKAMUL COMPANY FOR ENGINEERING TESTS  
AND PROFESSIONAL SAFETY LIMITED**

Basra, North Rumaila, Quality Control Yard - Iraq

Tel: +9647810009138 / +9647834964657

Email: [OP@qualitycontrol-iraq.com](mailto:OP@qualitycontrol-iraq.com) / [hany.akafi@qualitycontrol-iraq.com](mailto:hany.akafi@qualitycontrol-iraq.com)



**CERTIFICATE OF THOROUGH EXAMINATION**

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

<b>Date of Examination:</b>	22/02/2025	<b>Date of Report:</b>	22/02/2025	<b>Certificate No:</b>	QC-25/-WPS-2202-007
<b>Client Name:</b>	HALLIBURTON	<b>Location:</b>	WPS	<b>Job Number:</b>	220225

Serial Number:	QTY	Description	SWL	Date of manufacture if known:	Date of last thorough examination
F6839	01	<p align="center"><b><u>SAFETY PIN BOW SHACKLE</u></b></p> <p>MANUFACTURER: BASH P</p> <p>SIZE: 1 1/8"</p> <p>GRADE: 6</p> <p>FOS: 5:1</p>	9.5 TON	N/A	01/07/2024

**Reference Standard:** BS EN 13889/ HAL DOC: ST-GL-HAL-HSE-0420

Is this the first examination after Installation or assembly at a new site or location?	YES	NO	✓	Was the examination carried out: Within an interval of 6 months? With an interval of 12 months? In accordance with an examination scheme? After the occurrence of exceptional circumstances?	YES	✓	NO	
					YES		NO	✓
If the answer to the above question is YES has the equipment been installed correctly?	YES	NO			YES	✓	NO	
					YES		NO	✓

Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none state NONE) **NONE**

Is the above a defect which is of immediate danger to persons: YES  NO

Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when) N/A

Particulars of any repair, renewal or alteration required to remedy the defect identified above:


Particulars of any tests carried out as part of the examination: (If none state NONE)

The subject items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory

**IS THIS EQUIPMENT SAFE TO OPERATE?** YES  NO

<b>Name of Inspector:</b>	<b>Name of person authenticating this report:</b>	<b>Client Signature &amp; Stamp:</b>	
ASHRAF ELSAID	MOHAMED ABDALLAH	<b>ALI Talib HB48903</b>	
<b>Date of Next Through Examination:</b>	21/08/2025	<b>Date: 23/02/2025</b> <b>Signature</b> <b>Haliburton</b>	

REV: 01 Dated: 20 June 2022



**THIS IS TO CERTIFY THAT;** a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of inspection and considered Safe for Lifting.

