

**AI TAKAMUL COMPANY FOR ENGINEERING TESTS  
AND PROFESSIONAL SAFETY LIMITED**

Basra, North Rumaila, Quality Control Yard - Iraq

Tel: +9647810009138 / +9647834964657

Email: [OP@qualitycontrol-iraq.com](mailto:OP@qualitycontrol-iraq.com) / [hany.akafi@qualitycontrol-iraq.com](mailto:hany.akafi@qualitycontrol-iraq.com)



**CERTIFICATE OF THOROUGH EXAMINATION**

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

<b>Date of Examination:</b>	16/03/2025	<b>Date of Report:</b>	16/03/2025	<b>Certificate No:</b>	QC-25-TSS-1603-031
<b>Client Name:</b>	HALLIBURTON	<b>Location:</b>	TSS YARD	<b>Job Number:</b>	16032025
<b>Serial Number:</b>	QTY	<b>Description</b>	<b>SWL</b>	<b>Date of manufacture if known:</b>	<b>Date of last thorough examination</b>
338634-2-5	1	<b>4 LEG WIRE ROPE SLING</b> <b>Manufacture:</b> HOLLOWAY <b>DIM:</b> 13 MM (DIA) X 0.45 M (L) IWRC MECHANICALLY SPLICED WITH ALUMINUM FERRULES C/W MASTER LINK ASSEMBLY AT THE TOP  HARD EYE BOTH ENDS  S.F: 5:1	8.7 T at 60° Angle	15/7/2009	29/08/2024
<b>Reference Standard:</b>		BS EN 13414-1/ HAL DOC: WM-GL-HAL-HSE-0420F & WM-GL-HAL-HSE-0420C REV 1			
Is this the first examination after Installation or assembly at a new site or location?		YES <input type="checkbox"/>	NO <input checked="" type="checkbox"/>	Was the examination carried out: Within an interval of 6 months? YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>	
If the answer to the above question is YES has the equipment been installed correctly?		YES <input type="checkbox"/>	NO <input type="checkbox"/>	With an interval of 12 months? YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>	
		YES <input type="checkbox"/>	NO <input type="checkbox"/>	In accordance with an examination scheme? YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>	
		YES <input type="checkbox"/>	NO <input type="checkbox"/>	After the occurrence of exceptional circumstances? YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>	
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none state NONE) NONE					
Is the above a defect which is of immediate danger to persons:				YES <input type="checkbox"/>	NO <input checked="" type="checkbox"/>
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)				N/A	
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
Particulars of any tests carried out as part of the examination: (If none state NONE) The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory					
<b>IS THIS EQUIPMENT SAFE TO OPERATE?</b>				YES <input checked="" type="checkbox"/>	NO <input type="checkbox"/>
<b>Name of Inspector:</b>	<b>Name of person authenticating this report:</b>		<b>Signature &amp; Stamp:</b>		
ASHRAF ELSAID	MOHAMED ABDALLAH				
<b>Date of Next Through Examination:</b>	15/09/2025				

REV: 00 Dated: 30 May 2021

**THIS IS TO CERTIFY THAT;** a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.

