




Al Takamul Company for Engineering Services  
Quality Control – Iraq





**LIFTING ACCESSORIES OF VISUAL AND THOROUGH EXAMINATION**

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

<b>Client:</b>	Daqing Drilling Company	<b>Certificate no:</b>	QC-B-03-25-0156-03/01
<b>Location:</b>	RIG DQ-011	<b>Job Order No:</b>	QC-B-03-25-0156
<b>Date of Examination:</b>	01-Apr-2025	<b>Next Inspection Due:</b>	30-Sep-2025
<b>Last Inspection</b>		<b>Last Proof Load Test Date</b>	
NEW		By Manufacture	

IDENTIFICATION NO	DESCRIPTION	QTY	SWL
V9809	<p>Flat Woven Webbing Sling</p> <p>Double Ply Folded Eye at both ends</p> <p>Manufacturer: SAFETY MARINE Date of Manufacture: 07/2022 Material: 100% PES, Colour: RED Length: 8 m Width: 5” Safety Factor: 7:1 Location: store</p> 	01	<p>5000 KG Vertical</p> <p>4000 KG Choker</p> <p>10000 KG Basket</p>

<b>Applicable Reference Standard:</b>	BS EN 1492-1:2000-A1:2008						
* Is this the first examination after installation or assembly at a new site or location?	YES	NO	√	<b>Was the examination carried out?</b>			
				* Within an interval of 6 months?	YES	√	NO
* If the answer to the above question is YES has the equipment been installed correctly?	YES	NO		* Within an interval of 12 months?	YES		NO
				* In accordance with an examination scheme?	YES	√	NO
				* After the occurrence of exceptional circumstances?	YES		NO
Identification Of Any Part Found to Have a Defect Which Is or Could Become a Danger to Persons and a Description of The Defect: <b>None</b>							
Is The Above a Defect Which Is of Immediate Danger to Persons				YES		NO	√
Is The Above a Defect Which Is Not Yet but Could Become a Danger to Persons: (If YES State the Date by When)				NO	√	YES	By:
Particulars Of Any Repair, Renewal or Alteration Required to Remedy the Defect Identified Above: <b>None</b>							
<b>** Visual And Dimension Check was Carried Out.</b>							
Is This Equipment Safe to Operate?				Yes Accept	√	NO Reject	

<b>LEEA &amp; ASNT Level II Inspector Name:</b>		<b>Authenticating This Report:</b>	
Mohammed Abdalla		Ashraf El Said	

**THIS IS TO CERTIFY THAT:** a competent person did attend the above-mentioned owner’s work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation “LOLER”. The result was found Satisfactory at the time of Inspection. And considered Safe for Lifting.








**LIFTING ACCESSORIES OF VISUAL AND THOROUGH EXAMINATION**

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

<b>Client:</b>	Daqing Drilling Company	<b>Certificate no:</b>	QC-B-03-25-0156-03/02
<b>Location:</b>	RIG DQ-011	<b>Job Order No:</b>	QC-B-03-25-0156
<b>Date of Examination:</b>	01-Apr-2025	<b>Next Inspection Due:</b>	30-Sep-2025
<b>Last Inspection</b>		<b>Last Proof Load Test Date</b>	
NEW		By Manufacture	

IDENTIFICATION NO	DESCRIPTION	QTY	SWL
544940036 544940002	<p>Flat Woven Webbing Sling</p> <p>Double Ply Folded Eye at both ends</p> <p>Manufacturer: DELTAPLUS Date of Manufacture: 07/2024 Material: 100% PES, Colour: RED Length: 8 m Width: 5” Safety Factor: 7:1 Location: store</p> 	02	<p>5000 KG Vertical</p> <p>4000 KG Choker</p> <p>10000 KG Basket</p>

<b>Applicable Reference Standard:</b>	BS EN 1492-1:2000-A1:2008									
* Is this the first examination after installation or assembly at a new site or location?	YES		NO	√	<b>Was the examination carried out?</b>					
					* Within an interval of 6 months?		YES	√	NO	
* If the answer to the above question is YES has the equipment been installed correctly?	YES		NO		* Within an interval of 12 months?		YES		NO	
					* In accordance with an examination scheme?		YES	√	NO	
					* After the occurrence of exceptional circumstances?		YES		NO	
Identification Of Any Part Found to Have a Defect Which Is or Could Become a Danger to Persons and a Description of The Defect: <b>None</b>										
Is The Above a Defect Which Is of Immediate Danger to Persons					YES		NO			
Is The Above a Defect Which Is Not Yet but Could Become a Danger to Persons: (If YES State the Date by When)					NO	√	YES		By:	
Particulars Of Any Repair, Renewal or Alteration Required to Remedy the Defect Identified Above: <b>None</b>										
<b>** Visual And Dimension Check was Carried Out.</b>										
Is This Equipment Safe to Operate?					Yes Accept		√	NO Reject		

<b>LEEA &amp; ASNT Level II Inspector Name:</b>		<b>Authenticating This Report:</b>	
Mohammed Abdalla		Ashraf El Said	

**THIS IS TO CERTIFY THAT:** a competent person did attend the above-mentioned owner’s work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation “LOLER”. The result was found Satisfactory at the time of Inspection. And considered Safe for Lifting.




Al Takamul Company for Engineering Services  
Quality Control – Iraq





**LIFTING ACCESSORIES OF VISUAL AND THOROUGH EXAMINATION**

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

<b>Client:</b>	Daqing Drilling Company	<b>Certificate no:</b>	QC-B-03-25-0156-03/03
<b>Location:</b>	RIG DQ-011	<b>Job Order No:</b>	QC-B-03-25-0156
<b>Date of Examination:</b>	01-Apr-2025	<b>Next Inspection Due:</b>	30-Sep-2025
<b>Last Inspection</b>		<b>Last Proof Load Test Date</b>	
NEW		By Manufacture	

IDENTIFICATION NO	DESCRIPTION	QTY	SWL
54585075 54585109 54585025 54585106	<p>Flat Woven Webbing Sling</p> <p>Double Ply Folded Eye at both ends</p> <p>Manufacturer: DELTAPLUS Date of Manufacture: 08/2024 Material: 100% PES, Colour: YELLOW Length: 5 m Width: 3” Safety Factor: 7:1 Location: store</p> 	04	<p>3000 KG Vertical</p> <p>2400 KG Choker</p> <p>6000 KG Basket</p>

<b>Applicable Reference Standard:</b>	BS EN 1492-1:2000-A1:2008						
* Is this the first examination after installation or assembly at a new site or location?	YES	NO	√	<b>Was the examination carried out?</b>			
				* Within an interval of 6 months?	YES	√	NO
* If the answer to the above question is YES has the equipment been installed correctly?	YES	NO		* Within an interval of 12 months?	YES		NO
				* In accordance with an examination scheme?	YES	√	NO
				* After the occurrence of exceptional circumstances?	YES		NO
Identification Of Any Part Found to Have a Defect Which Is or Could Become a Danger to Persons and a Description of The Defect: <b>None</b>							
Is The Above a Defect Which Is of Immediate Danger to Persons				YES		NO	√
Is The Above a Defect Which Is Not Yet but Could Become a Danger to Persons: (If YES State the Date by When)				NO	√	YES	By:
Particulars Of Any Repair, Renewal or Alteration Required to Remedy the Defect Identified Above: <b>None</b>							
<b>** Visual And Dimension Check was Carried Out.</b>							
Is This Equipment Safe to Operate?				Yes Accept	√	NO Reject	

<b>LEEA &amp; ASNT Level II Inspector Name:</b>		<b>Authenticating This Report:</b>	
Mohammed Abdalla		Ashraf El Said	

**THIS IS TO CERTIFY THAT:** a competent person did attend the above-mentioned owner’s work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation “LOLER”. The result was found Satisfactory at the time of Inspection. And considered Safe for Lifting.






Al Takamul Company for Engineering Services  
Quality Control – Iraq





**LIFTING ACCESSORIES OF VISUAL AND THOROUGH EXAMINATION**

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

<b>Client:</b>	Daqing Drilling Company	<b>Certificate no:</b>	QC-B-03-25-0156-03/04
<b>Location:</b>	RIG DQ-011	<b>Job Order No:</b>	QC-B-03-25-0156
<b>Date of Examination:</b>	01-Apr-2025	<b>Next Inspection Due:</b>	30-Sep-2025
<b>Last Inspection</b>		<b>Last Proof Load Test Date</b>	
NEW		By Manufacture	

IDENTIFICATION NO	DESCRIPTION	QTY	SWL
54585107 54585060 54585045 54585046	<p>Flat Woven Webbing Sling</p> <p>Double Ply Folded Eye at both ends</p> <p>Manufacturer: DELTAPLUS Date of Manufacture: 08/2024 Material: 100% PES, Colour: YELLOW Length: 5 m Width: 3” Safety Factor: 7:1 Location: store</p> 	04	<p>3000 KG Vertical</p> <p>2400 KG Choker</p> <p>6000 KG Basket</p>

<b>Applicable Reference Standard:</b>	BS EN 1492-1:2000-A1:2008							
* Is this the first examination after installation or assembly at a new site or location?	YES		NO	√	<b>Was the examination carried out?</b>			
					* Within an interval of 6 months?	YES	√	NO
					* Within an interval of 12 months?	YES		NO
* If the answer to the above question is YES has the equipment been installed correctly?	YES		NO		* In accordance with an examination scheme?	YES	√	NO
					* After the occurrence of exceptional circumstances?	YES		NO
Identification Of Any Part Found to Have a Defect Which Is or Could Become a Danger to Persons and a Description of The Defect: <b>None</b>								
Is The Above a Defect Which Is of Immediate Danger to Persons					YES		NO	√
Is The Above a Defect Which Is Not Yet but Could Become a Danger to Persons: (If YES State the Date by When)					NO	√	YES	By:
Particulars Of Any Repair, Renewal or Alteration Required to Remedy the Defect Identified Above: <b>None</b>								
<b>** Visual And Dimension Check was Carried Out.</b>								
Is This Equipment Safe to Operate?					Yes Accept	√	NO Reject	

<b>LEEA &amp; ASNT Level II Inspector Name:</b>		<b>Authenticating This Report:</b>	
Mohammed Abdalla		Ashraf El Said	

**THIS IS TO CERTIFY THAT:** a competent person did attend the above-mentioned owner’s work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation “LOLER”. The result was found Satisfactory at the time of Inspection. And considered Safe for Lifting.






Al Takamul Company for Engineering Services  
Quality Control – Iraq





**LIFTING ACCESSORIES OF VISUAL AND THOROUGH EXAMINATION**

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

<b>Client:</b>	Daqing Drilling Company	<b>Certificate no:</b>	QC-B-03-25-0156-03/05
<b>Location:</b>	RIG DQ-011	<b>Job Order No:</b>	QC-B-03-25-0156
<b>Date of Examination:</b>	01-Apr-2025	<b>Next Inspection Due:</b>	30-Sep-2025
<b>Last Inspection</b>		<b>Last Proof Load Test Date</b>	
NEW		By Manufacture	

IDENTIFICATION NO	DESCRIPTION	QTY	SWL
54585131 54585166	<p>Flat Woven Webbing Sling</p> <p>Double Ply Folded Eye at both ends</p> <p>Manufacturer: DELTAPLUS Date of Manufacture: 08/2024 Material: 100% PES, Colour: Green Length: 5 m Width: 3” Safety Factor: 7:1 Location: store</p> 	02	<p>2000 KG Vertical</p> <p>1600 KG Choker</p> <p>4000 KG Basket</p>

<b>Applicable Reference Standard:</b>	BS EN 1492-1:2000-A1:2008						
* Is this the first examination after installation or assembly at a new site or location?	YES	NO	√	<b>Was the examination carried out?</b>			
				* Within an interval of 6 months?	YES	√	NO
* If the answer to the above question is YES has the equipment been installed correctly?	YES	NO		* Within an interval of 12 months?	YES		NO
				* In accordance with an examination scheme?	YES	√	NO
				* After the occurrence of exceptional circumstances?	YES		NO
Identification Of Any Part Found to Have a Defect Which Is or Could Become a Danger to Persons and a Description of The Defect: <b>None</b>							
Is The Above a Defect Which Is of Immediate Danger to Persons				YES		NO	√
Is The Above a Defect Which Is Not Yet but Could Become a Danger to Persons: (If YES State the Date by When)				NO	√	YES	By:
Particulars Of Any Repair, Renewal or Alteration Required to Remedy the Defect Identified Above: <b>None</b>							
<b>** Visual And Dimension Check was Carried Out.</b>							
Is This Equipment Safe to Operate?				Yes Accept	√	NO Reject	

<b>LEEA &amp; ASNT Level II Inspector Name:</b>		<b>Authenticating This Report:</b>	
Mohammed Abdalla		Ashraf El Said	

**THIS IS TO CERTIFY THAT:** a competent person did attend the above-mentioned owner’s work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation “LOLER”. The result was found Satisfactory at the time of Inspection. And considered Safe for Lifting.

