



## Visual & Dye Penetrant Examination Report

Client:	Black Gold Gulf	Certificate no:	QC-B-03-25-0148-01
Location:	TRS BGG Yard	Job Order No:	QC-B-03-25-0148
Date of Examination:	26-March-2025	Next Inspection Due:	25-Sep-2025

Serial Number	Description of the examined equipment	Result
231150	Flange 13 5/8" 10K 5X	Accept



### NDT Equipment Details

Standard	ASTM E 709	Viewing Condition:	Colored Media	Method	WET
Red Penetrant Manufacture:		Batch No:	008A009	Due Date	April.2026
Developer Manufacture:		Batch No:	008A103	Due Date	Jun.2026

### NDT procedure

Visual and MPI were carried out for the above description and found free of surface defects at the time of inspection
Identification of any part found to have a defect and a description of the defect: None
Particulars of any repair, renewal, or alteration required to remedy the defect identified above: None
All MPI was performed per OEM's instructions, and OEM did the measurements.

LEEA & ASNT Level II Inspector Name:	Signature:	Authenticating This Report:	Signature:
Mohamed Magdy		Mohammed Abdulla	