



Visual & Magnetic Particles Examination Report



Client:	Daqing Drilling Company	Certificate no:	QC-B-04-25-0167-28
Location:	DQ Rig 037	Job Order No:	QC-B-04-25-0167
Date of Examination:	12-Apr-2025	Next Inspection Due:	11-Oct-2025

Serial Number	Description of the examined equipment	Result
MS037	Mud Saver Welding Area	Accept



NDT Equipment Details					
Standard	ASTM E 709	Viewing Condition:	Colored Media	Method	WET
Yoke	Permanent	Serial No:	PY-11	Due Date	11. May.2025
White Contrast	WCP-2	Batch No:	008A009	Due Date	April.2026
Black Ink	7HF	Batch No:	008A103	Due Date	Jun.2026

NDT procedure
Visual and MPI were carried out for the above description and found free of surface defects at the time of inspection
Identification of any part found to have a defect and a description of the defect: None
Particulars of any repair, renewal, or alteration required to remedy the defect identified above: None
All MPI Performed as Per Instructions of OEM:

LEEA & ASNT Level II Inspector Name:	Signature:	Authenticating This Report:	Signature:
Abdullah Mofeed		Mohamed Abdulla	





Visual & Magnetic Particles Examination Report

Client:	Daqing Drilling Company	Certificate no:	QC-B-04-25-0167-29
Location:	DQ Rig 037	Job Order No:	QC-B-04-25-0167
Date of Examination:	12-Apr-2025	Next Inspection Due:	11-Oct-2025

Serial Number	Description of the examined equipment	Result
539321 539322	Bushing Lifting Hook	Accept



NDT Equipment Details

Standard	ASTM E 709	Viewing Condition:	Colored Media	Method	WET
Yoke	Permanent	Serial No:	PY-11	Due Date	11. May.2025
White Contrast	WCP-2	Batch No:	008A009	Due Date	April.2026
Black Ink	7HF	Batch No:	008A103	Due Date	Jun.2026



NDT procedure

Visual and MPI were carried out for the above description and found free of surface defects at the time of inspection

Identification of any part found to have a defect and a description of the defect: None

Particulars of any repair, renewal, or alteration required to remedy the defect identified above: None

All MPI Performed as Per Instructions of OEM:

LEEA & ASNT Level II Inspector Name:	Signature:	Authenticating This Report:	Signature:
Abdullah Mofeed		Mohamed Abdulla	





Visual & Magnetic Particles Examination Report

Client:	Daqing Drilling Company	Certificate no:	QC-B-04-25-0167-30
Location:	DQ Rig 037	Job Order No:	QC-B-04-25-0167
Date of Examination:	12-Apr-2025	Next Inspection Due:	11-Oct-2025

Serial Number	Description of the examined equipment	Result
37-33	Drilling Line Stabilizer	Accept




NDT Equipment Details

Standard	ASTM E 709	Viewing Condition:	Colored Media	Method	WET
Yoke	Permanent	Serial No:	PY-11	Due Date	11. May.2025
White Contrast	WCP-2	Batch No:	008A009	Due Date	April.2026
Black Ink	7HF	Batch No:	008A103	Due Date	Jun.2026

NDT procedure

Visual and MPI were carried out for the above description and found free of surface defects at the time of inspection
Identification of any part found to have a defect and a description of the defect: None
Particulars of any repair, renewal, or alteration required to remedy the defect identified above: None
All MPI Performed as Per Instructions of OEM:

LEEA & ASNT Level II Inspector Name:	Signature:	Authenticating This Report:	Signature:
Abdullah Mofeed		Mohamed Abdulla	