

## Equipment Inspection Technical Report



<b>Client Name:</b>	Ras Al-Khaimah Company		<b>Job Number:</b>	QC-B-02-25-0051
<b>Date of Examination:</b>	30. May.2025	<b>Location:</b>	QC-YARD	<b>Certificate No:</b> QC-B-02-25-0051/02

### Equipment under Inspection: Vacuum Waste Truck

<b>Truck Manufacture</b>	<b>Reg.No.</b>	<b>Chassis number</b>	<b>Tank Volume</b>
MERCEDES	21 G 16390	WDB9302041L581713	22,500 Liters

Inspection Method: Visual and functional Inspection

No.	Section Under Inspection	Status
<b>1</b>	<b>Hydraulic system</b>	OK
1.1	Hydraulic Oil Level	OK
1.2	Condition of Oil	OK
1.3	System and hoses	OK
1.4	Lubrication	OK
<b>2</b>	<b>Pump &amp; Operation system</b>	OK
2.1	Hoses and fittings are of the correct pressure rating and in good condition	OK
2.2	Tank /vessel	OK
2.3	Pressure pump	OK
2.4	Operation controls for pump or transfer system ,gauge and valves	OK
2.5	All hoses are joined by threaded female couplings of the correct pressure rating No quick Connect fittings are used.	OK
2.6	Diesel engine working Property	OK
2.7	Water gun	OK
<b>3</b>	<b>Safety devices</b>	OK
3.1	Warning alarms	OK
3.2	First aid box	OK
3.3	Fire extinguisher	OK
<b>4</b>	<b>General</b>	OK
4.1	Tires	OK
4.2	Drive gears	OK
4.3	Hydraulic Cylinder	OK

<b>Name of Inspector:</b>	<b>Name of person authenticating this report:</b>	<b>Signature &amp; Stamp:</b>	
Abdulla Al-Rahaman	Ashraf El Said		
<b>Date of Next Through Examination:</b>	29.May.2026		


## Equipment Inspection Technical Report

No.	Section Under Inspection	Status
4.4	Electrics	OK
4.5	Engine compartment	OK
4.6	Exhaust system	OK
4.7	Steering	OK
4.8	Gauge in cabin	OK
4.9	Safety belt	OK
4.10	Front and rear lights	OK
4.11	Windscreen	OK
4.12	Windshield wipers	OK
4.13	Driver right mirror	OK



### Result:-

- 1-The vehicle has been inspected, tested and found to meet the manufacture's specifications
- 2-Inspection has been done in According with BS 474-1:2022
- 3-Inspection has been done In According with OHS Regulation
- 4-This inspection report is valid for one year.
- 5-The inspected equipment is in specification at the time it had been inspected
- 6-This inspection was carried out in compliance with the OHS Regulations
- 7-Inspection has been done for the above-mentioned items
- 8-This report is valid only with signature and stamp

Name of Inspector:	Name of person authenticating this report:	Signature & Stamp	QR Code
Abdulla Al-Rahaman	Ashraf El Said		
Date of Next Through Examination:	29.May.2026		