





LIFTING ACCESSORIES OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	DAQING DRILLING COMPANY	Certificate no:	QC-B-05-25-0263-10-01
Location:	DQ RIG 022	Job Order No:	QC-B-05-25-0263
Date of Examination:	11-MaY-2025	Next Inspection Due:	10-NOV-2025
Last Inspection		Last Proof Load Test Date	
08- JAN - 2025		By Manufacture	

IDENTIFICATION NO	DESCRIPTION	QTY	SWL
B4082 B4081 A7493 A3516 A6372	Single Leg Wire Rope Sling DIM : 6 m (L) X 44 mm (DIA) IWRC MECHANICALLY SPLICED WITH ALUMINUM FERRULES. SOFT EYE X SOFT EYE FOS: 5 : 1 Location: STORE	05	24.8 TON
Applicable Reference Standard:	BS EN 13414-1		
* Is this the first examination after installation or assembly at a new site or location?	YES	NO	√
	Was the examination carried out?		
* If the answer to the above question is YES has the equipment been installed correctly?	YES	NO	√
	* Within an interval of 6 months?		
			YES
			NO
			√
			YES
			NO
			√
Identification Of Any Part Found To Have A Defect Which Is Or Could Become A Danger To Persons And A Description Of The Defect: None			
Is The Above A Defect Which Is Of Immediate Danger To Persons			YES
			NO
Is The Above A Defect Which Is Not Yet But Could Become A Danger To Persons: (If YES State The Date By When)			NO
			√
			YES
			By:
Particulars Of Any Repair, Renewal, Or Alteration Required To Remedy The Defect Identified Above: None			
** Visual And Dimension Check was Carried Out.			
Is This Equipment Safe To Operate?		Yes Accept	NO Reject
		√	

LEE & ASNT Level II Inspector Name:	SIGNATURE:	Authenticating This Report:	SIGNATURE:
Khaled Mahmoud		Mohammed Abdullah	

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner’s work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation “LOLER”. The result was found Satisfactory at the time of Inspection and considered Safe for Lifting





LIFTING ACCESSORIES OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	DAQING DRILLING COMPANY	Certificate no:	QC-B-05-25-0263-10-02
Location:	DQ RIG 022	Job Order No:	QC-B-05-25-0263
Date of Examination:	11-MaY-2025	Next Inspection Due:	10-NOV-2025
Last Inspection		Last Proof Load Test Date	
08- JAN - 2025		By Manufacture	

IDENTIFICATION NO	DESCRIPTION	QTY	SWL
DQ22-10 DQ22-11 DQ22-12	Single Leg Wire Rope Sling DIM : 7.20 m (L) X 26 mm (DIA) IWRC MECHANICALLY SPLICED WITH ALUMINUM FERRULES. SOFT EYE X SOFT EYE FOS: 5 : 1 Location: STORE	03	6.12 TON
Applicable Reference Standard:	BS EN 13414-1		
* Is this the first examination after installation or assembly at a new site or location?	Was the examination carried out?		
	YES	NO	√
* If the answer to the above question is YES has the equipment been installed correctly?	* Within an interval of 6 months?		YES
	YES	NO	√
	* Within an interval of 12 months?		YES
	YES	NO	√
	* By an examination scheme?		YES
	YES	NO	√
	* After the occurrence of exceptional circumstances?		YES
	YES	NO	√
Identification Of Any Part Found To Have A Defect Which Is Or Could Become A Danger To Persons And A Description Of The Defect: None			
Is The Above A Defect Which Is Of Immediate Danger To Persons			YES
Is The Above A Defect Which Is Not Yet But Could Become A Danger To Persons: (If YES State The Date By When)			NO
Particulars Of Any Repair, Renewal, Or Alteration Required To Remedy The Defect Identified Above: None			
** Visual And Dimension Check was Carried Out.			
Is This Equipment Safe To Operate?		Yes Accept	NO Reject

LEE & ASNT Level II Inspector Name:	SIGNATURE:	Authenticating This Report:	SIGNATURE:
Khaled Mahmoud		Mohammed Abdullah	

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner’s work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation “LOLER”. The result was found Satisfactory at the time of Inspection and considered Safe for Lifting





LIFTING ACCESSORIES OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	DAQING DRILLING COMPANY	Certificate no:	QC-B-05-25-0263-10-03
Location:	DQ RIG 022	Job Order No:	QC-B-05-25-0263
Date of Examination:	11-MaY-2025	Next Inspection Due:	10-NOV-2025
Last Inspection		Last Proof Load Test Date	
08- JAN - 2025		By Manufacture	

IDENTIFICATION NO	DESCRIPTION	QTY	SWL			
D9208	<p>Single Leg Wire Rope Sling</p> <p>DIM : 6 m (L) X 22 mm (DIA) IWRM MECHANICALLY SPLICED WITH ALUMINUM FERRULES. HARD EYE X SOFT EYE FOS: 5 : 1 Location: STORE</p>	01	5.65 TON			
Applicable Reference Standard:	BS EN 13414-1					
* Is this the first examination after installation or assembly at a new site or location?	YES	NO	√			
	Was the examination carried out?					
* If the answer to the above question is YES has the equipment been installed correctly?	YES	NO	√			
	* Within an interval of 6 months?					
			YES	NO	√	
			* Within an interval of 12 months?			
			YES	NO	√	
			* By an examination scheme?			
			YES	NO	√	
			* After the occurrence of exceptional circumstances?			
			YES	NO	√	
Identification Of Any Part Found To Have A Defect Which Is Or Could Become A Danger To Persons And A Description Of The Defect: None						
Is The Above A Defect Which Is Of Immediate Danger To Persons				YES	NO	√
Is The Above A Defect Which Is Not Yet But Could Become A Danger To Persons: (If YES State The Date By When)				NO	√	YES
Particulars Of Any Repair, Renewal, Or Alteration Required To Remedy The Defect Identified Above: None						
** Visual And Dimension Check was Carried Out.						
Is This Equipment Safe To Operate?		Yes Accept	√	NO Reject		

LEE & ASNT Level II Inspector Name:	SIGNATURE:	Authenticating This Report:	SIGNATURE:
Khaled Mahmoud		Mohammed Abdullah	

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting



LIFTING ACCESSORIES OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	DAQING DRILLING COMPANY	Certificate no:	QC-B-05-25-0263-10-04
Location:	DQ RIG 022	Job Order No:	QC-B-05-25-0263
Date of Examination:	11-MaY-2025	Next Inspection Due:	10-NOV-2025
Last Inspection		Last Proof Load Test Date	
08- JAN - 2025		By Manufacture	

IDENTIFICATION NO	DESCRIPTION	QTY	SWL			
A5496	<p>Single Leg Wire Rope Sling</p> <p>DIM : 3 m (L) X 26 mm (DIA) IWRC MECHANICALLY SPLICED WITH ALUMINUM FERRULES. HARD EYE X HARD EYE FOS: 5 : 1 Location: STORE</p>	01	7.6 TON			
Applicable Reference Standard:	BS EN 13414-1					
* Is this the first examination after installation or assembly at a new site or location?	YES	NO	√			
	Was the examination carried out?					
* If the answer to the above question is YES has the equipment been installed correctly?	YES	NO	√			
	* Within an interval of 6 months?					
			YES	NO	√	
			* Within an interval of 12 months?			
			YES	NO	√	
			* By an examination scheme?			
			YES	NO	√	
			* After the occurrence of exceptional circumstances?			
			YES	NO	√	
Identification Of Any Part Found To Have A Defect Which Is Or Could Become A Danger To Persons And A Description Of The Defect: None						
Is The Above A Defect Which Is Of Immediate Danger To Persons				YES	NO	√
Is The Above A Defect Which Is Not Yet But Could Become A Danger To Persons: (If YES State The Date By When)				NO	√	YES
Particulars Of Any Repair, Renewal, Or Alteration Required To Remedy The Defect Identified Above: None						
** Visual And Dimension Check was Carried Out.						
Is This Equipment Safe To Operate?		Yes Accept	√	NO Reject		

LEE & ASNT Level II Inspector Name:	SIGNATURE:	Authenticating This Report:	SIGNATURE:
Khaled Mahmoud		Mohammed Abdullah	

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner’s work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation “LOLER”. The result was found Satisfactory at the time of Inspection and considered Safe for Lifting





Al Takamul Company for Engineering Services
Quality Control – Iraq



LIFTING ACCESSORIES OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	DAQING DRILLING COMPANY	Certificate no:	QC-B-05-25-0263-10-05
Location:	DQ RIG 022	Job Order No:	QC-B-05-25-0263
Date of Examination:	11-MaY-2025	Next Inspection Due:	10-NOV-2025
Last Inspection		Last Proof Load Test Date	
08- JAN - 2025		By Manufacture	

IDENTIFICATION NO	DESCRIPTION	QTY	SWL
A7606 A6699 A6704 A6701	Single Leg Wire Rope Sling DIM : 1 m (L) X 13 mm (DIA) IWRC MECHANICALLY SPLICED WITH ALUMINUM FERRULES. HARD EYE X HARD EYE FOS: 5 : 1 Location: STORE	04	2.1 TON
Applicable Reference Standard:	BS EN 13414-1		
* Is this the first examination after installation or assembly at a new site or location?	YES	NO	√
	Was the examination carried out?		
* If the answer to the above question is YES has the equipment been installed correctly?	YES	NO	√
	* Within an interval of 6 months?		
			YES
			NO
			√
			NO
			√
			NO
			√
Identification Of Any Part Found To Have A Defect Which Is Or Could Become A Danger To Persons And A Description Of The Defect: None			
Is The Above A Defect Which Is Of Immediate Danger To Persons			YES
			NO
			√
Is The Above A Defect Which Is Not Yet But Could Become A Danger To Persons: (If YES State The Date By When)			NO
			√
			YES
			By:
Particulars Of Any Repair, Renewal, Or Alteration Required To Remedy The Defect Identified Above: None			
** Visual And Dimension Check was Carried Out.			
Is This Equipment Safe To Operate?		Yes Accept	NO Reject
		√	

LEE A & ASNT Level II Inspector Name:	SIGNATURE:	Authenticating This Report:	SIGNATURE:
Khaled Mahmoud		Mohammed Abdullah	

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner’s work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation “LOLER”. The result was found Satisfactory at the time of Inspection and considered Safe for Lifting





Al Takamul Company for Engineering Services
Quality Control – Iraq



LIFTING ACCESSORIES OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	DAQING DRILLING COMPANY	Certificate no:	QC-B-05-25-0263-10-06
Location:	DQ RIG 022	Job Order No:	QC-B-05-25-0263
Date of Examination:	11-MaY-2025	Next Inspection Due:	10-NOV-2025
Last Inspection		Last Proof Load Test Date	
08- JAN - 2025		By Manufacture	

IDENTIFICATION NO	DESCRIPTION	QTY	SWL
B4392 B4401 B440 B4385 B4388	Single Leg Wire Rope Sling DIM : 1 m (L) X 16 mm (DIA) IWRC MECHANICALLY SPLICED WITH ALUMINUM FERRULES. SOFT EYE X SOFT EYE FOS: 5 : 1 Location: STORE	05	3.3 TON
Applicable Reference Standard:	BS EN 13414-1		
* Is this the first examination after installation or assembly at a new site or location?	YES	NO	√
	Was the examination carried out?		
* If the answer to the above question is YES has the equipment been installed correctly?	YES	NO	√
	* Within an interval of 6 months?		YES
* Within an interval of 12 months?		YES	√
* By an examination scheme?		YES	√
* After the occurrence of exceptional circumstances?		YES	√
Identification Of Any Part Found To Have A Defect Which Is Or Could Become A Danger To Persons And A Description Of The Defect: None			
Is The Above A Defect Which Is Of Immediate Danger To Persons		YES	NO
Is The Above A Defect Which Is Not Yet But Could Become A Danger To Persons: (If YES State The Date By When)		NO	YES
Particulars Of Any Repair, Renewal, Or Alteration Required To Remedy The Defect Identified Above: None			
** Visual And Dimension Check was Carried Out.			
Is This Equipment Safe To Operate?		Yes Accept	NO Reject

LEE & ASNT Level II Inspector Name:	SIGNATURE:	Authenticating This Report:	SIGNATURE:
Khaled Mahmoud		Mohammed Abdullah	

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner’s work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation “LOLER”. The result was found Satisfactory at the time of Inspection and considered Safe for Lifting





Al Takamul Company for Engineering Services
Quality Control – Iraq



LIFTING ACCESSORIES OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	DAQING DRILLING COMPANY	Certificate no:	QC-B-05-25-0263-10-07
Location:	DQ RIG 022	Job Order No:	QC-B-05-25-0263
Date of Examination:	11-May-2025	Next Inspection Due:	10-NOV-2025
Last Inspection		Last Proof Load Test Date	
08- JAN - 2025		By Manufacture	

IDENTIFICATION NO	DESCRIPTION	QTY	SWL
B4390 B4391 B4402 B4397	Single Leg Wire Rope Sling DIM : 1 m (L) X 16 mm (DIA) IWRC MECHANICALLY SPLICED WITH ALUMINUM FERRULES. SOFT EYE X SOFT EYE FOS: 5 : 1 Location: STORE	04	3.3 TON
Applicable Reference Standard:	BS EN 13414-1		
* Is this the first examination after installation or assembly at a new site or location?	Was the examination carried out?		
	YES	NO	√
* If the answer to the above question is YES has the equipment been installed correctly?	* Within an interval of 6 months?		
	YES	NO	√
	* Within an interval of 12 months?		
	YES	NO	√
	* By an examination scheme?		
	YES	NO	√
	* After the occurrence of exceptional circumstances?		
	YES	NO	√
Identification Of Any Part Found To Have A Defect Which Is Or Could Become A Danger To Persons And A Description Of The Defect: None			
Is The Above A Defect Which Is Of Immediate Danger To Persons			YES NO √
Is The Above A Defect Which Is Not Yet But Could Become A Danger To Persons: (If YES State The Date By When)			NO √ YES By:
Particulars Of Any Repair, Renewal, Or Alteration Required To Remedy The Defect Identified Above: None			
** Visual And Dimension Check was Carried Out.			
Is This Equipment Safe To Operate?		Yes Accept	NO Reject
		√	

LEE & ASNT Level II Inspector Name:	SIGNATURE:	Authenticating This Report:	SIGNATURE:
Khaled Mahmoud		Mohammed Abdullah	

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner’s work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation “LOLER”. The result was found Satisfactory at the time of Inspection and considered Safe for Lifting





LIFTING ACCESSORIES OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	DAQING DRILLING COMPANY	Certificate no:	QC-B-05-25-0263-10-08
Location:	DQ RIG 022	Job Order No:	QC-B-05-25-0263
Date of Examination:	11-MaY-2025	Next Inspection Due:	10-NOV-2025
Last Inspection		Last Proof Load Test Date	
08- JAN - 2025		By Manufacture	

IDENTIFICATION NO	DESCRIPTION	QTY	SWL
M3571 M3564 M3572 M3579 M3582 M3575	Single Leg Wire Rope Sling DIM : 1.5 m (L) X 13 mm (DIA) IWRC MECHANICALLY SPLICED WITH ALUMINUM FERRULES. SOFT EYE X SOFT EYE FOS: 5 : 1 Location: STORE	06	2.1 TON
Applicable Reference Standard:	BS EN 13414-1		
* Is this the first examination after installation or assembly at a new site or location?	YES	NO	√
	Was the examination carried out?		
* If the answer to the above question is YES has the equipment been installed correctly?	YES	NO	√
	* Within an interval of 6 months?		YES
* Within an interval of 12 months?		YES	√
* By an examination scheme?		YES	√
* After the occurrence of exceptional circumstances?		YES	√
Identification Of Any Part Found To Have A Defect Which Is Or Could Become A Danger To Persons And A Description Of The Defect: None			
Is The Above A Defect Which Is Of Immediate Danger To Persons		YES	NO
Is The Above A Defect Which Is Not Yet But Could Become A Danger To Persons: (If YES State The Date By When)		NO	YES
Particulars Of Any Repair, Renewal, Or Alteration Required To Remedy The Defect Identified Above: None			
** Visual And Dimension Check was Carried Out.			
Is This Equipment Safe To Operate?		Yes Accept	NO Reject

LEE & ASNT Level II Inspector Name:	SIGNATURE:	Authenticating This Report:	SIGNATURE:
Khaled Mahmoud		Mohammed Abdullah	

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner’s work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation “LOLER”. The result was found Satisfactory at the time of Inspection and considered Safe for Lifting





Al Takamul Company for Engineering Services
Quality Control – Iraq



LIFTING ACCESSORIES OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	DAQING DRILLING COMPANY	Certificate no:	QC-B-05-25-0263-10-09
Location:	DQ RIG 022	Job Order No:	QC-B-05-25-0263
Date of Examination:	11-MaY-2025	Next Inspection Due:	10-NOV-2025
Last Inspection		Last Proof Load Test Date	
08- JAN - 2025		By Manufacture	

IDENTIFICATION NO	DESCRIPTION	QTY	SWL
A6649 A6639 A6642 A6644 A6643 A6645 A6647	Single Leg Wire Rope Sling DIM : 1 m (L) X 19 mm (DIA) IWRC MECHANICALLY SPLICED WITH ALUMINUM FERRULES. HARD EYE X HARD EYE FOS: 5 : 1 Location: STORE	07	2.1 TON
Applicable Reference Standard:	BS EN 13414-1		
* Is this the first examination after installation or assembly at a new site or location?	Was the examination carried out?		
	YES	NO	√
* If the answer to the above question is YES has the equipment been installed correctly?	* Within an interval of 6 months?		
	YES	NO	√
	* Within an interval of 12 months?		
	YES	NO	√
	* By an examination scheme?		
	YES	NO	√
	* After the occurrence of exceptional circumstances?		
	YES	NO	√
Identification Of Any Part Found To Have A Defect Which Is Or Could Become A Danger To Persons And A Description Of The Defect: None			
Is The Above A Defect Which Is Of Immediate Danger To Persons			YES NO √
Is The Above A Defect Which Is Not Yet But Could Become A Danger To Persons: (If YES State The Date By When)			NO √ YES By:
Particulars Of Any Repair, Renewal, Or Alteration Required To Remedy The Defect Identified Above: None			
** Visual And Dimension Check was Carried Out.			
Is This Equipment Safe To Operate?		Yes Accept	NO Reject
		√	

LEE & ASNT Level II Inspector Name:	SIGNATURE:	Authenticating This Report:	SIGNATURE:
Khaled Mahmoud		Mohammed Abdullah	

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner’s work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation “LOLER”. The result was found Satisfactory at the time of Inspection and considered Safe for Lifting





LIFTING ACCESSORIES OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	DAQING DRILLING COMPANY	Certificate no:	QC-B-05-25-0263-10-10
Location:	DQ RIG 022	Job Order No:	QC-B-05-25-0263
Date of Examination:	11-MaY-2025	Next Inspection Due:	10-NOV-2025
Last Inspection		Last Proof Load Test Date	
08- JAN - 2025		By Manufacture	

IDENTIFICATION NO	DESCRIPTION	QTY	SWL
A6556 B2433 B2432	Single Leg Wire Rope Sling DIM : 1.5 m (L) X 19 mm (DIA) IWRC MECHANICALLY SPLICED WITH ALUMINUM FERRULES. HARD EYE X HARD EYE FOS: 5 : 1 Location: STORE	07	4.6 TON
Applicable Reference Standard:	BS EN 13414-1		
* Is this the first examination after installation or assembly at a new site or location?	YES	NO	√
	Was the examination carried out?		
* If the answer to the above question is YES has the equipment been installed correctly?	YES	NO	√
	* Within an interval of 6 months?		YES
* Within an interval of 12 months?		YES	√
* By an examination scheme?		YES	√
* After the occurrence of exceptional circumstances?		YES	√
Identification Of Any Part Found To Have A Defect Which Is Or Could Become A Danger To Persons And A Description Of The Defect: None			
Is The Above A Defect Which Is Of Immediate Danger To Persons		YES	NO
Is The Above A Defect Which Is Not Yet But Could Become A Danger To Persons: (If YES State The Date By When)		NO	YES
Particulars Of Any Repair, Renewal, Or Alteration Required To Remedy The Defect Identified Above: None			
** Visual And Dimension Check was Carried Out.			
Is This Equipment Safe To Operate?		Yes Accept	NO Reject

LEE & ASNT Level II Inspector Name:	SIGNATURE:	Authenticating This Report:	SIGNATURE:
Khaled Mahmoud		Mohammed Abdullah	

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner’s work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation “LOLER”. The result was found Satisfactory at the time of Inspection and considered Safe for Lifting





LIFTING ACCESSORIES OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	DAQING DRILLING COMPANY	Certificate no:	QC-B-05-25-0263-10-11
Location:	DQ RIG 022	Job Order No:	QC-B-05-25-0263
Date of Examination:	11-MaY-2025	Next Inspection Due:	10-NOV-2025
Last Inspection		Last Proof Load Test Date	
08- JAN - 2025		By Manufacture	

IDENTIFICATION NO	DESCRIPTION	QTY	SWL			
D0583	<p>Single Leg Wire Rope Sling</p> <p>DIM : 1 m (L) X 13 mm (DIA) IWRC MECHANICALLY SPLICED WITH ALUMINUM FERRULES. HARD EYE X HARD EYE FOS: 5 : 1 Location: STORE</p>	01	2 TON			
Applicable Reference Standard:	BS EN 13414-1					
* Is this the first examination after installation or assembly at a new site or location?	YES	NO	√			
	Was the examination carried out?					
* If the answer to the above question is YES has the equipment been installed correctly?	YES	NO	√			
	* Within an interval of 6 months?					
			YES	NO	√	
			* Within an interval of 12 months?			
			YES	NO	√	
			* By an examination scheme?			
			YES	NO	√	
			* After the occurrence of exceptional circumstances?			
			YES	NO	√	
Identification Of Any Part Found To Have A Defect Which Is Or Could Become A Danger To Persons And A Description Of The Defect: None						
Is The Above A Defect Which Is Of Immediate Danger To Persons				YES	NO	√
Is The Above A Defect Which Is Not Yet But Could Become A Danger To Persons: (If YES State The Date By When)				NO	√	YES
Particulars Of Any Repair, Renewal, Or Alteration Required To Remedy The Defect Identified Above: None						
** Visual And Dimension Check was Carried Out.						
Is This Equipment Safe To Operate?		Yes Accept	√	NO Reject		

LEE A & ASNT Level II Inspector Name:	SIGNATURE:	Authenticating This Report:	SIGNATURE:
Khaled Mahmoud		Mohammed Abdullah	

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner’s work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation “LOLER”. The result was found Satisfactory at the time of Inspection and considered Safe for Lifting







LIFTING ACCESSORIES OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	DAQING DRILLING COMPANY	Certificate no:	QC-B-05-25-0263-10-12
Location:	DQ RIG 022	Job Order No:	QC-B-05-25-0263
Date of Examination:	11-MaY-2025	Next Inspection Due:	10-NOV-2025
Last Inspection		Last Proof Load Test Date	
08- JAN - 2025		By Manufacture	

IDENTIFICATION NO	DESCRIPTION	QTY	SWL
A6670 A667 A7544 A7542	Single Leg Wire Rope Sling DIM : 2 m (L) X 19 mm (DIA) IWRC MECHANICALLY SPLICED WITH ALUMINUM FERRULES. HARD EYE X HARD EYE FOS: 5 : 1 Location: STORE	04	4.6 TON
Applicable Reference Standard:	BS EN 13414-1		
* Is this the first examination after installation or assembly at a new site or location?	YES	NO	√
	Was the examination carried out?		
* If the answer to the above question is YES has the equipment been installed correctly?	YES	NO	√
	* Within an interval of 6 months?		
			YES
			NO
			√
			NO
			√
			NO
			√
Identification Of Any Part Found To Have A Defect Which Is Or Could Become A Danger To Persons And A Description Of The Defect: None			
Is The Above A Defect Which Is Of Immediate Danger To Persons			YES
			NO
Is The Above A Defect Which Is Not Yet But Could Become A Danger To Persons: (If YES State The Date By When)			NO
			√
			YES
			By:
Particulars Of Any Repair, Renewal, Or Alteration Required To Remedy The Defect Identified Above: None			
** Visual And Dimension Check was Carried Out.			
Is This Equipment Safe To Operate?		Yes Accept	NO Reject
		√	

LEE & ASNT Level II Inspector Name:	SIGNATURE:	Authenticating This Report:	SIGNATURE:
Khaled Mahmoud		Mohammed Abdullah	

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting




LIFTING ACCESSORIES OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	DAQING DRILLING COMPANY	Certificate no:	QC-B-05-25-0263-10-13
Location:	DQ RIG 022	Job Order No:	QC-B-05-25-0263
Date of Examination:	11-May-2025	Next Inspection Due:	10-NOV-2025
Last Inspection		Last Proof Load Test Date	
08- JAN - 2025		By Manufacture	

IDENTIFICATION NO	DESCRIPTION	QTY	SWL																				
T4865	<p>Single Leg Wire Rope Sling</p> <p>DIM : 4 m (L) X 16 mm (DIA) IWRC MECHANICALLY SPLICED WITH ALUMINUM FERRULES. HARD EYE X HARD EYE FOS: 5 : 1 Location: STORE</p>	01	3.3 TON																				
Applicable Reference Standard:	BS EN 13414-1																						
* Is this the first examination after installation or assembly at a new site or location?	YES		NO																				
	YES		NO																				
* If the answer to the above question is YES has the equipment been installed correctly?	YES		NO																				
	YES		NO																				
<table border="1"> <tr> <th colspan="4">Was the examination carried out?</th> </tr> <tr> <td>* Within an interval of 6 months?</td> <td>YES</td> <td>NO</td> <td></td> </tr> <tr> <td>* Within an interval of 12 months?</td> <td>YES</td> <td>NO</td> <td></td> </tr> <tr> <td>* By an examination scheme?</td> <td>YES</td> <td>NO</td> <td></td> </tr> <tr> <td>* After the occurrence of exceptional circumstances?</td> <td>YES</td> <td>NO</td> <td></td> </tr> </table>				Was the examination carried out?				* Within an interval of 6 months?	YES	NO		* Within an interval of 12 months?	YES	NO		* By an examination scheme?	YES	NO		* After the occurrence of exceptional circumstances?	YES	NO	
Was the examination carried out?																							
* Within an interval of 6 months?	YES	NO																					
* Within an interval of 12 months?	YES	NO																					
* By an examination scheme?	YES	NO																					
* After the occurrence of exceptional circumstances?	YES	NO																					
Identification Of Any Part Found To Have A Defect Which Is Or Could Become A Danger To Persons And A Description Of The Defect: None																							
Is The Above A Defect Which Is Of Immediate Danger To Persons			YES																				
Is The Above A Defect Which Is Not Yet But Could Become A Danger To Persons: (If YES State The Date By When)			NO																				
Particulars Of Any Repair, Renewal, Or Alteration Required To Remedy The Defect Identified Above: None																							
** Visual And Dimension Check was Carried Out.																							
Is This Equipment Safe To Operate?		Yes Accept	NO Reject																				

LEE & ASNT Level II Inspector Name:	SIGNATURE:	Authenticating This Report:	SIGNATURE:
Khaled Mahmoud		Mohammed Abdullah	

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner’s work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation “LOLER”. The result was found Satisfactory at the time of Inspection and considered Safe for Lifting





Al Takamul Company for Engineering Services
Quality Control – Iraq



LIFTING ACCESSORIES OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	DAQING DRILLING COMPANY	Certificate no:	QC-B-05-25-0263-10-14
Location:	DQ RIG 022	Job Order No:	QC-B-05-25-0263
Date of Examination:	11-MaY-2025	Next Inspection Due:	10-NOV-2025
Last Inspection		Last Proof Load Test Date	
08- JAN - 2025		By Manufacture	

IDENTIFICATION NO	DESCRIPTION	QTY	SWL			
A5497	Single Leg Wire Rope Sling DIM : 3 m (L) X 26 mm (DIA) IWRC MECHANICALLY SPLICED WITH ALUMINUM FERRULES. HARD EYE X HARD EYE FOS: 5 : 1 Location: STORE	01	7.8 TON			
Applicable Reference Standard:	BS EN 13414-1					
* Is this the first examination after installation or assembly at a new site or location?	YES	NO	√			
	Was the examination carried out?					
* If the answer to the above question is YES has the equipment been installed correctly?	YES	NO	√			
	* Within an interval of 6 months?					
			YES	NO	√	
			* Within an interval of 12 months?			
			YES	NO	√	
			* By an examination scheme?			
			YES	NO	√	
			* After the occurrence of exceptional circumstances?			
			YES	NO	√	
Identification Of Any Part Found To Have A Defect Which Is Or Could Become A Danger To Persons And A Description Of The Defect: None						
Is The Above A Defect Which Is Of Immediate Danger To Persons				YES	NO	√
Is The Above A Defect Which Is Not Yet But Could Become A Danger To Persons: (If YES State The Date By When)				NO	YES	√
Particulars Of Any Repair, Renewal, Or Alteration Required To Remedy The Defect Identified Above: None						
** Visual And Dimension Check was Carried Out.						
Is This Equipment Safe To Operate?		Yes Accept	√	NO Reject		

LEE & ASNT Level II Inspector Name:	SIGNATURE:	Authenticating This Report:	SIGNATURE:
Khaled Mahmoud		Mohammed Abdullah	

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting







LIFTING ACCESSORIES OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	DAQING DRILLING COMPANY	Certificate no:	QC-B-05-25-0263-10-15
Location:	DQ RIG 022	Job Order No:	QC-B-05-25-0263
Date of Examination:	11-MaY-2025	Next Inspection Due:	10-NOV-2025
Last Inspection		Last Proof Load Test Date	
08- JAN - 2025		By Manufacture	

IDENTIFICATION NO	DESCRIPTION	QTY	SWL
A7037 A7036	Single Leg Wire Rope Sling DIM : 4 m (L) X 28 mm (DIA) IWRC MECHANICALLY SPLICED WITH ALUMINUM FERRULES. HARD EYE X HARD EYE FOS: 5 : 1 Location: STORE	02	10 TON
Applicable Reference Standard:	BS EN 13414-1		
* Is this the first examination after installation or assembly at a new site or location?	YES	NO	√
	Was the examination carried out?		
* If the answer to the above question is YES has the equipment been installed correctly?	YES	NO	√
	* Within an interval of 6 months?		YES
* Within an interval of 12 months?		YES	√
* By an examination scheme?		YES	√
* After the occurrence of exceptional circumstances?		YES	√
Identification Of Any Part Found To Have A Defect Which Is Or Could Become A Danger To Persons And A Description Of The Defect: None			
Is The Above A Defect Which Is Of Immediate Danger To Persons		YES	NO
Is The Above A Defect Which Is Not Yet But Could Become A Danger To Persons: (If YES State The Date By When)		NO	YES
Particulars Of Any Repair, Renewal, Or Alteration Required To Remedy The Defect Identified Above: None			
** Visual And Dimension Check was Carried Out.			
Is This Equipment Safe To Operate?		Yes Accept	NO Reject

LEE & ASNT Level II Inspector Name:	SIGNATURE:	Authenticating This Report:	SIGNATURE:
Khaled Mahmoud		Mohammed Abdullah	

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner’s work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation “LOLER”. The result was found Satisfactory at the time of Inspection and considered Safe for Lifting





LIFTING ACCESSORIES OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	DAQING DRILLING COMPANY	Certificate no:	QC-B-05-25-0263-10-16
Location:	DQ RIG 022	Job Order No:	QC-B-05-25-0263
Date of Examination:	11-May-2025	Next Inspection Due:	10-NOV-2025
Last Inspection		Last Proof Load Test Date	
08- JAN - 2025		By Manufacture	

IDENTIFICATION NO	DESCRIPTION	QTY	SWL			
B1057	Single Leg Wire Rope Sling DIM : 0.610 m (L) X 16 mm (DIA) IWRC MECHANICALLY SPLICED WITH ALUMINUM FERRULES. SOFT EYE X SOFT EYE FOS: 5 : 1 Location: STORE	01	3.3 TON			
Applicable Reference Standard:	BS EN 13414-1					
* Is this the first examination after installation or assembly at a new site or location?	YES	NO	√			
	Was the examination carried out?					
* If the answer to the above question is YES has the equipment been installed correctly?	YES	NO	√			
	* Within an interval of 6 months?					
			YES	NO	√	
			* Within an interval of 12 months?			
			YES	NO	√	
			* By an examination scheme?			
			YES	NO	√	
			* After the occurrence of exceptional circumstances?			
			YES	NO	√	
Identification Of Any Part Found To Have A Defect Which Is Or Could Become A Danger To Persons And A Description Of The Defect: None						
Is The Above A Defect Which Is Of Immediate Danger To Persons				YES	NO	√
Is The Above A Defect Which Is Not Yet But Could Become A Danger To Persons: (If YES State The Date By When)				NO	√	YES
Particulars Of Any Repair, Renewal, Or Alteration Required To Remedy The Defect Identified Above: None						
** Visual And Dimension Check was Carried Out.						
Is This Equipment Safe To Operate?		Yes Accept	√	NO Reject		

LEE & ASNT Level II Inspector Name:	SIGNATURE:	Authenticating This Report:	SIGNATURE:
Khaled Mahmoud		Mohammed Abdullah	

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner’s work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation “LOLER”. The result was found Satisfactory at the time of Inspection and considered Safe for Lifting







LIFTING ACCESSORIES OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	DAQING DRILLING COMPANY	Certificate no:	QC-B-05-25-0263-10-17
Location:	DQ RIG 022	Job Order No:	QC-B-05-25-0263
Date of Examination:	11-MaY-2025	Next Inspection Due:	10-NOV-2025
Last Inspection		Last Proof Load Test Date	
08- JAN - 2025		By Manufacture	

IDENTIFICATION NO	DESCRIPTION	QTY	SWL
M5698 M5697 M5696 B4090 B4083 M5699	Single Leg Wire Rope Sling DIM : 6 m (L) X 44 mm (DIA) IWRC MECHANICALLY SPLICED WITH ALUMINUM FERRULES. SOFT EYE X SOFT EYE FOS: 5 : 1 Location: STORE	06	24.8 TON
Applicable Reference Standard:	BS EN 13414-1		
* Is this the first examination after installation or assembly at a new site or location?	YES	NO	√
	Was the examination carried out?		
* If the answer to the above question is YES has the equipment been installed correctly?	YES	NO	√
	* Within an interval of 6 months?		
			YES
			NO
			√
			NO
			√
			NO
			√
Identification Of Any Part Found To Have A Defect Which Is Or Could Become A Danger To Persons And A Description Of The Defect: None			
Is The Above A Defect Which Is Of Immediate Danger To Persons			YES
			NO
Is The Above A Defect Which Is Not Yet But Could Become A Danger To Persons: (If YES State The Date By When)			NO
			√
			YES
			By:
Particulars Of Any Repair, Renewal, Or Alteration Required To Remedy The Defect Identified Above: None			
** Visual And Dimension Check was Carried Out.			
Is This Equipment Safe To Operate?		Yes Accept	NO Reject
		√	

LEE & ASNT Level II Inspector Name:	SIGNATURE:	Authenticating This Report:	SIGNATURE:
Khaled Mahmoud		Mohammed Abdullah	

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting



Al Takamul Company for Engineering Services
Quality Control – Iraq



LIFTING ACCESSORIES OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	DAQING DRILLING COMPANY	Certificate no:	QC-B-05-25-0263-10-18
Location:	DQ RIG 022	Job Order No:	QC-B-05-25-0263
Date of Examination:	11-MaY-2025	Next Inspection Due:	10-NOV-2025
Last Inspection		Last Proof Load Test Date	
08- JAN - 2025		By Manufacture	

IDENTIFICATION NO	DESCRIPTION	QTY	SWL
B896 B894	Single Leg Wire Rope Sling DIM : 7 m (L) X 16 mm (DIA) IWRC MECHANICALLY SPLICED WITH ALUMINUM FERRULES. SOFT EYE X SOFT EYE FOS: 5 : 1 Location: STORE	02	3.3 TON
Applicable Reference Standard:	BS EN 13414-1		
* Is this the first examination after installation or assembly at a new site or location?	Was the examination carried out?		
	YES	NO	√
* If the answer to the above question is YES has the equipment been installed correctly?	* Within an interval of 6 months?		
	YES	NO	√
	* Within an interval of 12 months?		
	YES	NO	√
	* By an examination scheme?		
	YES	NO	√
	* After the occurrence of exceptional circumstances?		
	YES	NO	√
Identification Of Any Part Found To Have A Defect Which Is Or Could Become A Danger To Persons And A Description Of The Defect: None			
Is The Above A Defect Which Is Of Immediate Danger To Persons			YES NO √
Is The Above A Defect Which Is Not Yet But Could Become A Danger To Persons: (If YES State The Date By When)			NO √ YES By:
Particulars Of Any Repair, Renewal, Or Alteration Required To Remedy The Defect Identified Above: None			
** Visual And Dimension Check was Carried Out.			
Is This Equipment Safe To Operate?		Yes Accept	NO Reject
		√	

LEE A & ASNT Level II Inspector Name:	SIGNATURE:	Authenticating This Report:	SIGNATURE:
Khaled Mahmoud		Mohammed Abdullah	

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner’s work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation “LOLER”. The result was found Satisfactory at the time of Inspection and considered Safe for Lifting





LIFTING ACCESSORIES OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	DAQING DRILLING COMPANY	Certificate no:	QC-B-05-25-0263-10-19
Location:	DQ RIG 022	Job Order No:	QC-B-05-25-0263
Date of Examination:	11-May-2025	Next Inspection Due:	10-NOV-2025
Last Inspection		Last Proof Load Test Date	
08- JAN - 2025		By Manufacture	

IDENTIFICATION NO	DESCRIPTION	QTY	SWL
666	<p>Single Leg Wire Rope Sling</p> <p>DIM : 12 m (L) X 38 mm (DIA) IWRC MECHANICALLY SPLICED WITH ALUMINUM FERRULES. SOFT EYE X SOFT EYE FOS: 5 : 1 Location: STORE</p>	01	139 KN
Applicable Reference Standard:	BS EN 13414-1		
* Is this the first examination after installation or assembly at a new site or location?	Was the examination carried out?		
	YES	NO	√
* If the answer to the above question is YES has the equipment been installed correctly?	* Within an interval of 6 months?		
	YES	NO	√
	* Within an interval of 12 months?		
	YES	NO	√
	* By an examination scheme?		
	YES	NO	√
	* After the occurrence of exceptional circumstances?		
	YES	NO	√
Identification Of Any Part Found To Have A Defect Which Is Or Could Become A Danger To Persons And A Description Of The Defect: None			
Is The Above A Defect Which Is Of Immediate Danger To Persons			YES NO √
Is The Above A Defect Which Is Not Yet But Could Become A Danger To Persons: (If YES State The Date By When)			NO √ YES By:
Particulars Of Any Repair, Renewal, Or Alteration Required To Remedy The Defect Identified Above: None			
** Visual And Dimension Check was Carried Out.			
Is This Equipment Safe To Operate?		Yes Accept	NO Reject
		√	

LEE & ASNT Level II Inspector Name:	SIGNATURE:	Authenticating This Report:	SIGNATURE:
Khaled Mahmoud		Mohammed Abdullah	

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting





LIFTING ACCESSORIES OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	DAQING DRILLING COMPANY	Certificate no:	QC-B-05-25-0263-10-20
Location:	DQ RIG 022	Job Order No:	QC-B-05-25-0263
Date of Examination:	11-May-2025	Next Inspection Due:	10-NOV-2025
Last Inspection		Last Proof Load Test Date	
08- JAN - 2025		By Manufacture	

IDENTIFICATION NO	DESCRIPTION	QTY	SWL
A7531 A7530 A7533 A7532	Single Leg Wire Rope Sling DIM : 7.2 m (L) X 26 mm (DIA) IWRC MECHANICALLY SPLICED WITH ALUMINUM FERRULES. SOFT EYE X SOFT EYE FOS: 5 : 1 Location: STORE	04	8.6 TON
Applicable Reference Standard:	BS EN 13414-1		
* Is this the first examination after installation or assembly at a new site or location?	Was the examination carried out?		
	YES	NO	√
* If the answer to the above question is YES has the equipment been installed correctly?	* Within an interval of 6 months?		
	YES	NO	√
Identification Of Any Part Found To Have A Defect Which Is Or Could Become A Danger To Persons And A Description Of The Defect: None			
Is The Above A Defect Which Is Of Immediate Danger To Persons			YES NO √
Is The Above A Defect Which Is Not Yet But Could Become A Danger To Persons: (If YES State The Date By When)			NO √ YES By:
Particulars Of Any Repair, Renewal, Or Alteration Required To Remedy The Defect Identified Above: None			
** Visual And Dimension Check was Carried Out.			
Is This Equipment Safe To Operate?		Yes Accept	NO Reject
Is This Equipment Safe To Operate?		√	

LEE A & ASNT Level II Inspector Name:	SIGNATURE:	Authenticating This Report:	SIGNATURE:
Khaled Mahmoud		Mohammed Abdullah	

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner’s work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation “LOLER”. The result was found Satisfactory at the time of Inspection and considered Safe for Lifting







LIFTING ACCESSORIES OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	DAQING DRILLING COMPANY	Certificate no:	QC-B-05-25-0263-10-21
Location:	DQ RIG 022	Job Order No:	QC-B-05-25-0263
Date of Examination:	11-MaY-2025	Next Inspection Due:	10-NOV-2025
Last Inspection		Last Proof Load Test Date	
08- JAN - 2025		By Manufacture	

IDENTIFICATION NO	DESCRIPTION	QTY	SWL
S1909	<p>Single Leg Wire Rope Sling</p> <p>DIM : 8 m (L) X 36 mm (DIA) IWRC MECHANICALLY SPLICED WITH ALUMINUM FERRULES. SOFT EYE X SOFT EYE FOS: 5 : 1 Location: STORE</p>	01	13 TON
Applicable Reference Standard:	BS EN 13414-1		
* Is this the first examination after installation or assembly at a new site or location?	YES	NO	√
	Was the examination carried out?		
* If the answer to the above question is YES has the equipment been installed correctly?	YES	NO	√
	* Within an interval of 6 months?		
			YES
			NO
			√
			NO
			√
			NO
			√
Identification Of Any Part Found To Have A Defect Which Is Or Could Become A Danger To Persons And A Description Of The Defect: None			
Is The Above A Defect Which Is Of Immediate Danger To Persons			YES
			NO
Is The Above A Defect Which Is Not Yet But Could Become A Danger To Persons: (If YES State The Date By When)			NO
			√
			YES
			By:
Particulars Of Any Repair, Renewal, Or Alteration Required To Remedy The Defect Identified Above: None			
** Visual And Dimension Check was Carried Out.			
Is This Equipment Safe To Operate?		Yes Accept	NO Reject
		√	

LEE & ASNT Level II Inspector Name:	SIGNATURE:	Authenticating This Report:	SIGNATURE:
Khaled Mahmoud		Mohammed Abdullah	

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting





LIFTING ACCESSORIES OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	DAQING DRILLING COMPANY	Certificate no:	QC-B-05-25-0263-10-22
Location:	DQ RIG 022	Job Order No:	QC-B-05-25-0263
Date of Examination:	11-MaY-2025	Next Inspection Due:	10-NOV-2025
Last Inspection		Last Proof Load Test Date	
08- JAN - 2025		By Manufacture	

IDENTIFICATION NO	DESCRIPTION	QTY	SWL
A5421 A5417 A5412 A5413 C3999	Single Leg Wire Rope Sling DIM : 8 m (L) X 16 mm (DIA) IWRC MECHANICALLY SPLICED WITH ALUMINUM FERRULES. SOFT EYE X SOFT EYE FOS: 5 : 1 Location: STORE	05	3 TON
Applicable Reference Standard:	BS EN 13414-1		
* Is this the first examination after installation or assembly at a new site or location?	YES	NO	√
	Was the examination carried out?		
* If the answer to the above question is YES has the equipment been installed correctly?	YES	NO	√
	* Within an interval of 6 months?		
			YES
			NO
			√
			NO
			√
			NO
			√
Identification Of Any Part Found To Have A Defect Which Is Or Could Become A Danger To Persons And A Description Of The Defect: None			
Is The Above A Defect Which Is Of Immediate Danger To Persons			YES
			NO
Is The Above A Defect Which Is Not Yet But Could Become A Danger To Persons: (If YES State The Date By When)			NO
			√
			YES
			By:
Particulars Of Any Repair, Renewal, Or Alteration Required To Remedy The Defect Identified Above: None			
** Visual And Dimension Check was Carried Out.			
Is This Equipment Safe To Operate?		Yes Accept	NO Reject
		√	

LEE & ASNT Level II Inspector Name:	SIGNATURE:	Authenticating This Report:	SIGNATURE:
Khaled Mahmoud		Mohammed Abdullah	

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting





LIFTING ACCESSORIES OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	DAQING DRILLING COMPANY	Certificate no:	QC-B-05-25-0263-10-23
Location:	DQ RIG 022	Job Order No:	QC-B-05-25-0263
Date of Examination:	11-MaY-2025	Next Inspection Due:	10-NOV-2025
Last Inspection		Last Proof Load Test Date	
08- JAN - 2025		By Manufacture	

IDENTIFICATION NO	DESCRIPTION	QTY	SWL
D9209	<p align="center">Single Leg Wire Rope Sling</p> <p>DIM : 4.95m (L) X 22 mm (DIA) IWRC MECHANICALLY SPLICED WITH ALUMINUM FERRULES. HARD EYE X SOFT EYE FOS: 5 : 1 Location: STORE</p>	01	5.65 TON
Applicable Reference Standard:	BS EN 13414-1		
* Is this the first examination after installation or assembly at a new site or location?	YES	NO	√
	Was the examination carried out?		
* If the answer to the above question is YES has the equipment been installed correctly?	YES	NO	√
	* Within an interval of 6 months?		
			YES
			NO
			√
			YES
			NO
			√
Identification Of Any Part Found To Have A Defect Which Is Or Could Become A Danger To Persons And A Description Of The Defect: None			
Is The Above A Defect Which Is Of Immediate Danger To Persons			YES
			NO
Is The Above A Defect Which Is Not Yet But Could Become A Danger To Persons: (If YES State The Date By When)			NO
			√
			YES
			By:
Particulars Of Any Repair, Renewal, Or Alteration Required To Remedy The Defect Identified Above: None			
** Visual And Dimension Check was Carried Out.			
Is This Equipment Safe To Operate?		Yes Accept	NO Reject
		√	

LEE & ASNT Level II Inspector Name:	SIGNATURE:	Authenticating This Report:	SIGNATURE:
Khaled Mahmoud		Mohammed Abdullah	

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner’s work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation “LOLER”. The result was found Satisfactory at the time of Inspection and considered Safe for Lifting





LIFTING ACCESSORIES OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	DAQING DRILLING COMPANY	Certificate no:	QC-B-05-25-0263-10-24
Location:	DQ RIG 022	Job Order No:	QC-B-05-25-0263
Date of Examination:	11-MaY-2025	Next Inspection Due:	10-NOV-2025
Last Inspection		Last Proof Load Test Date	
08- JAN - 2025		By Manufacture	

IDENTIFICATION NO	DESCRIPTION	QTY	SWL
DQ22-822	<p>Single Leg Wire Rope Sling</p> <p>DIM : 8 m (L) X 16 mm (DIA) IWRC MECHANICALLY SPLICED WITH ALUMINUM FERRULES. HARD EYE X SOFT EYE FOS: 5 : 1 Location: STORE</p>	01	3 TON
Applicable Reference Standard:	BS EN 13414-1		
* Is this the first examination after installation or assembly at a new site or location?	YES	NO	√
	Was the examination carried out?		
* If the answer to the above question is YES has the equipment been installed correctly?	YES	NO	√
	* Within an interval of 6 months?		
* Within an interval of 12 months?			√
* By an examination scheme?			√
* After the occurrence of exceptional circumstances?			√
Identification Of Any Part Found To Have A Defect Which Is Or Could Become A Danger To Persons And A Description Of The Defect: None			
Is The Above A Defect Which Is Of Immediate Danger To Persons			YES NO √
Is The Above A Defect Which Is Not Yet But Could Become A Danger To Persons: (If YES State The Date By When)			NO √ YES By:
Particulars Of Any Repair, Renewal, Or Alteration Required To Remedy The Defect Identified Above: None			
** Visual And Dimension Check was Carried Out.			
Is This Equipment Safe To Operate?		Yes Accept	NO Reject

LEE & ASNT Level II Inspector Name:	SIGNATURE:	Authenticating This Report:	SIGNATURE:
Khaled Mahmoud		Mohammed Abdullah	

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner’s work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation “LOLER”. The result was found Satisfactory at the time of Inspection and considered Safe for Lifting



Al Takamul Company for Engineering Services
Quality Control – Iraq



LIFTING ACCESSORIES OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	DAQING DRILLING COMPANY	Certificate no:	QC-B-05-25-0263-10-25
Location:	DQ RIG 022	Job Order No:	QC-B-05-25-0263
Date of Examination:	11-MaY-2025	Next Inspection Due:	10-NOV-2025
Last Inspection		Last Proof Load Test Date	
08- JAN - 2025		By Manufacture	

IDENTIFICATION NO	DESCRIPTION	QTY	SWL
221 222 223 226 225 229 227 224	Single Leg Wire Rope Sling DIM : 3 m (L) X 10 mm (DIA) IWRC MECHANICALLY SPLICED WITH ALUMINUM FERRULES. HARD EYE X HARD EYE FOS: 5 : 1 Location: STORE	08	18 KN
Applicable Reference Standard:	BS EN 13414-1		
* Is this the first examination after installation or assembly at a new site or location?	Was the examination carried out?		
	YES	NO	√
* If the answer to the above question is YES has the equipment been installed correctly?	* Within an interval of 6 months?		YES
	YES	NO	√
* Within an interval of 12 months?		YES	NO
* By an examination scheme?		YES	NO
* After the occurrence of exceptional circumstances?		YES	NO
Identification Of Any Part Found To Have A Defect Which Is Or Could Become A Danger To Persons And A Description Of The Defect: None			
Is The Above A Defect Which Is Of Immediate Danger To Persons		YES	NO
Is The Above A Defect Which Is Not Yet But Could Become A Danger To Persons: (If YES State The Date By When)		NO	YES
Particulars Of Any Repair, Renewal, Or Alteration Required To Remedy The Defect Identified Above: None			
** Visual And Dimension Check was Carried Out.			
Is This Equipment Safe To Operate?		Yes Accept	NO Reject
		√	

LEE & ASNT Level II Inspector Name:	SIGNATURE:	Authenticating This Report:	SIGNATURE:
Khaled Mahmoud		Mohammed Abdullah	

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner’s work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation “LOLER”. The result was found Satisfactory at the time of Inspection and considered Safe for Lifting





Al Takamul Company for Engineering Services
Quality Control – Iraq



LIFTING ACCESSORIES OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	DAQING DRILLING COMPANY	Certificate no:	QC-B-05-25-0263-10-26
Location:	DQ RIG 022	Job Order No:	QC-B-05-25-0263
Date of Examination:	11-MaY-2025	Next Inspection Due:	10-NOV-2025
Last Inspection		Last Proof Load Test Date	
08- JAN - 2025		By Manufacture	

IDENTIFICATION NO	DESCRIPTION	QTY	SWL				
B4387	<p>Single Leg Wire Rope Sling</p> <p>DIM : 1 m (L) X 16 mm (DIA) IWRC MECHANICALLY SPLICED WITH ALUMINUM FERRULES. SOFT EYE X SOFT EYE FOS: 5 : 1 Location: CHEMICAL BAG CROSS LIFTING</p>	01	3.3 TON				
Applicable Reference Standard:	BS EN 13414-1						
* Is this the first examination after installation or assembly at a new site or location?	YES		NO	Was the examination carried out?			
			√	* Within an interval of 6 months?		YES	NO
* If the answer to the above question is YES has the equipment been installed correctly?	YES		NO	* Within an interval of 12 months?		YES	NO
	√			* By an examination scheme?		YES	NO
				* After the occurrence of exceptional circumstances?		YES	NO
Identification Of Any Part Found To Have A Defect Which Is Or Could Become A Danger To Persons And A Description Of The Defect: None							
Is The Above A Defect Which Is Of Immediate Danger To Persons						YES	NO
Is The Above A Defect Which Is Not Yet But Could Become A Danger To Persons: (If YES State The Date By When)						NO	YES
Particulars Of Any Repair, Renewal, Or Alteration Required To Remedy The Defect Identified Above: None							
** Visual And Dimension Check was Carried Out.							
Is This Equipment Safe To Operate?				Yes Accept	√	NO Reject	

LEE & ASNT Level II Inspector Name:	SIGNATURE:	Authenticating This Report:	SIGNATURE:
Khaled Mahmoud		Mohammed Abdullah	

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner’s work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation “LOLER”. The result was found Satisfactory at the time of Inspection and considered Safe for Lifting







LIFTING ACCESSORIES OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	DAQING DRILLING COMPANY	Certificate no:	QC-B-05-25-0263-10-27
Location:	DQ RIG 022	Job Order No:	QC-B-05-25-0263
Date of Examination:	11-MaY-2025	Next Inspection Due:	10-NOV-2025
Last Inspection		Last Proof Load Test Date	
08- JAN - 2025		By Manufacture	

IDENTIFICATION NO	DESCRIPTION	QTY	SWL
M3552 M3555	Single Leg Wire Rope Sling DIM : 1 m (L) X 14 mm (DIA) IWRC MECHANICALLY SPLICED WITH ALUMINUM FERRULES. SOFT EYE X SOFT EYE FOS: 5 : 1 Location: SENSOR BOX	01	2.1 TON
Applicable Reference Standard:	BS EN 13414-1		
* Is this the first examination after installation or assembly at a new site or location?	YES	NO	√
	Was the examination carried out?		
* If the answer to the above question is YES has the equipment been installed correctly?	YES	NO	√
	* Within an interval of 6 months?		
			YES
			NO
			√
			NO
			√
			NO
			√
Identification Of Any Part Found To Have A Defect Which Is Or Could Become A Danger To Persons And A Description Of The Defect: None			
Is The Above A Defect Which Is Of Immediate Danger To Persons			YES
			NO
Is The Above A Defect Which Is Not Yet But Could Become A Danger To Persons: (If YES State The Date By When)			NO
			√
			YES
			By:
Particulars Of Any Repair, Renewal, Or Alteration Required To Remedy The Defect Identified Above: None			
** Visual And Dimension Check was Carried Out.			
Is This Equipment Safe To Operate?		Yes Accept	NO Reject
		√	

LEE & ASNT Level II Inspector Name:	SIGNATURE:	Authenticating This Report:	SIGNATURE:
Khaled Mahmoud		Mohammed Abdullah	

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting

