

**AI TAKAMUL COMPANY FOR ENGINEERING TESTS
AND PROFESSIONAL SAFETY LIMITED**

Basra, North Rumaila, Quality Control Yard - Iraq

Tel: +9647810009138 / +9647834964657

Email: OP@qualitycontrol-iraq.com / hany.akafi@qualitycontrol-iraq.com



CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

| | | | | | |
|---|---|--|---|--------------------------------------|---|
| Date of Examination: | 03/05/2025 | Date of Report: | 03/05/2025 | Certificate No: | QC-25-HDBS-0205-028 |
| Client Name: | HALLIBURTON | Location: | HDBS | Job Number: | 02052025 |
| Serial Number: | QTY | Description | SWL | Date of manufacture if known: | Date of last thorough examination |
| 0803 | 01 | <p><u>SINGLE LEG WIRE ROPE SLING</u></p> <p>Manufacturer: Safety Marine Dimension: 1.8 m (L) x 12 mm (Dia) FOS: 5:1 IWRC, Mechanically Spliced with Aluminum Ferrule HARD EYE X HARD EYE</p> | 1.7 ton | N/A | 28/11/2024 |
| Reference Standard: | | BS EN 13414-1 / HAL DOC: WM-GL-HAL-HSE-0420F & WM-GL-HAL-HSE-0420C REV 1 | | | |
| Is this the first examination after Installation or assembly at a new site or location? | | YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> | Was the examination carried out: Within an interval of 6 months? | | YES <input checked="" type="checkbox"/> NO <input type="checkbox"/> |
| If the answer to the above question is YES has the equipment been installed correctly? | | YES <input type="checkbox"/> NO <input type="checkbox"/> | With an interval of 12 months? | | YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> |
| | | | In accordance with an examination scheme? | | YES <input checked="" type="checkbox"/> NO <input type="checkbox"/> |
| | | | After the occurrence of exceptional circumstances? | | YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> |
| Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none state NONE) NONE | | | | | |
| Is the above a defect which is of immediate danger to persons: | | | | | YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> |
| Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when) | | | | | N/A |
| Particulars of any repair, renewal or alteration required to remedy the defect identified above: | | | | | |
| Particulars of any tests carried out as part of the examination: (If none state NONE) The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory | | | | | |
| IS THIS EQUIPMENT SAFE TO OPERATE? | | | | | YES <input checked="" type="checkbox"/> NO <input type="checkbox"/> |
| Name of Inspector: | Name of person authenticating this report: | | Signature & Stamp: | | |
| ASHRAF ELSAID | MOHAMED ABDALLAH | | | | |
| Date of Next Through Examination: | 02/11/2025 | | | | |

REV: 01 Dated: 20 June 2022

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.

