



LIFTING ACCESSORIES OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	DAQING DRILLING COMPANY	Certificate no:	QC-B-05-25-0263-11-01
Location:	DQ RIG 022	Job Order No:	QC-B-05-25-0263
Date of Examination:	09-May-2025	Next Inspection Due:	08-Nov-2025
Last Inspection		Last Proof Load Test Date	
N/A		By Manufacture	

IDENTIFICATION NO	DESCRIPTION	QTY	SWL
XK-19-1179000	<p>MASTER BUSHING PULLER SLING ASSEMBLY</p> <p>Two Way Bowl Lifter Plate Connected With One Top Shackle 1 1/8” 9.5T With Two Side Shackles 5/8” 3.25T And Connected With Two Single Leg Wire Rope, SWL 3T SN (N141NMSK.3) & (N141NMSK.4) 16 mm Diameter, 1.30 M Length, IWRC, Mechanically Spliced With Crosby Steel Swage Spelter Sockets X Steel Ferrules Hard Eyes C/W Two GP Regular Swivel 7/8" WLL 4.5 T SN (22) & (23) With Two Side Shackles 7/8” 6.5T C/W Two Regular Bushing Eye Hooks At Bottom SN: (525572 & 525571) Location: Bushing Puller – Rig Floor</p>	01	<p>1.4 Short TONS 1.27 Metric Tonnes @0- 45°</p>
Applicable Reference Standard:	BS EN 13414		
* Is this the first examination after installation or assembly at a new site or location?	YES	NO	√
	Was the examination carried out?		
* If the answer to the above question is YES has the equipment been installed correctly?	YES	NO	√
	* Within an interval of 6 months?		
			YES
			NO
			√
			YES
			NO
			√
Identification Of Any Part Found To Have A Defect Which Is Or Could Become A Danger To Persons And A Description Of The Defect: None			
Is The Above A Defect Which Is Of Immediate Danger To Persons			YES
			NO
			√
Is The Above A Defect Which Is Not Yet But Could Become A Danger To Persons: (If YES State The Date By When)			NO
			√
			YES
			By:
Particulars Of Any Repair, Renewal, Or Alteration Required To Remedy The Defect Identified Above: None			
** Visual And Dimension Check was Carried Out.			
Is This Equipment Safe To Operate?		Yes Accept	NO Reject
		√	

LEEA & ASNT Level II Inspector Name:	SIGNATURE:	Authenticating This Report:	SIGNATURE:
Khaled Mahmoud		Ashraf Al Said	

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner’s work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation “LOLER”. The result was found Satisfactory at the time of Inspection and considered Safe for Lifting








LIFTING ACCESSORIES OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	DAQING DRILLING COMPANY	Certificate no:	QC-B-05-25-0263-11-02
Location:	DQ RIG 022	Job Order No:	QC-B-05-25-0263
Date of Examination:	09-May-2025	Next Inspection Due:	08-Nov-2025
Last Inspection		Last Proof Load Test Date	
N/A		By Manufacture	

IDENTIFICATION NO	DESCRIPTION	QTY	SWL
A25	<p>Safety pin bow Shackles</p> <p>Size : 7/8" Grade : 6</p> <p>Manufacture: Crosby</p> <p>Location: Bushing Puller – Rig Floor</p> 	01	6.5 Ton
Applicable Reference Standard:	BS EN 13889 / US FED SPEC RR-C-27 1 D		
<p>* Is this the first examination after installation or assembly at a new site or location?</p> <p>* If the answer to the above question is YES has the equipment been installed correctly?</p>	<p>Was the examination carried out?</p>		
	<p>YES</p> <p>NO</p>	<p>YES</p> <p>YES</p> <p>YES</p> <p>YES</p>	<p>NO</p> <p>NO</p> <p>NO</p> <p>NO</p>
	<p>YES</p> <p>NO</p>	<p>YES</p> <p>YES</p> <p>YES</p> <p>YES</p>	<p>NO</p> <p>NO</p> <p>NO</p> <p>NO</p>
	<p>YES</p> <p>NO</p>	<p>YES</p> <p>YES</p> <p>YES</p> <p>YES</p>	<p>NO</p> <p>NO</p> <p>NO</p> <p>NO</p>
<p>Identification Of Any Part Found To Have A Defect Which Is Or Could Become A Danger To Persons And A Description Of The Defect: None</p>			
<p>Is The Above A Defect Which Is Of Immediate Danger To Persons</p>			<p>YES</p> <p>NO</p>
<p>Is The Above A Defect Which Is Not Yet But Could Become A Danger To Persons: (If YES State The Date By When)</p>			<p>NO</p> <p>YES</p> <p>By:</p>
<p>Particulars Of Any Repair, Renewal, Or Alteration Required To Remedy The Defect Identified Above: None</p>			
<p>** Visual And Dimension Check was Carried Out.</p>			
<p>Is This Equipment Safe To Operate?</p>		<p>Yes Accept</p> <p>NO Reject</p>	<p>√</p>

LEE & ASNT Level II Inspector Name:	SIGNATURE:	Authenticating This Report:	SIGNATURE:
Khaled Mahmoud		Ashraf Al Said	


THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner’s work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation “LOLER”. The result was found Satisfactory at the time of Inspection and considered Safe for Lifting





LIFTING ACCESSORIES OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	DAQING DRILLING COMPANY	Certificate no:	QC-B-05-25-0263-11-03
Location:	DQ RIG 022	Job Order No:	QC-B-05-25-0263
Date of Examination:	09-May-2025	Next Inspection Due:	08-Nov-2025
Last Inspection		Last Proof Load Test Date	
N/A		By Manufacture	

IDENTIFICATION NO	DESCRIPTION	QTY	SWL					
A7971	<p>Safety pin bow Shackles</p> <p>Size : 5/8" Grade : 6</p> <p>Manufacture: Toyolift</p> <p>Location: Bushing Puller – Rig Floor</p> 	01	3.25 Ton					
Applicable Reference Standard:	BS EN 13889 / US FED SPEC RR-C-27 1 D							
<p>* Is this the first examination after installation or assembly at a new site or location?</p> <p>* If the answer to the above question is YES has the equipment been installed correctly?</p>	Was the examination carried out?							
	YES		NO	√	<p>* Within an interval of 6 months?</p> <p>YES</p>	√	NO	
					<p>* Within an interval of 12 months?</p> <p>YES</p>		NO	√
	YES	√	NO		<p>* By an examination scheme?</p> <p>YES</p>	√	NO	
				<p>* After the occurrence of exceptional circumstances?</p> <p>YES</p>		NO	√	
Identification Of Any Part Found To Have A Defect Which Is Or Could Become A Danger To Persons And A Description Of The Defect: None								
Is The Above A Defect Which Is Of Immediate Danger To Persons			YES		NO	√		
Is The Above A Defect Which Is Not Yet But Could Become A Danger To Persons: (If YES State The Date By When)			NO	√	YES	By:		
Particulars Of Any Repair, Renewal, Or Alteration Required To Remedy The Defect Identified Above: None								
** Visual And Dimension Check was Carried Out.								
Is This Equipment Safe To Operate?		Yes Accept	√	NO Reject				

LEE & ASNT Level II Inspector Name:	SIGNATURE:	Authenticating This Report:	SIGNATURE:
Khaled Mahmoud		Ashraf Al Said	


THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting





LIFTING ACCESSORIES OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	DAQING DRILLING COMPANY	Certificate no:	QC-B-05-25-0263-11-04
Location:	DQ RIG 022	Job Order No:	QC-B-05-25-0263
Date of Examination:	09-May-2025	Next Inspection Due:	08-Nov-2025
Last Inspection		Last Proof Load Test Date	
N/A		By Manufacture	

IDENTIFICATION NO	DESCRIPTION	QTY	SWL	
1	<p>Safety pin bow Shackles</p> <p>Size : 7/8" Grade : 6</p> <p>Manufacture: H.K</p> <p>Location: Bushing Puller – Rig Floor</p> 	01	6.5 Ton	
Applicable Reference Standard:	BS EN 13889 / US FED SPEC RR-C-27 1 D			
<p>* Is this the first examination after installation or assembly at a new site or location?</p> <p>* If the answer to the above question is YES has the equipment been installed correctly?</p>	Was the examination carried out?			
	YES	NO	√	
	* Within an interval of 6 months?		YES	NO
	* Within an interval of 12 months?		YES	NO
* By an examination scheme?		YES	NO	
* After the occurrence of exceptional circumstances?		YES	NO	
Identification Of Any Part Found To Have A Defect Which Is Or Could Become A Danger To Persons And A Description Of The Defect: None				
Is The Above A Defect Which Is Of Immediate Danger To Persons			YES	NO
Is The Above A Defect Which Is Not Yet But Could Become A Danger To Persons: (If YES State The Date By When)			NO	YES
Particulars Of Any Repair, Renewal, Or Alteration Required To Remedy The Defect Identified Above: None				
** Visual And Dimension Check was Carried Out.				
Is This Equipment Safe To Operate?		Yes Accept	NO Reject	
		√		

LEE & ASNT Level II Inspector Name:	SIGNATURE:	Authenticating This Report:	SIGNATURE:
Khaled Mahmoud		Ashraf Al Said	


THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting





LIFTING ACCESSORIES OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	DAQING DRILLING COMPANY	Certificate no:	QC-B-05-25-0263-11-05
Location:	DQ RIG 022	Job Order No:	QC-B-05-25-0263
Date of Examination:	09-May-2025	Next Inspection Due:	08-Nov-2025
Last Inspection		Last Proof Load Test Date	
N/A		By Manufacture	

IDENTIFICATION NO	DESCRIPTION	QTY	SWL					
118	<p>Safety pin bow Shackles</p> <p>Size : 7/8" Grade : 6</p> <p>Manufacture: XW</p> <p>Location: Bushing Puller – Rig Floor</p> 	01	6.5 Ton					
Applicable Reference Standard:	BS EN 13889 / US FED SPEC RR-C-27 1 D							
<p>* Is this the first examination after installation or assembly at a new site or location?</p> <p>* If the answer to the above question is YES has the equipment been installed correctly?</p>	Was the examination carried out?							
	YES		NO	√	<p>* Within an interval of 6 months?</p> <p>YES</p>	√	NO	
					<p>* Within an interval of 12 months?</p> <p>YES</p>		NO	√
	YES	√	NO		<p>* By an examination scheme?</p> <p>YES</p>	√	NO	
				<p>* After the occurrence of exceptional circumstances?</p> <p>YES</p>		NO	√	
Identification Of Any Part Found To Have A Defect Which Is Or Could Become A Danger To Persons And A Description Of The Defect: None								
Is The Above A Defect Which Is Of Immediate Danger To Persons				YES		NO	√	
Is The Above A Defect Which Is Not Yet But Could Become A Danger To Persons: (If YES State The Date By When)				NO	√	YES	By:	
Particulars Of Any Repair, Renewal, Or Alteration Required To Remedy The Defect Identified Above: None								
** Visual And Dimension Check was Carried Out.								
Is This Equipment Safe To Operate?		Yes Accept	√	NO Reject				

LEE & ASNT Level II Inspector Name:	SIGNATURE:	Authenticating This Report:	SIGNATURE:
Khaled Mahmoud		Ashraf Al Said	

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner’s work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation “LOLER”. The result was found Satisfactory at the time of Inspection and considered Safe for Lifting








LIFTING ACCESSORIES OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	DAQING DRILLING COMPANY	Certificate no:	QC-B-05-25-0263-11-06
Location:	DQ RIG 022	Job Order No:	QC-B-05-25-0263
Date of Examination:	09-May-2025	Next Inspection Due:	08-Nov-2025
Last Inspection		Last Proof Load Test Date	
N/A		By Manufacture	

IDENTIFICATION NO	DESCRIPTION	QTY	SWL					
40	<p>D- Shackles</p> <p>Size : 5/8" Grade : 6</p> <p>Manufacture: DY</p> <p>Location: Bushing Puller – Rig Floor</p> 	01	6.5 Ton					
Applicable Reference Standard:	BS EN 13889 / US FED SPEC RR-C-27 1 D							
<p>* Is this the first examination after installation or assembly at a new site or location?</p> <p>* If the answer to the above question is YES has the equipment been installed correctly?</p>	Was the examination carried out?							
	YES		NO	√	<p>* Within an interval of 6 months?</p> <p>YES</p>	√	NO	
					<p>* Within an interval of 12 months?</p> <p>YES</p>		NO	√
	YES	√	NO		<p>* By an examination scheme?</p> <p>YES</p>	√	NO	
				<p>* After the occurrence of exceptional circumstances?</p> <p>YES</p>		NO	√	
Identification Of Any Part Found To Have A Defect Which Is Or Could Become A Danger To Persons And A Description Of The Defect: None								
Is The Above A Defect Which Is Of Immediate Danger To Persons			YES		NO	√		
Is The Above A Defect Which Is Not Yet But Could Become A Danger To Persons: (If YES State The Date By When)			NO	√	YES		By:	
Particulars Of Any Repair, Renewal, Or Alteration Required To Remedy The Defect Identified Above: None								
** Visual And Dimension Check was Carried Out.								
Is This Equipment Safe To Operate?		Yes Accept	√	NO Reject				

LEEAA & ASNT Level II Inspector Name:	SIGNATURE:	Authenticating This Report:	SIGNATURE:
Khaled Mahmoud		Ashraf Al Said	


THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner’s work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation “LOLER”. The result was found Satisfactory at the time of Inspection and considered Safe for Lifting





LIFTING ACCESSORIES OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	DAQING DRILLING COMPANY	Certificate no:	QC-B-05-25-0263-11-07
Location:	DQ RIG 022	Job Order No:	QC-B-05-25-0263
Date of Examination:	09-May-2025	Next Inspection Due:	08-Nov-2025
Last Inspection		Last Proof Load Test Date	
N/A		By Manufacture	

IDENTIFICATION NO	DESCRIPTION	QTY	SWL
F3	<p>Safety pin bow Shackles</p> <p>Size : 1 1/8" Grade : 6</p> <p>Manufacture: J&L</p> <p>Location: Bushing Puller – Rig Floor</p> 	01	9.5 Ton
Applicable Reference Standard:	BS EN 13889 / US FED SPEC RR-C-27 1 D		
<p>* Is this the first examination after installation or assembly at a new site or location?</p> <p>* If the answer to the above question is YES has the equipment been installed correctly?</p>	<p>Was the examination carried out?</p>		
	<p>YES</p> <p>NO</p>	<p>YES</p> <p>YES</p> <p>YES</p> <p>YES</p>	<p>NO</p> <p>NO</p> <p>NO</p> <p>NO</p>
	<p>NO</p> <p>YES</p>	<p>NO</p> <p>NO</p> <p>NO</p> <p>NO</p>	<p>NO</p> <p>NO</p> <p>NO</p> <p>NO</p>
	<p>YES</p> <p>NO</p>	<p>NO</p> <p>NO</p> <p>NO</p> <p>NO</p>	<p>NO</p> <p>NO</p> <p>NO</p> <p>NO</p>
<p>Identification Of Any Part Found To Have A Defect Which Is Or Could Become A Danger To Persons And A Description Of The Defect: None</p>			
<p>Is The Above A Defect Which Is Of Immediate Danger To Persons</p>			<p>YES</p> <p>NO</p>
<p>Is The Above A Defect Which Is Not Yet But Could Become A Danger To Persons: (If YES State The Date By When)</p>			<p>NO</p> <p>YES</p> <p>By:</p>
<p>Particulars Of Any Repair, Renewal, Or Alteration Required To Remedy The Defect Identified Above: None</p>			
<p>** Visual And Dimension Check was Carried Out.</p>			
<p>Is This Equipment Safe To Operate?</p>		<p>Yes Accept</p> <p>NO Reject</p>	<p>√</p>

LEEAA & ASNT Level II Inspector Name:	SIGNATURE:	Authenticating This Report:	SIGNATURE:
Khaled Mahmoud		Ashraf Al Said	


THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner’s work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation “LOLER”. The result was found Satisfactory at the time of Inspection and considered Safe for Lifting





LIFTING ACCESSORIES OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	DAQING DRILLING COMPANY	Certificate no:	QC-B-05-25-0263-11-08
Location:	DQ RIG 022	Job Order No:	QC-B-05-25-0263
Date of Examination:	09-May-2025	Next Inspection Due:	08-Nov-2025
Last Inspection		Last Proof Load Test Date	
N/A		By Manufacture	

IDENTIFICATION NO	DESCRIPTION	QTY	SWL								
B5957	<p>Safety pin bow Shackles</p> <p>Size : 7/8" Grade : 6</p> <p>Manufacture: Toyolift</p> <p>Location: Rig Floor</p> 	01	6.5 Ton								
Applicable Reference Standard:	BS EN 13889 / US FED SPEC RR-C-27 1 D										
* Is this the first examination after installation or assembly at a new site or location?	YES		NO	√	Was the examination carried out?						
					* Within an interval of 6 months?		YES	√	NO		
* If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO		* Within an interval of 12 months?		YES		NO	√	
					* By an examination scheme?		YES	√	NO		
					* After the occurrence of exceptional circumstances?		YES		NO	√	
Identification Of Any Part Found To Have A Defect Which Is Or Could Become A Danger To Persons And A Description Of The Defect: None											
Is The Above A Defect Which Is Of Immediate Danger To Persons								YES		NO	√
Is The Above A Defect Which Is Not Yet But Could Become A Danger To Persons: (If YES State The Date By When)								NO	√	YES	
Particulars Of Any Repair, Renewal, Or Alteration Required To Remedy The Defect Identified Above: None											
** Visual And Dimension Check was Carried Out.											
Is This Equipment Safe To Operate?				Yes Accept		√	NO Reject				

LEE & ASNT Level II Inspector Name:	SIGNATURE:	Authenticating This Report:	SIGNATURE:
Khaled Mahmoud		Ashraf Al Said	


THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting





LIFTING ACCESSORIES OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	DAQING DRILLING COMPANY	Certificate no:	QC-B-05-25-0263-11-09
Location:	DQ RIG 022	Job Order No:	QC-B-05-25-0263
Date of Examination:	09-May-2025	Next Inspection Due:	08-Nov-2025
Last Inspection		Last Proof Load Test Date	
N/A		By Manufacture	

IDENTIFICATION NO	DESCRIPTION	QTY	SWL
CB4P	<p>Safety pin bow Shackles</p> <p>Size : 7/8" Grade : 6</p> <p>Manufacture: Crosby</p> <p>Location: Rig Floor</p> 	01	6.5 Ton
Applicable Reference Standard:	BS EN 13889 / US FED SPEC RR-C-27 1 D		
* Is this the first examination after installation or assembly at a new site or location?	YES	NO	√
	Was the examination carried out?		
* If the answer to the above question is YES has the equipment been installed correctly?	* Within an interval of 6 months?		YES √ NO
	* Within an interval of 12 months?		YES NO √
	* By an examination scheme?		YES √ NO
	* After the occurrence of exceptional circumstances?		YES NO √
Identification Of Any Part Found To Have A Defect Which Is Or Could Become A Danger To Persons And A Description Of The Defect: None			
Is The Above A Defect Which Is Of Immediate Danger To Persons			YES NO √
Is The Above A Defect Which Is Not Yet But Could Become A Danger To Persons: (If YES State The Date By When)			NO √ YES By:
Particulars Of Any Repair, Renewal, Or Alteration Required To Remedy The Defect Identified Above: None			
** Visual And Dimension Check was Carried Out.			
Is This Equipment Safe To Operate?		Yes Accept	√ NO Reject

LEE & ASNT Level II Inspector Name:	SIGNATURE:	Authenticating This Report:	SIGNATURE:
Khaled Mahmoud		Ashraf Al Said	

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner’s work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation “LOLER”. The result was found Satisfactory at the time of Inspection and considered Safe for Lifting