






## LIFTING ACCESSORIES OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

<b>Client:</b>	DAQING DRILLING COMPANY	<b>Certificate no:</b>	QC-B-05-25-0263-10
<b>Location:</b>	DQ RIG 022	<b>Job Order No:</b>	QC-B-05-25-0263
<b>Date of Examination:</b>	13-MaY-2025	<b>Next Inspection Due:</b>	12-NOV-2025
<b>Last Inspection</b>		<b>Last Proof Load Test Date</b>	
01- JAN - 2025		By Manufacture	

IDENTIFICATION NO	DESCRIPTION	QTY	SWL
30 17 DF1 25	<p><u>Dee Shackles</u></p> <p>Size : 5/8" Grade : 6</p> <p>Manufacture: DY</p> <p>Location: Security Tower 3#</p> 	04	3.25 TON
<b>Applicable Reference Standard:</b>	BS EN 13889 / US FED SPEC RR-C-27 1 D		
* Is this the first examination after installation or assembly at a new site or location?	YES	NO	√
	Was the examination carried out?		
* If the answer to the above question is YES has the equipment been installed correctly?	YES	NO	
	* Within an interval of 6 months?		YES √ NO
* Within an interval of 12 months?		YES NO √	
* By an examination scheme?		YES √ NO	
* After the occurrence of exceptional circumstances?		YES NO √	
Identification Of Any Part Found To Have A Defect Which Is Or Could Become A Danger To Persons And A Description Of The Defect: <b>None</b>			
Is The Above A Defect Which Is Of Immediate Danger To Persons		YES	NO √
Is The Above A Defect Which Is Not Yet But Could Become A Danger To Persons: (If YES State The Date By When)		NO √ YES	By:
Particulars Of Any Repair, Renewal, Or Alteration Required To Remedy The Defect Identified Above: <b>None</b>			
<b>** Visual And Dimension Check was Carried Out.</b>			
Is This Equipment Safe To Operate?		Yes Accept	NO Reject
		√	

<b>LEEA &amp; ASNT Level II Inspector Name:</b>	<b>SIGNATURE:</b>	<b>Authenticating This Report:</b>	<b>SIGNATURE:</b>
Khaled Mahmoud		Mohammed Abdullah	


**THIS IS TO CERTIFY THAT:** a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting





## LIFTING ACCESSORIES OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

<b>Client:</b>	DAQING DRILLING COMPANY	<b>Certificate no:</b>	QC-B-05-25-0263-11
<b>Location:</b>	DQ RIG 022	<b>Job Order No:</b>	QC-B-05-25-0263
<b>Date of Examination:</b>	13-May-2025	<b>Next Inspection Due:</b>	12-NOV-2025
<b>Last Inspection</b>		<b>Last Proof Load Test Date</b>	
01- JAN - 2025		By Manufacture	

IDENTIFICATION NO	DESCRIPTION	QTY	SWL
D7P X4F PM6 38	<p><b>Dee Shackles</b></p> <p>Size : 5/8" Grade : 6</p> <p>Manufacture: DY</p> <p>Location: Security Tower 4#</p> 	04	3.25 TON
<b>Applicable Reference Standard:</b>	BS EN 13889 / US FED SPEC RR-C-27 1 D		
* Is this the first examination after installation or assembly at a new site or location?	YES	NO	√
	Was the examination carried out?		
* If the answer to the above question is YES has the equipment been installed correctly?	YES	NO	
	* Within an interval of 6 months?		YES √ NO
* Within an interval of 12 months?		YES NO √	
* By an examination scheme?		YES √ NO	
* After the occurrence of exceptional circumstances?		YES NO √	
Identification Of Any Part Found To Have A Defect Which Is Or Could Become A Danger To Persons And A Description Of The Defect: <b>None</b>			
Is The Above A Defect Which Is Of Immediate Danger To Persons		YES	NO √
Is The Above A Defect Which Is Not Yet But Could Become A Danger To Persons: (If YES State The Date By When)		NO √ YES	By:
Particulars Of Any Repair, Renewal, Or Alteration Required To Remedy The Defect Identified Above: <b>None</b>			
<b>** Visual And Dimension Check was Carried Out.</b>			
Is This Equipment Safe To Operate?		Yes Accept	NO Reject
		√	

<b>LEEA &amp; ASNT Level II Inspector Name:</b>	<b>SIGNATURE:</b>	<b>Authenticating This Report:</b>	<b>SIGNATURE:</b>
Khaled Mahmoud		Mohammed Abdullah	


**THIS IS TO CERTIFY THAT:** a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting





## LIFTING ACCESSORIES OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

<b>Client:</b>	DAQING DRILLING COMPANY	<b>Certificate no:</b>	QC-B-05-25-0263-12
<b>Location:</b>	DQ RIG 022	<b>Job Order No:</b>	QC-B-05-25-0263
<b>Date of Examination:</b>	13-May-2025	<b>Next Inspection Due:</b>	12-NOV-2025
<b>Last Inspection</b>		<b>Last Proof Load Test Date</b>	
01- JAN - 2025		By Manufacture	

IDENTIFICATION NO	DESCRIPTION	QTY	SWL
S2 D9M	<p><b>Dee Shackles</b></p> <p>Size : 5/8" Grade : 6</p> <p>Manufacture: DY</p> <p>Location: Security Tower 2#</p> 	02	3.25 TON
<b>Applicable Reference Standard:</b>	BS EN 13889 / US FED SPEC RR-C-27 1 D		
* Is this the first examination after installation or assembly at a new site or location?	YES	NO	√
	Was the examination carried out?		
* If the answer to the above question is YES has the equipment been installed correctly?	YES	NO	
	* Within an interval of 6 months?		YES
		* Within an interval of 12 months?	
		* By an examination scheme?	
		* After the occurrence of exceptional circumstances?	
Identification Of Any Part Found To Have A Defect Which Is Or Could Become A Danger To Persons And A Description Of The Defect: <b>None</b>			
Is The Above A Defect Which Is Of Immediate Danger To Persons		YES	NO
Is The Above A Defect Which Is Not Yet But Could Become A Danger To Persons: (If YES State The Date By When)		NO	YES
Particulars Of Any Repair, Renewal, Or Alteration Required To Remedy The Defect Identified Above: <b>None</b>			
<b>** Visual And Dimension Check was Carried Out.</b>			
Is This Equipment Safe To Operate?		Yes Accept	NO Reject

<b>LEEA &amp; ASNT Level II Inspector Name:</b>	<b>SIGNATURE:</b>	<b>Authenticating This Report:</b>	<b>SIGNATURE:</b>
Khaled Mahmoud		Mohammed Abdullah	


**THIS IS TO CERTIFY THAT:** a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting





## LIFTING ACCESSORIES OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

<b>Client:</b>	DAQING DRILLING COMPANY	<b>Certificate no:</b>	QC-B-05-25-0263-13
<b>Location:</b>	DQ RIG 022	<b>Job Order No:</b>	QC-B-05-25-0263
<b>Date of Examination:</b>	13-MaY-2025	<b>Next Inspection Due:</b>	12-NOV-2025
<b>Last Inspection</b>		<b>Last Proof Load Test Date</b>	
01- JAN - 2025		By Manufacture	

IDENTIFICATION NO	DESCRIPTION	QTY	SWL
A6 LC90	<p><b>Safety pin bow Shackles</b></p> <p>Size : 5/8" Grade : 6</p> <p>Manufacture: CROSBY</p> <p>Location: Security Tower 2#</p> 	02	3.25 TON
<b>Applicable Reference Standard:</b>	BS EN 13889 / US FED SPEC RR-C-27 1 D		
* Is this the first examination after installation or assembly at a new site or location?	YES	NO	√
	Was the examination carried out?		
* If the answer to the above question is YES has the equipment been installed correctly?	YES	NO	
	* Within an interval of 6 months?		
			YES
			NO
			√
			NO
			√
Identification Of Any Part Found To Have A Defect Which Is Or Could Become A Danger To Persons And A Description Of The Defect: <b>None</b>			
Is The Above A Defect Which Is Of Immediate Danger To Persons			YES
			NO
Is The Above A Defect Which Is Not Yet But Could Become A Danger To Persons: (If YES State The Date By When)			NO
			√
			YES
			By:
Particulars Of Any Repair, Renewal, Or Alteration Required To Remedy The Defect Identified Above: <b>None</b>			
<b>** Visual And Dimension Check was Carried Out.</b>			
Is This Equipment Safe To Operate?		Yes Accept	NO Reject
		√	

<b>LEEA &amp; ASNT Level II Inspector Name:</b>	<b>SIGNATURE:</b>	<b>Authenticating This Report:</b>	<b>SIGNATURE:</b>
Khaled Mahmoud		Mohammed Abdullah	


**THIS IS TO CERTIFY THAT:** a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting





### LIFTING ACCESSORIES OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

<b>Client:</b>	DAQING DRILLING COMPANY	<b>Certificate no:</b>	QC-B-05-25-0263-14
<b>Location:</b>	DQ RIG 022	<b>Job Order No:</b>	QC-B-05-25-0263
<b>Date of Examination:</b>	13-May-2025	<b>Next Inspection Due:</b>	12-NOV-2025
<b>Last Inspection</b>		<b>Last Proof Load Test Date</b>	
01- JAN - 2025		By Manufacture	

IDENTIFICATION NO	DESCRIPTION	QTY	SWL
444 AS7	<p><b>Dee Shackles</b></p> <p>Size : 5/8" Grade : 6</p> <p>Manufacture: DY</p> <p>Location: Security Tower 1#</p> 	02	3.25 TON
<b>Applicable Reference Standard:</b>	BS EN 13889 / US FED SPEC RR-C-27 1 D		
* Is this the first examination after installation or assembly at a new site or location?	YES	NO	√
	Was the examination carried out?		
* If the answer to the above question is YES has the equipment been installed correctly?	YES	NO	
	* Within an interval of 6 months?		YES √ NO
		* Within an interval of 12 months?	
		* By an examination scheme?	
		* After the occurrence of exceptional circumstances?	
Identification Of Any Part Found To Have A Defect Which Is Or Could Become A Danger To Persons And A Description Of The Defect: <b>None</b>			
Is The Above A Defect Which Is Of Immediate Danger To Persons		YES	NO √
Is The Above A Defect Which Is Not Yet But Could Become A Danger To Persons: (If YES State The Date By When)		NO √	YES
Particulars Of Any Repair, Renewal, Or Alteration Required To Remedy The Defect Identified Above: <b>None</b>			
<b>** Visual And Dimension Check was Carried Out.</b>			
Is This Equipment Safe To Operate?		Yes Accept	NO Reject

<b>LEEA &amp; ASNT Level II Inspector Name:</b>	<b>SIGNATURE:</b>	<b>Authenticating This Report:</b>	<b>SIGNATURE:</b>
Khaled Mahmoud		Mohammed Abdullah	


**THIS IS TO CERTIFY THAT:** a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting





## LIFTING ACCESSORIES OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

<b>Client:</b>	DAQING DRILLING COMPANY	<b>Certificate no:</b>	QC-B-05-25-0263-15
<b>Location:</b>	DQ RIG 022	<b>Job Order No:</b>	QC-B-05-25-0263
<b>Date of Examination:</b>	13-MaY-2025	<b>Next Inspection Due:</b>	12-NOV-2025
<b>Last Inspection</b>		<b>Last Proof Load Test Date</b>	
01- JAN - 2025		By Manufacture	

IDENTIFICATION NO	DESCRIPTION	QTY	SWL
44	<p><b>Safety pin bow Shackles</b></p> <p>Size : 5/8" Grade : 6</p> <p>Manufacture: DY</p> <p>Location: Security Tower 1#</p> 	01	3.25 TON
<b>Applicable Reference Standard:</b>	BS EN 13889 / US FED SPEC RR-C-27 1 D		
* Is this the first examination after installation or assembly at a new site or location?	YES	NO	√
	Was the examination carried out?		
* If the answer to the above question is YES has the equipment been installed correctly?	YES	NO	
	* Within an interval of 6 months?		YES √ NO
* Within an interval of 12 months?		YES	NO √
* By an examination scheme?		YES	NO √
* After the occurrence of exceptional circumstances?		YES	NO √
Identification Of Any Part Found To Have A Defect Which Is Or Could Become A Danger To Persons And A Description Of The Defect: <b>None</b>			
Is The Above A Defect Which Is Of Immediate Danger To Persons		YES	NO √
Is The Above A Defect Which Is Not Yet But Could Become A Danger To Persons: (If YES State The Date By When)		NO √	YES
Particulars Of Any Repair, Renewal, Or Alteration Required To Remedy The Defect Identified Above: <b>None</b>			
<b>** Visual And Dimension Check was Carried Out.</b>			
Is This Equipment Safe To Operate?		Yes Accept	NO Reject
		√	

<b>LEEA &amp; ASNT Level II Inspector Name:</b>	<b>SIGNATURE:</b>	<b>Authenticating This Report:</b>	<b>SIGNATURE:</b>
Khaled Mahmoud		Mohammed Abdullah	


**THIS IS TO CERTIFY THAT:** a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting





## LIFTING ACCESSORIES OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

<b>Client:</b>	DAQING DRILLING COMPANY	<b>Certificate no:</b>	QC-B-05-25-0263-16
<b>Location:</b>	DQ RIG 022	<b>Job Order No:</b>	QC-B-05-25-0263
<b>Date of Examination:</b>	13-May-2025	<b>Next Inspection Due:</b>	12-NOV-2025
<b>Last Inspection</b>		<b>Last Proof Load Test Date</b>	
01- JAN - 2025		By Manufacture	

IDENTIFICATION NO	DESCRIPTION	QTY	SWL
C15	<p><b>Safety pin bow Shackles</b></p> <p>Size : 5/8" Grade : 6</p> <p>Manufacture: CROSBY</p> <p>Location: Security Tower 1#</p> 	01	3.25 TON
<b>Applicable Reference Standard:</b>	BS EN 13889 / US FED SPEC RR-C-27 1 D		
* Is this the first examination after installation or assembly at a new site or location?	YES	NO	√
	Was the examination carried out?		
* If the answer to the above question is YES has the equipment been installed correctly?	YES	NO	
	* Within an interval of 6 months?		YES
		* Within an interval of 12 months?	
		* By an examination scheme?	
		* After the occurrence of exceptional circumstances?	
Identification Of Any Part Found To Have A Defect Which Is Or Could Become A Danger To Persons And A Description Of The Defect: <b>None</b>			
Is The Above A Defect Which Is Of Immediate Danger To Persons		YES	NO
Is The Above A Defect Which Is Not Yet But Could Become A Danger To Persons: (If YES State The Date By When)		NO	YES
Particulars Of Any Repair, Renewal, Or Alteration Required To Remedy The Defect Identified Above: <b>None</b>			
<b>** Visual And Dimension Check was Carried Out.</b>			
Is This Equipment Safe To Operate?		Yes Accept	NO Reject

<b>LEEA &amp; ASNT Level II Inspector Name:</b>	<b>SIGNATURE:</b>	<b>Authenticating This Report:</b>	<b>SIGNATURE:</b>
Khaled Mahmoud		Mohammed Abdullah	

**THIS IS TO CERTIFY THAT:** a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting