






LIFTING ACCESSORIES OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	DAQING DRILLING COMPANY	Certificate no:	QC-B-05-25-0331-3/05
Location:	DQ RIG 012	Job Order No:	QC-B-05-25-0331
Date of Examination:	09-June-2025	Next Inspection Due:	08-Dec-2025
Last Inspection		Last Proof Load Test Date	
New		By Manufacture	

IDENTIFICATION NO	DESCRIPTION	QTY	SWL/CAPACITY
B6483	<p>Single Leg Wire Rope Sling.</p> <p>Dim : 19 MM (Dia) X 120 M (L)</p> <p>IWRC, Mechanically Spliced With Aluminum Ferrule Hard X Plain.</p> <p>Safety Factor: 5:1</p> <p>Location : Air Winch Wire Rope</p> 	01	27.1 MT
Applicable Reference Standard:	BS EN 13414-1:2003+A2:2008		
* Is this the first examination after installation or assembly at a new site or location?	Was the examination carried out?		
	YES	NO	√
* If the answer to the above question is YES has the equipment been installed correctly?	* Within an interval of 6 months?		
	YES	NO	√
	* Within an interval of 12 months?		
	YES	NO	√
	* By an examination scheme?		
	YES	NO	√
	* After the occurrence of exceptional circumstances?		
	YES	NO	√
Identification Of Any Part Found To Have A Defect Which Is Or Could Become A Danger To Persons And A Description Of The Defect: None			
Is The Above A Defect Which Is Of Immediate Danger To Persons			YES NO √
Is The Above A Defect Which Is Not Yet But Could Become A Danger To Persons: (If YES State The Date By When)			NO √ YES By:
Particulars Of Any Repair, Renewal, Or Alteration Required To Remedy The Defect Identified Above: None			
** Visual And Dimension Check was Carried Out.			
Is This Equipment Safe To Operate?		Yes Accept	NO Reject

LEE & ASNT Level II Inspector Name:	SIGNATURE:	Authenticating This Report:	SIGNATURE:
Khaled Mahmoud		Mohammed Abdullah	


THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner’s work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation “LOLER”. The result was found Satisfactory at the time of Inspection and considered Safe for Lifting





LIFTING ACCESSORIES OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	DAQING DRILLING COMPANY	Certificate no:	QC-B-05-25-0331-3/06
Location:	DQ RIG 012	Job Order No:	QC-B-05-25-0331
Date of Examination:	09-June-2025	Next Inspection Due:	08-Dec-2025
Last Inspection		Last Proof Load Test Date	
New		By Manufacture	

IDENTIFICATION NO	DESCRIPTION	QTY	MBL			
B2196	<p>Single Leg Wire Rope Sling.</p> <p>Dim : 19 MM (Dia) X 120 M (L)</p> <p>IWRC, Mechanically Spliced With Aluminum Ferrule Hard X Plain.</p> <p>Safety Factor: 5:1</p> <p>Location : Air Winch Wire Rope</p> 	01	253 KN			
Applicable Reference Standard:	BS EN 13414-1:2003+A2:2008					
* Is this the first examination after installation or assembly at a new site or location?	YES	NO	√			
	Was the examination carried out?					
* If the answer to the above question is YES has the equipment been installed correctly?	YES	NO	√			
	* Within an interval of 6 months?					
			YES	NO	√	
			YES	NO	√	
			YES	NO	√	
			YES	NO	√	
Identification Of Any Part Found To Have A Defect Which Is Or Could Become A Danger To Persons And A Description Of The Defect: None						
Is The Above A Defect Which Is Of Immediate Danger To Persons				YES	NO	√
Is The Above A Defect Which Is Not Yet But Could Become A Danger To Persons: (If YES State The Date By When)				NO	√	YES
Particulars Of Any Repair, Renewal, Or Alteration Required To Remedy The Defect Identified Above: None						
** Visual And Dimension Check was Carried Out.						
Is This Equipment Safe To Operate?		Yes Accept	√	NO Reject		

LEE & ASNT Level II Inspector Name:	SIGNATURE:	Authenticating This Report:	SIGNATURE:
Khaled Mahmoud		Mohammed Abdullah	

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting