

**AI TAKAMUL COMPANY FOR ENGINEERING TESTS
AND PROFESSIONAL SAFETY LIMITED**

Basra, North Rumaila, Quality Control Yard - Iraq

Tel: +9647810009138 / +9647834964657

Email: OP@qualitycontrol-iraq.com / hany.akafi@qualitycontrol-iraq.com



CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Date of Examination:	08/06/2025	Date of Report:	08/06/2025	Certificate No:	QC-25/-WPS-3112-06B
Client Name:	HALLIBURTON	Location:	WPS	Job Number:	8062025

Serial Number:	QTY	Description	SWL	Date of manufacture if known:	Date of last thorough examination
GL69076/21	01	<p>SINGLE LEG WIRE ROPE SLING DIM: 5.5 M (L) X 13 MM (DIA) MANUFACTURE: LIFTEK FOS: 5:1 IWRC, MECHANICALLY SPLICED WITH ALUMINUM FERRULE HARD EYE BOTH END</p>	2 T	N/A	31/12/2024

Reference Standard: BS EN 13414-1/ HAL DOC: ST-GL-HAL-HSE-0420

Is this the first examination after Installation or assembly at a new site or location?	YES	NO	✓	Was the examination carried out: Within an interval of 6 months?	YES	✓	NO	
					Was the examination carried out: Within an interval of 12 months?	YES		NO
If the answer to the above question is YES has the equipment been installed correctly?	YES	NO		In accordance with an examination scheme? After the occurrence of exceptional circumstances?	YES	✓	NO	
					YES		NO	✓

Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none state NONE) **NONE**

Is the above a defect which is of immediate danger to persons: YES NO

Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when) N/A

Particulars of any repair, renewal or alteration required to remedy the defect identified above:


Particulars of any tests carried out as part of the examination: (If none state NONE)

The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory

IS THIS EQUIPMENT SAFE TO OPERATE? YES NO

Name of Inspector:	Name of person authenticating this report:	Client Signature & Stamp:	
ASHRAF ELSAID	MOHAMED ABDALLAH	ALI Talib HB48903 Date: 09-06-2025 Signature Haliburton	
Date of Next Through Examination:	07/12/2025		

REV: 01 Dated: 20 June 2022



THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of inspection and considered Safe for Lifting.

