

**AI TAKAMUL COMPANY FOR ENGINEERING TESTS  
AND PROFESSIONAL SAFETY LIMITED**

Basra, North Rumaila, Quality Control Yard - Iraq

Tel: +9647834966105 / +9647834964657

Email: ashraf.said@qualitycontrol-iraq.com / hany.akafi@qualitycontrol-iraq.com



## Certificate of visual and thorough examination

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

<b>Date of Examination:</b>	10-July-2025	<b>Date of Report:</b>	10-July-2025	<b>Certificate No:</b>	QC-25-07-HPS-061
<b>Client Name:</b>	HALLIBURTON	<b>Location:</b>	HPS YARD	<b>Job Number:</b>	10072025
<b>Serial Number:</b>	<b>QTY</b>	<b>Description</b>	<b>SWL</b>	<b>Date of manufacture if known:</b>	<b>Date of last thorough examination</b>
82459-5/24	01	<p style="text-align: center;"><b>SAFETY PIN BOW SHACKLE</b></p> <p>Manufacture: TOYOLIFT</p> <p>SIZE: 1"</p> <p>Grade: 6</p> <p>FOS: 6:1</p>	8.5 T	N/A	23-May-2024
<b>Reference Standard:</b>		BS EN 13889 / HAL DOC: WM-GL-HAL-HSE-0420F & WM-GL-HAL-HSE-0420C REV 1			
Is this the first examination after Installation or assembly at a new site or location?		<input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> ✓	Was the examination carried out: Within an interval of 6 months?		<input type="checkbox"/> YES <input checked="" type="checkbox"/> ✓ <input type="checkbox"/> NO <input type="checkbox"/> ✓
			With an interval of 12 months?		<input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> ✓
If the answer to the above question is YES has the equipment been installed correctly?		<input type="checkbox"/> YES <input type="checkbox"/> NO <input type="checkbox"/> ✓	In accordance with an examination scheme? After the occurrence of exceptional circumstances?		<input type="checkbox"/> YES <input checked="" type="checkbox"/> ✓ <input type="checkbox"/> NO <input type="checkbox"/> ✓
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none state NONE) <b>NONE</b>					
Is the above a defect which is of immediate danger to persons:					<input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> ✓
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)			N/A		
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
Particulars of any tests carried out as part of the examination: (If none state NONE)					
The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory					
<b>IS THIS EQUIPMENT SAFE TO OPERATE?</b>					<input type="checkbox"/> YES <input checked="" type="checkbox"/> ✓ <input type="checkbox"/> NO <input type="checkbox"/> ✓
<b>Name of Inspector:</b>	<b>Name of person authenticating this report:</b>		<b>Signature &amp; Stamp:</b>		
ASHRAF ELSAID	MUHAMMAD ABDULLAH				
<b>Date of Next Thorough Examination:</b>	09-Jan-2026				

REV: 01 Dated: 20 June 2022

**THIS IS TO CERTIFY THAT;** a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.

