

CERTIFICATE OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

CLIENT:	SLB Basra	CERTIFICATE NO:	QC-SLB-25154-32	QR
LOCATION:	SLB BASA			
EXAMINATION DATE:	20-Jun-2025	JOB NO:	QC-SLB-25154	
LAST INSPECTION	NEXT INSPECTION DATE		LAST PROOF LOAD TEST DATE	
N/A	19-Dec-2025		AFTER ANY REPAIR OR MODIFICATION	

Serial Number:	QTY	Description:	SWL	
A5434-1/09	01	<u>DST UNIT (Offshore Container)</u> FULLY WELDED STEEL CONSTRUCTION WITH FOUR TOP-MOUNTED LIFTING POINTS. Dimension: 6.0 m (L) X 2.45 m (W) X 2.65 m (H) Tare weight: 6600 KG Gross weight: 13000 KG	6400 KG	
Reference Standard:		DNV 2.7-1		
Pad Eyes Dimension:		Thickness: 38 mm	Pin Hole: 30 mm	Length: 200 mm
			Height: 115 mm	SWL 8 Ton

Is this the first examination after Installation or assembly at a new site or location?	YES	NO	✓	Was the examination carried out? Within an interval of 6 months? With an interval of 12 months? In accordance with an examination scheme? After the occurrence of exceptional circumstances?	YES	✓	NO	✓
If the answer to the above question is YES has the equipment been installed correctly?	YES	NO			YES	✓	NO	✓
	N/A					YES		NO

Identify any part found to have a defect, which is or could not become a danger to persons, and describe the defect. **NONE**

Is the above a defect, which is of immediate danger to persons? YES ☐ NO ☒

Is the above a defect, which is not yet but could become a danger to persons? YES by: _____

Particulars of any repair, renewal, or alteration required to remedy the defect identified above: _____

Particulars of any tests carried out as part of the examination: **NONE**

** The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory

** MPI was carried out on the pad eyes Welding Areas and found satisfactory, **Check MPI Certificate attached.**

IS THIS EQUIPMENT SAFE TO OPERATE? YES ☒ NO ☐

ASNT LEVEL II INSPECTOR NAME:	Signature & Stamp:	SUPERVISOR:	Signature & Stamp:
Mohamad Abdullah LEEAA Registered Technician		ASHRAF EL SAAD LEEAA Registered Technician	

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.