



## Visual & Magnetic Particles Examination Report

Client:	Hong Hua Oil& Gas Engineering Services Ltd	Certificate no:	QC-B-06-25-0363-01
Location:	Rig: HH08 / RU-674	Job Order No:	QC-B-06-25-0363
Date of Examination:	13-06-2025	Next Inspection Due:	12-12-2025
Serial Number	Description of the examined equipment	Result	
V1 & V2	Catwalk Ramp to V-Door Connection Points	Accept	



### NDT Equipment Details

Standard	ASTM E 709	Viewing Condition:	Colored Media	Method	WET
Yoke	Permanent	Serial No:	PY-09	Due Date	11. NOV.2025
White Contrast	WCP-2	Batch No:	008A009	Due Date	April.2026
Black Ink	7HF	Batch No:	008A103	Due Date	Jun.2026


### NDT procedure

Visual and MPI were carried out for the above description and found free of surface defects at the time of inspection

Identification of any part found to have a defect and a description of the defect: None

Particulars of any repair, renewal, or alteration required to remedy the defect identified above:

None

LEEA & ASNT Level II Inspector Name:	Signature:	Authenticating This Report:	Signature:
Mohamed Magdy		Mohamed Abdulla	