




Lifting Accessories of Visual and Thorough Examination

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	AMJAAD AL ASEMA CO,	Certificate no:	QC-B-06-25-0379/01
Location:	Quality Control Yard	Job Order No:	QC-B-06-25-0379
Date of Examination:	22-June-2025	Next Inspection Due:	21-Dec-2025
Last Inspection		Last Proof Load Test Date	
N/A		By Manufacture	

IDENTIFICATION NO	DESCRIPTION	QTY	SWL
R6838 R6848 R6850 R6841	Safety pin bow Shackles Size: 1'' Grade: 6 Manufacturer: Bash-P Safety Factor 6:1	04	8.5 ton
Reference Standard:	BS EN 13889		



Is this the first examination after Installation or assembly at a new site or location?	YES		NO	v	Was the examination carried out: Within an interval of 6 months?	YES	v	NO	
If the answer to the above question is YES has the equipment been installed correctly?	YES		NO		With an interval of 12 months?	YES		NO	v
					By an examination scheme?	YES	v	NO	
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none State NONE) NONE					After the occurrence of exceptional circumstances?	YES		NO	v
Is the above a defect which is of immediate danger to persons:					YES		NO	v	
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)					N/A				
Particulars of any repair, renewal, or alteration required to remedy the defect identified above:									
Particulars of any tests carried out as part of the examination: (If none state NONE)									
The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory									
IS THIS EQUIPMENT SAFE TO OPERATE?					YES	v	NO		

LEEA & ASNT Level II Inspector Name:	Signature:	Authenticating This Report:	Signature:
Mohamed Abdulla		Ashraf ElSaid	

THIS IS TO CERTIFY THAT: a competent person did attend the owner mentioner's work location on the date shown above and the Equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.




Lifting Accessories of Visual and Thorough Examination

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	AMJAAD AL ASEMA CO,	Certificate no:	QC-B-06-25-0379/02
Location:	Quality Control Yard	Job Order No:	QC-B-06-25-0379
Date of Examination:	22-June-2025	Next Inspection Due:	21-Dec-2025
Last Inspection		Last Proof Load Test Date	
N/A		By Manufacture	

IDENTIFICATION NO	DESCRIPTION	QTY	SWL
R6839 R6849 R6851 R6840	Safety pin bow Shackles Size: 1'' Grade: 6 Manufacturer: Bash-P Safety Factor 6:1	04	8.5 ton
Reference Standard:	BS EN 13889		



Is this the first examination after Installation or assembly at a new site or location?	YES		NO	v	Was the examination carried out: Within an interval of 6 months? With an interval of 12 months? By an examination scheme? After the occurrence of exceptional circumstances?	YES	v	NO			
						YES		NO	v		
If the answer to the above question is YES has the equipment been installed correctly?	YES		NO			YES	v	NO			
						YES		NO	v		
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none State NONE) NONE											
Is the above a defect which is of immediate danger to persons:								YES		NO	v
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)								N/A			
Particulars of any repair, renewal, or alteration required to remedy the defect identified above:											
Particulars of any tests carried out as part of the examination: (If none state NONE)											
The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory											
IS THIS EQUIPMENT SAFE TO OPERATE?								YES	v	NO	

LEEA & ASNT Level II Inspector Name:	Signature:	Authenticating This Report:	Signature:
Mohamed Abdulla		Ashraf EISaid	


THIS IS TO CERTIFY THAT: a competent person did attend the owner mentioner's work location on the date shown above and the Equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



Lifting Accessories of Visual and Thorough Examination

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	AMJAAD AL ASEMA CO,	Certificate no:	QC-B-06-25-0379/03
Location:	Quality Control Yard	Job Order No:	QC-B-06-25-0379
Date of Examination:	22-June-2025	Next Inspection Due:	21-Dec-2025
Last Inspection		Last Proof Load Test Date	
N/A		By Manufacture	

IDENTIFICATION NO	DESCRIPTION	QTY	SWL
YZH ZH11 AC8 AC10 5660	Safety pin bow Shackles Size: 1'' Grade: 6 Manufacturer: Crosby Safety Factor 6:1	05	8.5 ton
			
Reference Standard:	BS EN 13889		

Is this the first examination after Installation or assembly at a new site or location?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	Was the examination carried out:	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>		
					Within an interval of 6 months?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>		
					With an interval of 12 months?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>		
If the answer to the above question is YES has the equipment been installed correctly?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	By an examination scheme?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>		
					After the occurrence of exceptional circumstances?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>		
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none State NONE) NONE											
Is the above a defect which is of immediate danger to persons:								YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)								N/A			
Particulars of any repair, renewal, or alteration required to remedy the defect identified above:											
Particulars of any tests carried out as part of the examination: (If none state NONE)											
The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory											
IS THIS EQUIPMENT SAFE TO OPERATE?								YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>

LEEA & ASNT Level II Inspector Name:	signature:	Authenticating This Report:	Signature:
Mohamed Abdulla		Ashraf ElSaid	

THIS IS TO CERTIFY THAT: a competent person did attend the owner mentioner's work location on the date shown above and the Equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.




Lifting Accessories of Visual and Thorough Examination

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	AMJAAD AL ASEMA CO,	Certificate no:	QC-B-06-25-0379/04
Location:	Quality Control Yard	Job Order No:	QC-B-06-25-0379
Date of Examination:	22-June-2025	Next Inspection Due:	21-Dec-2025
Last Inspection		Last Proof Load Test Date	
N/A		By Manufacture	

IDENTIFICATION NO	DESCRIPTION	QTY	SWL
A4328 A5373 A6463	Safety pin bow Shackles Size: 1'' Grade: 6 Manufacturer: Toyo Lift Safety Factor 6:1	03	8.5 ton
Reference Standard:	BS EN 13889		



Is this the first examination after Installation or assembly at a new site or location?	YES		NO	v	Was the examination carried out: Within an interval of 6 months? With an interval of 12 months? By an examination scheme? After the occurrence of exceptional circumstances?	YES	v	NO	
						YES		NO	v
If the answer to the above question is YES has the equipment been installed correctly?	YES		NO			YES	v	NO	
						YES		NO	v

Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none State NONE) **NONE**

Is the above a defect which is of immediate danger to persons: YES NO

Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when) N/A

Particulars of any repair, renewal, or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: (If none state NONE)

The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory

IS THIS EQUIPMENT SAFE TO OPERATE? YES NO

LEEA & ASNT Level II Inspector Name:	Signature:	Authenticating This Report:	Signature:
Mohamed Abdulla		Ashraf ElSaid	

THIS IS TO CERTIFY THAT: a competent person did attend the owner mentioner's work location on the date shown above and the Equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.