




CERTIFICATE OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulation

Report No:	QC-B-06-25-0379-06	Job No:	QC-B-06-25-0379
Customer:	AMJAAD AL ASEMA CO, Iraq	Examination date:	22-June-2025
Location:	AL ASEMA BASE	Next Due date:	21-Dec-2025
Serial Number:	QTY	Description :	SWL at (0-45 °)
B 3693 B 3694 B 3695 B 3696	04	<p align="center"><u>TWO LEG WIRE ROPE SLINGE</u></p> <p>Const. 6X36, RHO, Galvanized Steel IWRC, Mechanically Spliced with Aluminum Ferrule C/W C/W mater link (inner dimension: 600mm x 200mm):</p> <p>Hard Eye X Soft Eye: Dim: 28 mm X 6 M FOS: 5:1 Location: Al Asema Sling Store</p> 	14 Ton
Reference Standard:		BS EN 13414-1+A2:2008	
Is This the First Examination After Installation or Assembly at a New Site or Location?	YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>	Was The Examination Carried out: Within an Interval of 6 Months?	YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>
		With an Interval of 12 Months?	YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>
If the answer to the above question is YES has the equipment been installed correctly?	YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>	In Accordance with an Examination Scheme? After the Occurrence of Exceptional Circumstances?	YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none State NONE) NONE			
Is the Above a Defect Which is of Immediate Danger to Persons:	YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>		
Is the Above an Affect Which is not yet but Could Become a Danger to Persons (If YES State the Date by When)	YES by:		
Particulars of any Repair, Renewal or Alteration Required to Remedy the Defect Identified Above:			
Particulars of any tests Carried out as Part of the Examination: (If none state NONE) The Items Were Inspected Visually and Dimensionally Where No Signs of Defects Were Observed at The Time of Inspection Found Satisfactory:			
Visual and Dimension Checks was Carried Out.	YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>		
IS THIS EQUIPMENT SAFE TO OPERATE?	YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>		

LEEA AND ASNT LEVEL II NAME:	Authenticating This Report:	Signature & Stamp:
Mohamed Abdulla LEEA Registered Technician	Ashraf El Said LEEA Registered Technician	

REV: 01 Dated: 20 June 2022





CERTIFICATE OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulation

Report No:	QC-B-06-25-0379-07	Job No:	QC-B-06-25-0379
Customer:	AMJAAD AL ASEMA CO, Iraq	Examination date:	22-June-2025
Location:	AL ASEMA BASE	Next Due date:	21-Dec-2025
Serial Number:	QTY	Description	SWL at (0-45 °)
B 1009 B 1010 B 1011 B 1012	04	<p style="text-align: center;"><u>TWO LEG WIRE ROPE SLINGE</u></p> Const. 6X36, RHO, Galvanized Steel IWRC, Mechanically Spliced with Aluminum Ferrule C/W mater link (inner dimension:270mm x 140mm): Hard Eye at Both Ends: Dim: 24 mm X 8 M FOS: 5:1 Location: Al Asema Sling Store	10.3 Ton
Reference Standard:		BS EN 13414-1+A2:2008	
Is This the First Examination After Installation or Assembly at a New Site or Location?	YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>	Was The Examination Carried out: Within an Interval of 6 Months? With an Interval of 12 Months? In Accordance with an Examination Scheme? After the Occurrence of Exceptional Circumstances?	YES <input checked="" type="checkbox"/> NO <input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>
If the answer to the above question is YES has the equipment been installed correctly?	YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>		
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none State NONE) NONE			
Is the Above a Defect Which is of Immediate Danger to Persons:		YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>	
Is the Above an Affect Which is not yet but Could Become a Danger to Persons (If YES State the Date by When)		YES by:	
Particulars of any Repair, Renewal or Alteration Required to Remedy the Defect Identified Above:			
Particulars of any tests Carried out as Part of the Examination: (If none state NONE) The Items Were Inspected Visually and Dimensionally Where No Signs of Defects Were Observed at The Time of Inspection Found Satisfactory:			
Visual and Dimension Checks was Carried Out.		YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>	
IS THIS EQUIPMENT SAFE TO OPERATE?		YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>	

LEEAA AND ASNT LEVEL II NAME:	Authenticating This Report:	Signature & Stamp:
Mohamed Abdulla LEEAA Registered Technician	Ashraf El Said LEEAA Registered Technician	

REV: 01 Dated: 20 June 2022





CERTIFICATE OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulation

Report No:	QC-B-06-25-0379-08	Job No:	QC-B-06-25-0379
Customer:	AMJAAD AL ASEMA CO, Iraq	Examination date:	22-June-2025
Location:	AL ASEMA BASE	Next Due date:	21-Dec-2025
Serial Number:	QTY	Description :	SWL at (0-45 °)
H 5641 H 5642 H 5644 H 5645	04	<p style="text-align: center;"><u>SINGLE LEG WIRE ROPE SLINGE</u></p> <p>Const. 6X36, RHO, Galvanized Steel IWRC, Mechanically Spliced with Aluminum Ferrule C/W mater link (inner dimension: 600mm x 200mm):</p> <p>Soft Eye at Both Ends:</p> <p>Dim: 38 mm X 6 M</p> <p>FOS: 5:1</p> <p>Location: Al Asema Sling Store</p>	18.5 Ton
Reference Standard:		BS EN 13414-1+A2:2008	
Is This the First Examination After Installation or Assembly at a New Site or Location?		Was The Examination Carried out:	
YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>		Within an Interval of 6 Months? YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>	
If the answer to the above question is YES has the equipment been installed correctly?		With an Interval of 12 Months? YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>	
YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>		In Accordance with an Examination Scheme? YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>	
		After the Occurrence of Exceptional Circumstances? YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>	
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none State NONE) NONE			
Is the Above a Defect Which is of Immediate Danger to Persons:		YES <input type="checkbox"/>	NO <input checked="" type="checkbox"/>
Is the Above an Affect Which is not yet but Could Become a Danger to Persons (If YES State the Date by When)		YES by: _____	
Particulars of any Repair, Renewal or Alteration Required to Remedy the Defect Identified Above:			
Particulars of any tests Carried out as Part of the Examination: (If none state NONE)			
The Items Were Inspected Visually and Dimensionally Where No Signs of Defects Were Observed at The Time of Inspection Found Satisfactory:			
Visual and Dimension Checks was Carried Out.		YES <input checked="" type="checkbox"/>	NO <input type="checkbox"/>
IS THIS EQUIPMENT SAFE TO OPERATE?		<input checked="" type="checkbox"/>	NO <input type="checkbox"/>

LEEA AND ASNT LEVEL II NAME:	Authenticating This Report:	Signature & Stamp:
Mohamed Abdulla LEEA Registered Technician	Ashraf El Said LEEA Registered Technician	


REV: 01 Dated: 20 June 2022





CERTIFICATE OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulation

Report No:	QC-B-06-25-0379-09	Job No:	QC-B-06-25-0379
Customer:	AMJAAD AL ASEMA CO, Iraq	Examination date:	22-June-2025
Location:	AL ASEMA BASE	Next Due date:	21-Dec-2025
Serial Number:	QTY	Description	SWL at (0-45 °)
04140259-01 04140259-02 04140259-07 04140259-08	04	<p style="text-align: center;"><u>SINGLE LEG WIRE ROPE SLINGE</u></p> <p>Const. 6X36, RHO, Galvanized Steel IWRC, Mechanically Spliced with Aluminum Ferrule C/W mater link (inner dimension: 600mm x 200mm):</p> <p>Soft Eye at Both Ends: Dim: 36 mm X 10 M FOS: 5:1 Location: Al Asema Sling Store</p> 	15 Ton
Reference Standard:	BS EN 13414-1+A2:2008		
Is This the First Examination After Installation or Assembly at a New Site or Location?	YES	NO	√
If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO
Was The Examination Carried out: Within an Interval of 6 Months? With an Interval of 12 Months? In Accordance with an Examination Scheme? After the Occurrence of Exceptional Circumstances?	YES	√	NO
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none State NONE) NONE			
Is the Above a Defect Which is of Immediate Danger to Persons:	YES	NO	√
Is the Above an Affect Which is not yet but Could Become a Danger to Persons (If YES State the Date by When)	YES by:		
Particulars of any Repair, Renewal or Alteration Required to Remedy the Defect Identified Above:			
Particulars of any tests Carried out as Part of the Examination: (If none state NONE) The Items Were Inspected Visually and Dimensionally Where No Signs of Defects Were Observed at The Time of Inspection Found Satisfactory:			
Visual and Dimension Checks was Carried Out.	YES	√	NO
IS THIS EQUIPMENT SAFE TO OPERATE?	YES	√	NO

LEEA AND ASNT LEVEL II NAME:	Authenticating This Report:	Signature & Stamp:
Mohamed Abdulla LEEA Registered Technician	Ashraf El Said LEEA Registered Technician	

REV: 01 Dated: 20 June 2022





CERTIFICATE OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulation

Report No:	QC-B-06-25-0379-10	Job No:	QC-B-06-25-0379
Customer:	AMJAAD AL ASEMA CO, Iraq	Examination date:	22-June-2025
Location:	AL ASEMA BASE	Next Due date:	21-Dec-2025
Serial Number:	QTY	Description	SWL at (0-45 °)
04140257-02 04140257-03 04140257-05 04140257-06	04	<p style="text-align: center;"><u>SINGLE LEG WIRE ROPE SLINGE</u></p> <p>Const. 6X36, RHO, Galvanized Steel IWRC, Mechanically Spliced with Aluminum Ferrule C/W mater link (inner dimension: 600mm x 200mm):</p> <p>Soft Eye at Both Ends:</p> <p>Dim: 36 mm X 6 M</p> <p>FOS: 5:1</p> <p>Location: Al Asema Sling Store</p>	15 Ton
Reference Standard:		BS EN 13414-1+A2:2008	
Is This the First Examination After Installation or Assembly at a New Site or Location?		Was The Examination Carried out:	
YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>		Within an Interval of 6 Months? YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>	
If the answer to the above question is YES has the equipment been installed correctly?		With an Interval of 12 Months? YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>	
YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>		In Accordance with an Examination Scheme? YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>	
		After the Occurrence of Exceptional Circumstances? YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>	
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none State NONE) NONE			
Is the Above a Defect Which is of Immediate Danger to Persons:		YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>	
Is the Above an Affect Which is not yet but Could Become a Danger to Persons (If YES State the Date by When)		YES by: _____	
Particulars of any Repair, Renewal or Alteration Required to Remedy the Defect Identified Above:			
Particulars of any tests Carried out as Part of the Examination: (If none state NONE)			
The Items Were Inspected Visually and Dimensionally Where No Signs of Defects Were Observed at The Time of Inspection Found Satisfactory:			
Visual and Dimension Checks was Carried Out.		YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>	
IS THIS EQUIPMENT SAFE TO OPERATE?		YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>	

LEE A AND ASNT LEVEL II NAME:	Authenticating This Report:	Signature & Stamp:
Mohamed Abdulla LEE A Registered Technician	Ashraf El Said LEE A Registered Technician	

REV: 01 Dated: 20 June 2022

