



LIFTING ACCESSORIES OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	AMJAAD AL-ASIMA COMPANY BASRA IRAQ	Certificate no:	QC-B-06-25-0379/11
Location:	QC-YARD	Job Order No:	QC-B-06-25-0379
Date of Examination:	27-JUNE-2025	Next Inspection Due:	26-DEC-2025
Last Inspection		Last Proof Load Test Date	
New		By Manufacture	

IDENTIFICATION NO	DESCRIPTION	QTY	SWL
3601-6T/6M-2098 3601-6T/6M-2071 3601-6T/6M-2068 3601-6T/6M-2107	<u>Flat 100% Polyester Webbing Sling.</u> Type : Eye X Eye Length : 6 M Colour : Brown Manufacturer : DAWSON Safety Factor : 7:1	04	Vertical 6000 kg Choker 4800 Kg Basket 12000 kg

Applicable Reference Standard:	BS EN 1492-1:2000+A1:2008								
* Is this the first examination after installation or assembly at a new site or location?	YES		NO	√	Was the examination carried out?				
					* Within an interval of 6 months?	YES	√	NO	
* If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO		* Within an interval of 12 months?	YES		NO	√
					* By an examination scheme?	YES	√	NO	
					* After the occurrence of exceptional circumstances?	YES		NO	√

Identification Of Any Part Found To Have A Defect Which Is Or Could Become A Danger To Persons And A Description Of The Defect: **None**

Is The Above A Defect Which Is Of Immediate Danger To Persons	YES		NO	√
Is The Above A Defect Which Is Not Yet But Could Become A Danger To Persons: (If YES State The Date By When)	NO	√	YES	By:

Particulars Of Any Repair, Renewal, Or Alteration Required To Remedy The Defect Identified Above: **None**

**** Visual And Dimension Check was Carried Out.**

Is This Equipment Safe To Operate?	Yes Accept	√	NO Reject
------------------------------------	------------	---	-----------

LEEA & ASNT Level II Inspector Name:	SIGNATURE:	Authenticating This Report:	SIGNATURE:
Mohammed Abdullah		Ashraf El said	

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.