


LIFTING ACCESSORIES CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

CLIENT:	SLB BASRA	CERTIFICATION NO:	QC-SLB-25185-01		
LOCATION:	SLICK LINE WORKSHOP				
EXAMINATION DATE:	15/Jul/2025		JOB NO:	QC-SLB-25185	
LAST INSPECTION		NEXT INSPECTION DATE		LAST PROOF LOAD TEST DATE	
21/Jan/2025		14/Jan/2026		BY MANUFACTURE	
IDENTIFICATION NO	DESCRIPTION			QTY	
NE3945A NE3945B NE3945C NE3945D NE3922	Safety pin bow Shackles SIZE: 1/2" Grade: 6 Manufacturer: Crosby Safety Factor: 5:1 			05	
				2 TON	
Applicable Reference Standard:	BS EN 13889 / US FED SPEC RR-C-27 1 D				
* Is this the first examination after installation or assembly at a new site or location?	Was the examination carried out?				
	YES	NO	√		
	* Within an interval of 6 months?				
* If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO		
	* Within an interval of 12 months?				
	* By an examination scheme?				
* After the occurrence of exceptional circumstances?					
Identification Of Any Part Found To Have A Defect Which Is Or Could Become A Danger To Persons And A Description Of The Defect: None					
Is The Above A Defect Which Is Of Immediate Danger To Persons				YES	NO
Is The Above A Defect Which Is Not Yet But Could Become A Danger To Persons: (If YES State The Date By When)				NO	YES
Particulars Of Any Repair, Renewal, Or Alteration Required To Remedy The Defect Identified Above: None					
** Visual And Dimension Check was Carried Out.					
Is This Equipment Safe To Operate?		Yes Accept	√	NO Reject	

INSPECTOR	SIGNATURE:	SUPERVISOR:	SIGNATURE:
Mohammad Abdullah		Ashraf Elsaad	

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.

