

# WITNESSING PRESSURE TEST Certificate

|                       |                                                         |                              |                 |
|-----------------------|---------------------------------------------------------|------------------------------|-----------------|
| <b>Client:</b>        | <b>SLB BASRA<br/>(Testing Services)</b>                 | <b>Report No:</b>            | QC-SLB-25184-01 |
| <b>Work Location:</b> | North Rumaila Base-Basra-Iraq                           | <b>Date Of Inspection:</b>   | 10/Jul/2025     |
| <b>Reference:</b>     | ASTM E B31.1 Manufacture<br>Recommended – SLB Procedure | <b>Next Inspection Date:</b> | 09/Jul/2026     |

|                               |                             |
|-------------------------------|-----------------------------|
| <b>Equipment Description:</b> | <b><u>TEXSTEAM PUMP</u></b> |
|-------------------------------|-----------------------------|

|                      |                                                                                                                                                                                     |                                                                                      |
|----------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------|
| <b>722312-01-001</b> | <p><b><u>DRIVEN INJECTORS</u></b></p> <ul style="list-style-type: none"> <li>- Visual inspection for outside and inside surface leak</li> <li>- Witnessing Pressure Test</li> </ul> |  |
|----------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------|

**Hydro test:** Test applied by SLB and found no drops or leaks during test period.

|                       |                    |                                  |           |
|-----------------------|--------------------|----------------------------------|-----------|
| <b>TEST PRESSURE:</b> | Buildup to 7000PSI | <b>MAXIMUM WORKING PRESSURE:</b> | 10000 PSI |
|-----------------------|--------------------|----------------------------------|-----------|

| Test Methods                | Non-Destructive Test | Pressure Test                |
|-----------------------------|----------------------|------------------------------|
|                             | UT W/T Meter         | Pressure recorder            |
| <b>Equipment used:</b>      | ----                 | <b>820954</b>                |
| <b>Calibration Date</b>     | ----                 | <b>Due date –02/Feb/2026</b> |
| <b>Applicable procedure</b> | ----                 | <b>WI/CT/0090</b>            |

**REMARKS/RECOMMENDATION: Pressure Test Against Valve for 5 Minutes**

**RESULT** THE ABOVE ITEM WAS TESTED AND FOUND TO BE ACCEPTED AT TIME OF TEST

|                   |                |                             |                    |
|-------------------|----------------|-----------------------------|--------------------|
| <b>SUPERVISOR</b> | <b>M-TAREK</b> | <b>Inspection Engineer:</b> | <b>Rami Salama</b> |
|-------------------|----------------|-----------------------------|--------------------|

