

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

CLIENT:	SLB Basra	CERTIFICATION NO:	QC-SLB-25190-01A	
LOCATION:	WIRE LINE WORKSHOP			
EXAMINATION DATE:	21/July/2025	JOB NO:	QC-SLB-25190	
LAST INSPECTION	NEXT INSPECTION DATE		LAST PROOF LOAD TEST DATE	
02/Jan/2025	20/Jan/2026		AFTER ANY REPAIR OR MODIFICATION	

Serial Number:	QTY	Description	SWL	
L690665-135	01	<u>MAIN FRAME</u> FULLY WELDED STEEL CONSTRUCTION WITH FOUR TOP-MOUNTED LIFTING POINTS. Dimension : 3.65 M(L) X 1.30 M (W) X 1.69 M (H) TARE WEIGHT: 1200 KGS MAX. GROSS WEIGHT: 4900 KGS	3700 KG	
Reference Standard:	BS EN ISO 10855 / DNV 2.7-1 SKID # 030			
Pad Eyes Dimension:	Thickness:	Pin Hole:	Length:	Height:
	30 mm	23 mm	50 mm	65 mm

Is this the first examination after Installation or assembly at a new site or location?					Was the examination carried out? Within an interval of 6 months? With an interval of 12 months? In accordance with an examination scheme? After the occurrence of exceptional circumstances?				
	YES		NO	✓		YES	✓	NO	
If the answer to the above question is YES has the equipment been installed correctly?						YES		NO	✓
	YES	✓	NO			YES	✓	NO	
	N/A					YES		NO	✓

Identification of any part found to have a defect, which is or could not become a danger to persons, and a description of the defect. NONE							
Is the above a defect, which is of immediate danger to persons?				YES		NO	✓
Is the above a defect, which is not yet but could become a danger to persons?				YES by:			
Particulars of any repair, renewal, or alteration required to remedy the defect identified above:							
Particulars of any tests carried out as part of the examination: NONE							
** The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory							
** MPI was carried out on the pad eyes Welding Areas and found satisfactory, Check MPI Certificate No :(.....) attached.							
IS THIS EQUIPMENT SAFE TO OPERATE?				YES	✓	NO	

INSPECTOR	SIGNATURE:	SUPERVISOR:	SIGNATURE:
Mohamed Abdallah		ASHRAF ALSAAD	

THIS IS TO CERTIFY THAT: a competent person did attend the above mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.

