



Al Takamul Company for Engineering Services
Quality Control – Iraq

LIFTING ACCESSORIES OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	SLB BASRA	Certificate no:	QC-SLB-25180-02
Location:	WIRE LINE WORKSHOP	Job Order No:	QC-SLB-25180
Date of Examination:	10/Jul/2025	Next Inspection Due:	09/Jan/2026
Last Inspection		Last Proof Load Test Date	
01/Jan/2025		BY MANUFACTURE	

IDENTIFICATION NO	DESCRIPTION		QTY	SWL
284740-29	<u>ROUND WEBBING SLING FOR LOGIN UNIT RIG UP</u> Material: Nylon Length: 4 ft Model: RCHPE40 Colour: Orange Safety Factor: 7:1		01	VERTICAL: 40000 LBS CHOKER: 32000 LBS BASKET: 80000 LBS
Applicable Reference Standard:		BS EN 1492-1:2000+A1:2008		
* Is this the first examination after installation or assembly at a new site or location?	Was the examination carried out?			
	YES	NO	YES	NO
* If the answer to the above question is YES has the equipment been installed correctly?	* Within an interval of 6 months?			
	YES	NO	YES	NO
Identification Of Any Part Found To Have A Defect Which Is Or Could Become A Danger To Persons And A Description Of The Defect: None				
Is The Above A Defect Which Is Of Immediate Danger To Persons		YES	NO	
Is The Above A Defect Which Is Not Yet But Could Become A Danger To Persons: (If YES State The Date By When)		NO	YES	By:
Particulars Of Any Repair, Renewal, Or Alteration Required To Remedy The Defect Identified Above: None				
** Visual And Dimension Check was Carried Out.				
Is This Equipment Safe To Operate?		Yes Accept	NO Reject	

LEEA & ASNT Level II Inspector Name:	SIGNATURE:	Authenticating This Report:	SIGNATURE:
Mohammed Abdullah		Ashraf Alsaad	

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.

