

LIFTING ACCESSORIES CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

CLIENT:	SLB BASRA	CERTIFICATE NO:	QC-SLB-25179-02	
LOCATION:	SLICKLINE WORKSHOP			
EXAMINATION DATE:	08/Jul/2025	JOB NO:	QC-SLB-25179	
LAST INSPECTION		NEXT INSPECTION DATE		PROOF LOAD TEST DATE
12/Jan/2025		07/Jan/2026		By Manufacture
IDENTIFICATION NO	DESCRIPTION			QTY
NV1920	<u>Single Leg Wire Rope Sling.</u> Diameter: 13 mm Length: 7 ft IWRC, MECHANICALLY SPLICED WITH ALUMINUM FERRULE HARD EYE ON BOTH ENDS. SAFETY FACTOR 5:1 			01
SWL		2.1 TON		
Applicable Reference Standard:		BS EN 13414-1:2003+A2:2008 UNIT #03		
* Is this the first examination after installation or assembly at a new site or location?		Was the examination carried out?		
		YES	NO	✓
* If the answer to the above question is YES has the equipment been installed correctly?		* Within an interval of 6 months?		
		YES	NO	✓
* By an examination scheme?		YES		
		YES	NO	✓
* After the occurrence of exceptional circumstances?		YES		
		YES	NO	✓
Identification Of Any Part Found To Have A Defect Which Is Or Could Become A Danger To Persons And A Description Of The Defect: None				
Is The Above A Defect Which Is Of Immediate Danger To Persons		YES	NO	✓
Is The Above A Defect Which Is Not Yet But Could Become A Danger To Persons: (If YES State The Date By When)		NO	✓	YES
Particulars Of Any Repair, Renewal, Or Alteration Required To Remedy The Defect Identified Above: None				
** Visual And Dimension Check was Carried Out.				
Is This Equipment Safe To Operate?		Yes Accept	✓	NO Reject

INSPECTOR	SIGNATURE:	SUPERVISOR:	SIGNATURE:
Mohammad Abdullah		Ashraf Elsaad	

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.

