


CERTIFICATE OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

CLIENT:	SLB Basra	CERTIFICATION NO:	QC-SLB-25190-03a
LOCATION:	WIRE LINE WORKSHOP		
EXAMINATION DATE:	22/July/2025	JOB NO:	QC-SLB-25190
LAST INSPECTION	NEXT INSPECTION DATE		LAST PROOF LOAD TEST DATE
02/Jan/2025	21/Jan/2026		AFTER ANY REPAIR OR MODIFICATION

Serial Number:	QTY	Description	SWL
L-690465-225	01	<u>BOP FRAME</u> Dim : 1.40 M(L) X 0.43 M (W) X 0.87 M (H) FULLY WELDED STEEL CONSTRUCTION WITH FOUR TOP MOUNTED LIFTING POINTS TARE WEIGHT : 125 kg MAX. GROSS WEIGHT : 815 kg	690 kg

Reference Standard:	BS 7072	SKID # 030		
Pad Eyes Dimension:	Thickness:	Pin Hole:	Length:	Height:
	10mm	19mm	50mm	90mm



Is this the first examination after Installation or assembly at a new site or location?	YES	NO	✓	Was the examination carried out? Within an interval of 6 months?	YES	✓	NO	
				With an interval of 12 months?	YES		NO	✓
If the answer to the above question is YES has the equipment been installed correctly?	YES	✓	NO	In accordance with an examination scheme?	YES	✓	NO	
				After the occurrence of exceptional circumstances?	YES		NO	✓

Identification of any part found to have a defect, which is or could not become a danger to persons, and a description of the defect. NONE					
Is the above a defect, which is of immediate danger to persons?			YES	NO	✓
Is the above a defect, which is not yet but could become a danger to persons?			YES by:		
Particulars of any repair, renewal, or alteration required to remedy the defect identified above:					
Particulars of any tests carried out as part of the examination: NONE					
** The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory					
** MPI was carried out on the pad eyes Welding Areas and found satisfactory, Check MPI Certificate No :(.....) attached.					
IS THIS EQUIPMENT SAFE TO OPERATE?			YES	✓	NO

INSPECTOR	SIGNATURE:	SUPERVISOR:	SIGNATURE:
Mohamed Abdallah		ASHRAF ALSAAD	

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.

