



Al Takamul Company for Engineering Services
Quality Control – Iraq

LIFTING ACCESSORIES OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	SLB BASRA	Certificate no:	QC-SLB-25180-06
Location:	WIRELINE WORKSHOP	Job Order No:	QC-SLB-25180
Date of Examination:	10/Jul/2025	Next Inspection Due:	09/Jan/2026
Last Inspection		Last Proof Load Test Date	
N/A		BY MANUFACTURE	

IDENTIFICATION NO	DESCRIPTION						QTY	SWL	
1562 1559	17” (Wire line) SHAVE WHEEL Manufacture Date:14-12-20107 Part Number: H713155 Line size:5/16” Max Line Load: 5000 lbs. Pinhole Diameter: 40 mm  <td>02</td> <td>10,000 lbs.</td>						02	10,000 lbs.	
Applicable Reference Standard:	BS EN 13155								
* Is this the first examination after installation or assembly at a new site or location?	YES			NO			Was the examination carried out?		
							* Within an interval of 6 months?		
							YES		
* If the answer to the above question is YES has the equipment been installed correctly?	YES			NO			* Within an interval of 12 months?		
							YES		
							NO		
	YES			NO			* By an examination scheme?		
							YES		
							NO		
						* After the occurrence of exceptional circumstances?			
						YES			
						NO			
Identification Of Any Part Found To Have A Defect Which Is Or Could Become A Danger To Persons And A Description Of The Defect: None									
Is The Above A Defect Which Is Of Immediate Danger To Persons						YES		NO	
Is The Above A Defect Which Is Not Yet But Could Become A Danger To Persons: (If YES State The Date By When)						NO		By:	
Particulars Of Any Repair, Renewal, Or Alteration Required To Remedy The Defect Identified Above: None									
** Visual And Dimension Check was Carried Out.									
Is This Equipment Safe To Operate?				Yes Accept		NO Reject			

LEEA & ASNT Level II Inspector Name:	SIGNATURE:	Authenticating This Report:	SIGNATURE:
Mohammed Abdullah		Ashraf Elsaad	

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.