


LIFTING ACCESSORIES CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

CLIENT:	SLB BASRA	CERTIFICATION NO:	QC-SLB-25185-07	
LOCATION:	SLICK LINE WORKSHOP			
EXAMINATION DATE:	15/Jul/2025		JOB NO:	QC-SLB-25185
LAST INSPECTION		NEXT INSPECTION DATE		LAST PROOF LOAD TEST DATE
21/Jan/2025		14/Jan/2026		BY MANUFACTURE
IDENTIFICATION NO	DESCRIPTION			QTY
NE3741	Master Link Manufacture: GPT Model: 25B6 Dia: 25 mm Dim: 190 mm X 100 mm Safety Factor: 4:1			01
				
SWL		10 TON		
Applicable Reference Standard:	BS EN 1677-4			
* Is this the first examination after installation or assembly at a new site or location?	YES		NO	
			✓	
* If the answer to the above question is YES has the equipment been installed correctly?	YES		NO	
	✓			
Was the examination carried out?				
* Within an interval of 6 months?		YES		NO
		✓		
* Within an interval of 12 months?		YES		NO
				✓
* By an examination scheme?		YES		NO
		✓		
* After the occurrence of exceptional circumstances?		YES		NO
				✓
Identification Of Any Part Found To Have A Defect Which Is Or Could Become A Danger To Persons And A Description Of The Defect: None				
Is The Above A Defect Which Is Of Immediate Danger To Persons			YES	NO
				✓
Is The Above A Defect Which Is Not Yet But Could Become A Danger To Persons: (If YES State The Date By When)			NO	YES
			✓	By:
Particulars Of Any Repair, Renewal, Or Alteration Required To Remedy The Defect Identified Above: None				
** Visual And Dimension Check was Carried Out.				
Is This Equipment Safe To Operate?		Yes Accept	✓	NO Reject

INSPECTOR	SIGNATURE:	SUPERVISOR:	SIGNATURE:
Mohammad Abdullah		Ashraf Elsaad	

THIS IS TO CERTIFY THAT; a competent person has examined the above-mentioned owner's work location on the date shown above and the equipment described in this report was found to comply with the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found to be satisfactory and the equipment is safe for lifting.

