

LIFTING ACCESSORIES CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

CLIENT:	SLB BASRA	CERTIFICATE NO:	QC-SLB/25181-07A																				
LOCATION:	WIRE LINE WORKSHOP	JOB NO:	QC-SLB/25181																				
EXAMINATION DATE:	12/Jul/2025																						
LAST INSPECTION	NEXT INSPECTION DATE	LAST PROOF LOAD TEST DATE																					
14/Jan/2025	11/Jan/2026	By Manufacture																					
IDENTIFICATION NO	DESCRIPTION	QTY	SWL																				
L-690613-117	<u>LIFTING CLAMP</u> Manufacture: NOV Lifting clamp assembly (lower clamp) Into two halves bolted together complete Of two lifting points one on each side. Constructed of welded steel plates 	01	3 TON																				
Applicable Reference Standard:	BS EN 13155:2003 +A2:2009 UNIT #049																						
* Is this the first examination after installation or assembly at a new site or location?	<table border="1"> <tr> <td>YES</td> <td></td> <td>NO</td> <td>✓</td> </tr> </table>			YES		NO	✓																
YES		NO	✓																				
* If the answer to the above question is YES has the equipment been installed correctly?	<table border="1"> <tr> <td>YES</td> <td>✓</td> <td>NO</td> <td></td> </tr> </table>			YES	✓	NO																	
YES	✓	NO																					
	<table border="1"> <tr> <td colspan="2">Was the examination carried out?</td> <td colspan="2"></td> </tr> <tr> <td>* Within an interval of 6 months?</td> <td>YES</td> <td>✓</td> <td>NO</td> </tr> <tr> <td>* Within an interval of 12 months?</td> <td>YES</td> <td></td> <td>NO</td> </tr> <tr> <td>* By an examination scheme?</td> <td>YES</td> <td>✓</td> <td>NO</td> </tr> <tr> <td>* After the occurrence of exceptional circumstances?</td> <td>YES</td> <td></td> <td>NO</td> </tr> </table>			Was the examination carried out?				* Within an interval of 6 months?	YES	✓	NO	* Within an interval of 12 months?	YES		NO	* By an examination scheme?	YES	✓	NO	* After the occurrence of exceptional circumstances?	YES		NO
Was the examination carried out?																							
* Within an interval of 6 months?	YES	✓	NO																				
* Within an interval of 12 months?	YES		NO																				
* By an examination scheme?	YES	✓	NO																				
* After the occurrence of exceptional circumstances?	YES		NO																				
Identification Of Any Part Found To Have A Defect Which Is Or Could Become A Danger To Persons And A Description Of The Defect: None																							
Is The Above A Defect Which Is Of Immediate Danger To Persons		YES	NO ✓																				
Is The Above A Defect Which Is Not Yet But Could Become A Danger To Persons: (If YES State The Date By When)		NO	YES																				
Particulars Of Any Repair, Renewal, Or Alteration Required To Remedy The Defect Identified Above: None																							
** Visual And Dimension Check was Carried Out.																							
Is This Equipment Safe To Operate?		Yes Accept	NO Reject																				

INSPECTOR	SIGNATURE:	SUPERVISOR:	SIGNATURE:
Mohammad Abdullah		Ashraf Elsaad	

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.

