

LIFTING ACCESSORIES CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

CLIENT:	SLB BASRA	CERTIFICATE NO:	QC-SLB-27180-08	
LOCATION:	Wireline Workshop			
EXAMINATION DATE:	10/Jul/2025		JOB NO:	QC-SLB-27180
LAST INSPECTION		NEXT INSPECTION DATE		LAST PROOF LOAD TEST DATE
N/A		09/Jan/2026		BY MANUFACTURE
IDENTIFICATION NO	DESCRIPTION			QTY
7905-3T-3M-770 7905-3T-3M-791	<u>Flat 100% Polyester Webbing Sling.</u> Type: EYE X EYE Length: 3 Meter Color: Yellow Manufacturer: SAFETY MARINE SERVICES Safety Factor:7:1 			02
Vertical 3000 KG Chocker 2400 KG Basket 6000 KG				
Applicable Reference Standard:	BS EN 1492-1:2000+A1:2008			
* Is this the first examination after installation or assembly at a new site or location? * If the answer to the above question is YES has the equipment been installed correctly?	Was the examination carried out? YES NO ☒			
	* Within an interval of 6 months? YES ☒ NO ☐			
	* Within an interval of 12 months? YES ☐ NO ☒			
	* By an examination scheme? YES ☒ NO ☐			
* After the occurrence of exceptional circumstances? YES ☐ NO ☒				
Identification Of Any Part Found To Have A Defect Which Is Or Could Become A Danger To Persons And A Description Of The Defect: None				
Is The Above A Defect Which Is Of Immediate Danger To Persons				YES ☐ NO ☒
Is The Above A Defect Which Is Not Yet But Could Become A Danger To Persons: (If YES State The Date By When)				NO ☒ YES ☐ By:
Particulars Of Any Repair, Renewal, Or Alteration Required To Remedy The Defect Identified Above: None				
** Visual And Dimension Check was Carried Out.				
Is This Equipment Safe To Operate?		Yes Accept ☒	NO Reject ☐	

INSPECTOR	SIGNATURE:	SUPERVISOR:	SIGNATURE:
Mohammed Abdullah		Ashraf Elsaad	

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.

