

### Visual Through Examination & Magnetic Particles Examination Report

|                                          |                          |                        |                           |
|------------------------------------------|--------------------------|------------------------|---------------------------|
| <b>Client</b>                            | <b>SLB Basra</b>         | <b>Location</b>        | <b>WIRE LINE WORKSHOP</b> |
| <b>Date of Examination:</b>              | <b>28-Jun-25</b>         | <b>Certificate No:</b> | <b>QC-SLB-25172-09</b>    |
| <b>Date of Next Through Examination:</b> | <b>27-Dec-25</b>         | <b>Job Number:</b>     | <b>QC-SLB-25172</b>       |
| <b>Truck No.</b>                         | <b>UNIT DESCRIPTION:</b> | <b>Serial Number</b>   | <b>Result</b>             |
| <b>5898</b>                              | <b>SHEAVE HANGER</b>     | <b>1998</b>            | <b>Pass</b>               |



| NDT Equipment Details                                                                                            |                  |                           |                      |                  |                  |
|------------------------------------------------------------------------------------------------------------------|------------------|---------------------------|----------------------|------------------|------------------|
| <b>Standard</b>                                                                                                  | <b>ASTM E709</b> | <b>Viewing Condition:</b> | <b>Colored Media</b> | <b>Method:</b>   | <b>WET</b>       |
| <b>AC/DC YOKE</b>                                                                                                | <b>Permanent</b> | <b>Serial No:</b>         | <b>201504048</b>     | <b>Due Date:</b> | <b>23-Aug-25</b> |
| <b>White Contrast</b>                                                                                            | <b>WCP-2</b>     | <b>Batch No:</b>          | <b>008A009</b>       | <b>Due Date:</b> | <b>Apr-26</b>    |
| <b>Black Ink</b>                                                                                                 | <b>7HF</b>       | <b>Batch No:</b>          | <b>008A207</b>       | <b>Due Date:</b> | <b>Jul-25</b>    |
| NDT Procedure                                                                                                    |                  |                           |                      |                  |                  |
| Visual and MPI carried out for the above description and found free of surface defects at the time of inspection |                  |                           |                      |                  |                  |
| Identification of any part found to have a defect and a description of the defect: None                          |                  |                           |                      |                  |                  |
| Particulars of any repair, renewal or alteration required to remedy the defect identified above: None            |                  |                           |                      |                  |                  |

ASNT Level II Inspector  
Name:

Mohammad Abdullah

Authenticating This  
Report:

Ashraf Alsaad

Signature &amp; Stamp:

Review Signature &amp; Stamp:

