

LIFTING ACCESSORIES CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

CLIENT:	SLB BASRA	CERTIFICATION NO:	QC-SLB-25190-10
LOCATION:	WIRELINE WORKSHOP	JOB NO:	QC-SLB/25190
EXAMINATION DATE:	22/Jul/2025		
LAST INSPECTION	NEXT INSPECTION DATE	PROOF LOAD TEST DATE	
06/MAR/2025	21/Jan/2026	N/A	
IDENTIFICATION NO	DESCRIPTION	QTY	SWL
NE2366 NE2367	<u>Single Leg Wire Rope Sling.</u> Dim: 13 mm (Dia) X 18 ft (L) IWRC, 6 X 36 MECHANICALLY SPLICED WITH STEEL FERRULE HARD EYE AT BOTH END SAFETY FACTOR 5:1 	02	2 TON
Applicable Reference Standard:	BS EN 13414-1:2003+A2:2008		
* Is this the first examination after installation or assembly at a new site or location?	YES	NO	✓
* If the answer to the above question is YES has the equipment been installed correctly?	YES	✓	NO
Was the examination carried out?			
* Within an interval of 6 months?	YES	✓	NO
* Within an interval of 12 months?	YES		NO
* By an examination scheme?	YES	✓	NO
* After the occurrence of exceptional circumstances?	YES		NO
Identification Of Any Part Found To Have A Defect Which Is Or Could Become A Danger To Persons And A Description Of The Defect: None			
Is The Above A Defect Which Is Of Immediate Danger To Persons	YES		NO
Is The Above A Defect Which Is Not Yet But Could Become A Danger To Persons: (If YES State The Date By When)	NO	✓	YES
Particulars Of Any Repair, Renewal, Or Alteration Required To Remedy The Defect Identified Above: None			
** Visual And Dimension Check was Carried Out.			
Is This Equipment Safe To Operate?	Yes Accept	✓	NO Reject

INSPECTOR	SIGNATURE:	SUPERVISOR:	SIGNATURE:
Mohamed Abdallah		Ashraf Elsaad	

THIS IS TO CERTIFY THAT; a competent person has examined the mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.

