

**AI TAKAMUL COMPANY FOR ENGINEERING TESTS  
AND PROFESSIONAL SAFETY LIMITED**

Basra, North Rumaila, Quality Control Yard - Iraq

Tel: +9647810009138 / +9647834964657

Email: OP@qualitycontrol-iraq.com / hany.akafi@qualitycontrol-iraq.com



**CERTIFICATE OF THOROUGH EXAMINATION**

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

|   |   |   |   |  |  |
|---|---|---|---|--|--|
| <b>Date of Examination:</b>   | 01/08/2025  | <b>Date of Report:</b>  | 01/08/2025  | <b>Certificate No:</b>   | QC-25-WPS-0108-11                        |
| <b>Client Name:</b>   | HALLIBURTON                                       | <b>Location:</b>  | WPS   | <b>Job Number:</b>   | 010825                                   |
| <b>Serial Number:</b>   | QTY   | <b>Description</b>  | <b>SWL</b>  | <b>Date of manufacture if known:</b>   | <b>Date of last thorough examination</b> |
| L9477   | 1   | <b>4 LEG WIRE ROPE SLING</b><br><b>DIM: 3M (L) X 22 MM (DIA)</b><br><b>Manufacturer: Safety Marine</b><br><b>IWRC MECHANICALLY SPLICED WITH ALUMINUM FERRULES C/W MASTER LINK ASSEMBLY AT THE TOP</b><br><b>HARD EYE BOTH ENDS</b><br><b>S.F: 5:1</b> | 13 T  | 09/2023  | 28/01/2025                               |
| <b>Reference Standard:</b>  | BS EN 13414-1 /HAL DOC: ST-GL-HAL-HSE-0420        |   |   |  |  |
| Is this the first examination after Installation or assembly at a new site or location?   |   | YES <input type="checkbox"/>  | NO <input checked="" type="checkbox"/>  | Was the examination carried out:<br>Within an interval of 6 months?<br>YES <input checked="" type="checkbox"/> NO <input type="checkbox"/> |  |
| If the answer to the above question is YES has the equipment been installed correctly?  |   | YES <input type="checkbox"/>  | NO <input type="checkbox"/>   | With an interval of 12 months?<br>YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>                                      |  |
|   |   | YES <input type="checkbox"/>  | NO <input type="checkbox"/>   | In accordance with an examination scheme?<br>YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>                           |  |
|   |   | YES <input type="checkbox"/>  | NO <input type="checkbox"/>   | After the occurrence of exceptional circumstances?<br>YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>                  |  |
| Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none State NONE) NONE |   |   |   |  |  |
| Is the above a defect which is of immediate danger to persons:  |   |   |   | YES <input type="checkbox"/>   | NO <input checked="" type="checkbox"/>   |
| Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)   |   |   |   | N/A  |  |
| Particulars of any repair, renewal or alteration required to remedy the defect identified above:  |   |   |   |  |  |
| Particulars of any tests carried out as part of the examination: (If none state NONE)   |   |   |   |  |  |
| The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory          |   |   |   |  |  |
| <b>IS THIS EQUIPMENT SAFE TO OPERATE?</b>   |   |   |   | YES <input checked="" type="checkbox"/>  | NO <input type="checkbox"/>              |
| <b>Name of Inspector:</b>   | <b>Name of person authenticating this report:</b> |   | <b>Client Signature &amp; Stamp:</b>  |  |  |
| ASHRAF ELSAID   | MOHAMED ABDALLAH                                  |   | <b>ALI Talib HB48903</b><br><b>Date: 02-08-2025</b><br><b>Signature</b><br><b>Halliburton</b> |  |  |
| <b>Date of Next Through Examination:</b>  | 30/01/2026  |   |   |  |  |

REV: 01 Dated: 20 June 2022



**THIS IS TO CERTIFY THAT;** a competent person has inspected the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.

