



Al Takamul Company for Engineering Services
Quality Control – Iraq

LIFTING ACCESSORIES OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	SLB BASRA	Certificate no:	QC-SLB-25172-12
Location:	WIRE LINE WORKSHOP	Job Order No:	QC-SLB-25172
Date of Examination:	27/Jun/2025	Next Inspection Due:	28/Dec/2025
Last Inspection		Last Proof Load Test Date	
N/A		BY MANUFACTURE Feb-2024	

IDENTIFICATION NO	DESCRIPTION						QTY	SWL				
300909-56	ROUND WEBBING SLING FOR LOGIN UNIT RIG UP Material: Vectran Fiber Length: 4 ft Manufacturer: MAGNUM FORCE Safety Factor: 7:1 Model: RCHPE40 						01	VERTICAL 40000 LBS				
								CHOKER 32000 LBS				
	BASKET 80000 LBS											
Applicable Reference Standard:		BS EN 1492-1:2000+A1:2008										
* Is this the first examination after installation or assembly at a new site or location?						Was the examination carried out?						
		YES		NO	√	* Within an interval of 6 months?		YES	√	NO		
* If the answer to the above question is YES has the equipment been installed correctly?						* Within an interval of 12 months?		YES		NO	√	
		YES	√	NO		* By an examination scheme?		YES	√	NO		
						* After the occurrence of exceptional circumstances?		YES		NO	√	
Identification Of Any Part Found To Have A Defect Which Is Or Could Become A Danger To Persons And A Description Of The Defect: None												
Is The Above A Defect Which Is Of Immediate Danger To Persons							YES		NO			√
Is The Above A Defect Which Is Not Yet But Could Become A Danger To Persons: (If YES State The Date By When)					NO		√	YES		By:		
Particulars Of Any Repair, Renewal, Or Alteration Required To Remedy The Defect Identified Above: None												
** Visual And Dimension Check was Carried Out.												
Is This Equipment Safe To Operate?					Yes Accept		√	NO Reject				

LEEA & ASNT Level II Inspector Name:	SIGNATURE:	Authenticating This Report:	SIGNATURE:
Mohammed Abdullah		Ashraf Alsaad	

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.

